



TO: Winnebago Towables Dealers

SUBJECT: Campaign #001 – LP Line Bump Stop

The National Traffic and Motor Vehicle Safety Act, as amended, provides that each vehicle which is subject to a recall campaign of this type must be adequately repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time.

If the condition is not adequately repaired within a reasonable time, the owners may be entitled to an identical or reasonably equivalent vehicle at no charge or to a refund of the purchase price less a reasonable allowance for depreciation.

To avoid having to provide these burdensome solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. As you will see in reading the enclosed copy of the letter which is being sent to owners, the owners are being instructed to contact Winnebago Towables if you do not remedy the condition within five days of the mutually agreed upon service date. If the condition is not remedied within a reasonable time, they are instructed on how to contact the National Highway Traffic Safety Administration.

REASON FOR THIS RECALL

Winnebago Towables has decided that a defect which relates to motor vehicle safety exists on certain 2013 to 2015 model year Winnebago Minnie and Sunny Brook Remington (Models 2201DS, 2200DS, 2450BHS and 2451BHS) travel trailers.

These travel trailers were manufactured May 7, 2012 through November 13, 2014. These vehicles may encounter axle contact with the black LP pipe fitting, creating a broken or cracked fitting. This could result in LP gas being released. If the propane gas continues to flow, it has the potential to ignite resulting in the possibility of personal injury and/or vehicle and property damage.

OWNER NOTIFICATION

Owners will be notified of this campaign on their vehicles by Winnebago Towables. For all units in your inventory, the notification will be mailed to you. **DO NOT DELIVER TO A CUSTOMER ANY SUBJECT UNIT UNTIL CORRECTIVE ACTION HAS BEEN TAKEN.** Enclosed is a list of vehicles shipped to you.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to service all vehicles subject to this campaign at no charge to owners regardless of age of vehicle or ownership from this time forward.

Whenever a vehicle subject to this campaign is taken into new or used vehicle inventory or it is in your dealership for service in the future, you should take the steps necessary to be sure the campaign correction has been made before reselling or releasing the vehicle. Owners of vehicles recently sold from your new vehicle inventory are to be contacted by the dealer and arrangements made to make the required correction according to instructions contained in this campaign.

INSTRUCTION TO PERFORM CAMPAIGN #001 – LP Line Bump Stop

Affected Models:

Certain 2013 to 2015 model year Winnebago Minnie and Sunny Brook Remington (Models 2200DS & 2450BHS Remington 2201DS and 2451BHS Minnie) travel trailers.

Repair Procedure:

Refer to instruction sheet regarding inspection and installation of the bump stop, if necessary.

Parts Information:

Order the following Part Kit from Winnebago Towables. You will need the Winnebago Towable serial number of the affected vehicle to place the order. Contact Winnebago Towables Parts Department by telephone at (574) 825-5250 or by fax at (574) 825-0818 or by email at partswoi@wgo.net.

- Part #2RR800-15-701

REIMBURSEMENT

When the service has been completed, submit the labor amount and labor operation number listed below. Your repair order must be properly signed by both the dealer and the owner.

	<u>OPERATION NUMBER</u>	<u>TIME ALLOWANCE</u>
LP Line Inspection	44010101	.2
OR		
LP Line Inspection & Bump Stop Installation	44010201	.5

Thank you for your cooperation.

Winnebago Towables
Middlebury, IN 46540

Enclosures