

TOYOTA

◀ IMPORTANT UPDATE ▶

PRODUCT SUPPORT DIVISION

The attached Dealer Letter has been updated. Refer to the details below.

DATE	TOPIC
08/11/14	Update to Operation Codes regarding Sequoia Large Retaining Hex Nut and Sample Owner Letter Added
10/24/14	FAQ updated with additional information related to E04
11/13/14	ASM Reference Guide Added and UIO Updated
02/09/15	Update to UIO
04/09/15	Important Reminder Added
04/30/15	Phase 5 Launch
05/12/15	Additional 2003-2004MY Tundra and 2004MY Sequoia Vehicles Added
06/15/15	05-07MY Corolla, Corolla Matrix, Sequoia, and 05-06MY Tundra Vehicles Added to D3F – Interim Phase
07/01/15	Update to Rental Information, Warranty Sublet, and Return Parts Shipping
09/30/15	Phase 6 Launch
10/29/15	Phase 7 Launch
11/12/15	Phase 8 Launch
12/17/15	Phase 9 Launch
03/01/16	Expanded to include 08MY Corolla and Corolla Matrix (Phase 10)
03/10/16	An additional repair procedure to replace the airbag assembly is now available for Corolla Matrix vehicles.
05/09/16	An additional airbag inflator Part Number is now available for 2005-2008 Model Year Corolla vehicles.
08/08/16	An additional airbag inflator Part Number is now available for 2005-2007 Model Year Sequoia and 2005-2006 Tundra vehicles.
11/03/2016	Non- Desiccated Inflators for 2005-2008 Corolla, 2003-2008 Matrix, 2005-2007 Sequoia and 2005-2006 Tundra Vehicles are no longer available.
02/09/2017	<ul style="list-style-type: none">• Non-Desiccated Inflators for 2003-2004 Corolla, 2003-2004 Tundra and 2002-2004 Sequoia vehicles are no longer available.• Non-Desiccated Inflator return process available to Dealers• New Takata Part Number Available for 2003-2004 Tundra and 2002-2004 Sequoia Vehicles.
11/08/2017	A new section titled: Incomplete VINs for Dealers, has been added for SOAR.
04/18/2018	<ul style="list-style-type: none">• Non-Desiccated Part Recovery has been updated with additional part numbers.• Pre-owned Vehicles section has been updated.• Rental Section has been updated.
07/17/2018	<ul style="list-style-type: none">• Dealer Transportation Section added with new opcode and sublet for Customer Vehicle Pickup and Delivery.• Technician Training Requirements have been updated.
5/09/2019	Loaner Vehicle Reimbursement Procedure has been updated.
08/28/2019	<ul style="list-style-type: none">• <u>The remedy has been suspended for 05-08 Matrix vehicles until further notice.</u>• A section on campaign phase interpretation has been added• Instructions on inspecting airbag assemblies for 2005 – 2008 Matrix vehicles and the return process of these airbag assemblies have been added.

The most recent update in the attached Dealer Letter will be highlighted with a red box.

Please review this notification with your staff to assure that all relevant personnel have been briefed regarding this subject.

Thank you for your cooperation.

TOYOTA

Published October 20, 2014

Toyota Motor Sales, USA, Inc.
19001 South Western Avenue
Torrance, CA 90501
(310) 468-4000

To: All Toyota Dealer Principals, Service Managers, and Parts Managers

Subject: Safety Recall **DSF Remedy Update**
Certain 2003-2008 Model Year Corolla and Matrix Vehicles
Certain 2003-2006 Model Year Tundra Vehicles
Certain 2002-2007 Model Year Sequoia Vehicles
Front Passenger Airbag Inflator Module

Background

The original remedy for Safety Recall D0F launched in early April, 2013, included an inspection and, if necessary, replacement of the airbag inflator module.

- In early June, 2014, supplemental Safety Recall DSF was announced with a revised remedy which involved replacement of the passenger inflator module regardless of inspection results.
- In early May, 2015, Toyota expanded Safety Recall DSF to include certain 2003-2004 model year Tundra vehicles and 2004 model year Sequoia vehicles.
- In mid-June, 2015, Toyota expanded Safety Recall DSF to include certain 2005-2007 model year Corolla, Matrix, Sequoia, and 2005-2006 model year Tundra vehicles.
- In early March, 2016, Toyota expanded Safety Recall DSF to include certain 2008 Corolla and Matrix vehicles.

*Toyota has completed the remedy and owner mailing preparations for Phases 1-10. **All affected vehicles are eligible for an inflator replacement.***

Condition

The subject vehicles are equipped with front passenger airbag inflators which may have been manufactured in such a way as to have a potential for the intrusion of moisture over time. Depending on the circumstances, this could create excessive internal pressure when the airbag is deployed and cause the inflator to explode. In the event of an inflator explosion, metal fragments could pass through the airbag cushion material, striking the vehicle occupants and potentially resulting in serious injury or death.

Remedy

The remedy has been launched in phases due to limited parts availability.

Phase	Model	Location	Launch Date
1	03-04MY Corolla 03-04MY Matrix 03-04MY Tundra 02-04MY Sequoia	Vehicles registered in Florida, Hawaii, Puerto Rico and U.S. Virgin Islands.	Late June, 2014
2		Vehicles registered in Gulf States Toyota (GST) and Southeast Toyota (SET). States: AL, AR, FL, LA, GA, MS, NC, OK, SC, and TX	Mid-February, 2015
3		Vehicles registered in Central Atlantic Toyota (CAT) States: DE, MD, PA, VA, and WV	Late March, 2015
4		Vehicles registered in San Francisco and Los Angeles Regions State: CA	Early April, 2015
5		Vehicles registered in Boston and New York Regions States: CT, MA, ME, NH, NJ, NY, RI, and VT	Late April, 2015
6	03-04MY Corolla 03-04MY Matrix	Vehicles registered in Chicago, Cincinnati, Denver, Kansas City, and Portland Regions States: AK, AZ, CO, IA, ID, IL, IN, KS, KY, MI, MN, MO, MT, ND, NE, NM, NV, OH, OR, SD, TN, UT, WA, WI, and WY	Late September, 2015
7	03-04MY Tundra 02-04MY Sequoia		Late October, 2015
8	05-07MY Corolla 05-07MY Matrix 05-06MY Tundra 05-07MY Sequoia	Vehicles registered in Gulf States Toyota (GST) and Southeast Toyota (SET). States: AR, NC, and OK (GST/SET states not listed are involved in Safety Recall E04 – For Areas of High Absolute Humidity)	Mid-November, 2015
9		Vehicles registered in Boston, Central Atlantic Toyota (CAT), Chicago, Cincinnati, Denver, Kansas City, Los Angeles, New York, Portland, and San Francisco Regions States: AK, AZ, CA, CO, CT, DE, IA, ID, IL, IN, KS, KY, MA, MD, ME, MI, MN, MO, MT, ND, NE, NH, NJ, NM, NV, NY, OH, OR, PA, RI, SD, TN, UT, VA, VT, WA, WI, WV, and WY	Mid-December 2015
10	08MY Corolla 08MY Matrix	All Locations Note: Vehicles originally sold in, or currently/previously registered in, areas of High Absolute Humidity are included in Safety Recall E04.	Early March, 2016

Toyota dealers are requested to replace the front passenger airbag inflator at **no charge** to the vehicle owner. (For certain models, the front passenger airbag assembly may be replaced.)

The following information is provided to inform you of the owner notification timing and your degree of involvement.

Owner Letter Mailing

Toyota notified all owners of vehicles covered by Phases 1-10. The notification start and end dates vary based on the launch date of each phase. The owner letter notifications for these customers has been completed.

Toyota makes significant effort to obtain current customer name and address information when mailing owner letters. In the event your dealership receives a notice for a vehicle that was sold prior to the Safety Recall announcement, it is the dealership's responsibility to forward the owner letter to the customer who purchased the vehicle.

If a dealer is contacted by an owner who has not yet received the notification, please instruct the dealer to **verify coverage by confirming through TIS**. Dealers should perform the procedure as outlined in the Technical Instructions located on TIS.

Pre-Owned Vehicles in Dealer Stock

To ensure customer satisfaction, Toyota requests that dealers complete this Safety Recall on any used vehicles currently in dealer inventory that are covered by this Safety Recall prior to customer delivery. However, if the campaign cannot be completed (for example, due to remedy parts availability), delivery of a covered vehicle is acceptable if disclosed to the customer that the vehicle is involved in a Safety Recall.

Toyota expects dealers to use the attached Pre-Owned Vehicle-Safety Recall Customer Contact and Vehicle Disclosure Form to obtain vehicle buyer information. Dealers are expected to provide a copy of the completed form, along with the most current FAQ, to the vehicle buyer. Toyota and the dealer may use this information to contact the customer when the remedy becomes available.

Keep the completed form on file at the dealership and send a copy to quality_compliance@toyota.com. In the subject line of the email state "Disclosure Form – DSF" and include the VIN.

Also, as a reminder, Toyota Certified Used Vehicle (TCUV) policy prohibits the certification of any vehicle with an outstanding Special Service Campaign or Safety Recall. Thus, no affected units should be designated, sold or delivered as a TCUV until the Safety Recall has been completed on that vehicle.

Number and Identification of Covered Vehicles

There are approximately 1,874,000 Toyota vehicles covered by this Safety Recall. Vehicles covered by Safety Recall D0F that previously received a replacement airbag inflator module are not included in either action.

Model	Model Year	Appx. UIO	Production Range
Corolla	2003-2008	1,150,000	Mid-December, 2001 - Late December, 2007
Matrix	2003-2008	242,000	Mid-December, 2001 - Mid-December, 2007
Tundra	2003-2006	309,000	Late May, 2002 - Late December, 2006
Sequoia	2002-2007	173,000	Early April, 2002 - Early November, 2007

Campaign Phase Interpretation

The remedy has been suspended and is NOT available for some vehicles covered by campaign designation DSF. Specifically, the remedy is NOT available for 2005 – 2008 model year Matrix vehicles. Dealers should confirm the status of each VIN in TIS prior to beginning any repairs.

REMEDY PHASE – ELIGIBLE FOR REPAIR

Campaign Description: Safety Recall DSF - Remedy Notice - Multiple Models - Front Passenger Airbag Inflator Module
Campaign Status: Remedy Available
Completion Status: Not Completed
Memo: Remedy Available

[\[Show Documents\]](#)

B

STATUS IDENTIFICATION

A: Campaign Status: Remedy Available

B: Memo: Remedy Available

- **This vehicle is eligible to have the remedy performed if the completion status is "Not Completed."**

SUSPENDED PHASE – NOT ELIGIBLE FOR REPAIR

Campaign Description: Safety Recall DSF - Remedy Notice - Certain 2005 - 2008 Model Year Corolla Matrix Vehicles - Front Passenger Airbag Inflator Module
Campaign Status: Remedy Not Available
Completion Status: Not Completed
Memo: Remedy Not Available - DO NOT Replace Airbag Assembly

[\[Show Documents\]](#)

B

STATUS IDENTIFICATION

A: Campaign Status: Remedy Not Available

B: Memo: Remedy Not Available – DO NOT Replace Airbag Assembly

- **This vehicle is in the interim phase; the remedy CANNOT be performed at this time.**

Refer to the table below to determine the remedy status of vehicles involved in DSF.

Model	Model Year	DSF Remedy Status
Corolla	2003 – 2008	Remedy Available
Matrix	2003 – 2004	Remedy Available
	2005 - 2008	Remedy NOT Available
Tundra	2003 – 2006	Remedy Available
Sequoia	2002 – 2007	Remedy Available



The remedy status for all campaign codes that require the remedy parts affected by this condition is shown below for your reference. Please refer to the individual Takata Airbag recall dealer letters for more details.

Model Name	Model Year	DSF/E04	J0A/J0B/J0C	K0Q Remedy Status
Matrix	2005 - 2008	Remedy NOT Available	Remedy NOT Available	Remedy NOT Available
Corolla	2003 - 2004	Remedy Available	Remedy Available	Remedy Available
	2005 - 2008	Remedy Available	Remedy Available	Remedy Available

Campaign Special Service Tools

In a shipment which was scheduled to arrive on July 31, 2013, your dealership was sent a package containing special service tools for Safety Recall D0F which will also be used for this campaign.

These tools are needed when performing the front passenger airbag inflator module campaign. These tools **ARE NOT** available through normal parts or tools channels. There is a very limited supply of tools, but if additional tools are needed, contact your regional representative.

Name	Sample Image	Qty
Airbag Mounting Bracket & hardware		1
Barcode Scanner		1

Technician Training Requirements

The repair quality of covered vehicles is extremely important to Toyota. All dealership technicians performing this repair are required to successfully complete the most current version of the E-Learning course “Safety Recall and Service Campaign Essentials”. To ensure that all vehicles have the repair performed correctly; technicians performing this recall repair are required to have successfully completed E-Learning course SC18A (if you had previously completed E-Learning Course SC13B, you do not have to take SC18A), in addition to “Safety Recall and Service Campaign Essentials”, and currently hold at least one of the following certifications levels:

- **Toyota Certified (Electrical)**
- **Toyota Expert (Any Specialty)**
- **Master Technician**
- **Master Diagnostic Technician (MDT)**

It is the dealership’s responsibility to select technicians with the above certification level or greater to perform this Safety Recall repair. Carefully review your resources, the technician skill level, and ability before assigning technicians to this repair. It is important to consider technician days off and vacation schedules to ensure there are properly trained technicians available to perform this repair at all times.

Campaign Specific Part Associate E- Learning Training Requirement

The Airbag Inflator Assembly being replaced during this campaign is a Class 9 Hazmat part. Therefore Parts Associates involved in this recall are required to complete E-Learning Module (**E2140** “Safety Recall D0F – Front Passenger Airbag Inflator” found on www.utodealer.com) This E-Learning module will explain the proper procedure for documenting and returning the Airbag Inflator Assembly to TK Holdings Incorporated.

Shipping Information for Removed Inflators and Airbag Assemblies

This parts return procedure is applicable to removed airbag inflators, airbag modules, and airbag assemblies. With this process, each dealer will be required to perform the following:

- Apply a return address label to the outside of each inflator/module/assembly box (**label provided by Takata in the new part box**).
- Store the old parts on a pallet until 100 are accumulated or whatever amount is collected after 30 days.
- **Keep a running log of how many of each type of inflator/module/assembly are on the pallet.**
- Secure the parts on the pallet with shrink wrap.
- Contact Takata at 1-877-650-9409 to arrange LTL pick-up.
- Place an over-pack label on the palletized load and provide the LTL driver with the pre-filled out documentation that will be sent to the dealer by Takata.

This process will not require the dealer to fill out any paperwork. All documents will be filled out by Takata and returned to the dealer.

Refer to the Job Aid available on TIS for more details on this process and how to get more labels.

In addition, to compensate dealers for purchasing pallets and shrink wrap, a sublet claim of 0.20 cents per vehicle may be applied to each inflator replacement warranty claim.

NOTE: This updated inflator recovery program only applies to the continental 48 states. Alaska, Hawaii and the US Territories must contact the following Takata USA representative directly for shipping instructions: Miguel Prigadaa – Tel #: 210-250-5078 or e-mail: MLGTakataRestraints_International@menloworldwide.com.

Parts Ordering Process

On November 3rd, 2016, Toyota announced that Non-Desiccated Airbag Inflator kits for 05-08 Corolla, 03-08 Matrix, 05-06 Tundra, and 05-07 Sequoia vehicles could no longer be ordered.

Additionally, as of February 09, 2017, Non-Desiccated Airbag Inflators for 03-04 Corolla, 03-04 Tundra and 02-04 Sequoia are also no longer able to be ordered through your PDC.

Dealers should discontinue the installation of the parts listed below for the recalls, customer pay repairs AND over-the-counter sales (if applicable) unless they have a mark on the label.

Mark Present = OK Part

Do NOT Return



Model	Model Year	Location	Part Number	Part Description
Matrix	2005-2008	48 States in Continental U.S.	04005-22901	AIRBAG ASSEMBLY W/ INFLATOR
		USTT, Hawaii & AK	04005-22801	

Toyota requires all dealers to return any parts listed above that do NOT have a mark on the label that remain in dealer inventory by utilizing the Hazmat Part Return Program available. Dealers will be issued a refund for all part returns. This part return program is outlined in *PANT Bulletin 2014-042*.

Important Note:

In order to return the inflator, packages must **NOT** be opened/tampered with.

Updated: 8/28/2019

Non SET and GST Parts Ordering Process

Due to limited availability, the parts have been placed on either Manual Allocation Control (MAC) or Dealer Ordering Solutions (DOS). As the parts inventory improves, the ordering process may change. Please check the Toyota Special Activities MAC/DOS report on Dealer Daily for the most up-to-date parts ordering information.

Replacement *Takata* Airbag Inflators

Model	Model Year	Part Number	Part Description	Qty
Corolla	2003-2004	04006-06102	INFLATOR ASSY KIT, AIR BAG	1
	2005-2008			
Sequoia	2002-2004	04006-0490C		
	2005-2007	04006-0620C		
Tundra	2003-2004	04006-0490C		
	2005-2006	04006-0620C		

Replacement *Autoliv* Airbag Modules

Model	Model Year	Part Number	Part Description	Qty
Matrix	2003-2004	04005-22601	AIRBAG ASSEMBLY W/ INFLATOR	1
	2005-2008	04005-22901	AIRBAG ASSEMBLY W/ INFLATOR	1
- AND -				
Matrix	2003-2008	04005-28112	AIRBAG CONNECTOR	1

Non-Desiccated Part Recovery

Dealers should discontinue the installation of the non-desiccated parts listed below for recall, customer pay repairs AND over-the-counter sales (if applicable).

Model	Model Year	Location	Part Number	Part Description
Corolla	2003-2004	48 States in Continental U.S.	04003-28102	INFLATOR ASSY KIT, INSTR PNL AIRBAG
	2005-2008	48 States in Continental U.S.	04004-75202	
Sequoia	2002-2004	48 States in Continental U.S.	04003-2810C	
	2005-2007	48 States in Continental U.S.	04004-7520C	
Tundra	2003-2004	48 States in Continental U.S.	04003-2810C	
	2005-2006	48 States in Continental U.S.	04004-7520C	
Matrix	2003-2004	48 States in Continental U.S.	04003-28101	
	2005-2008	48 States in Continental U.S.	04004-75201	

Model	Model Year	Part Number	Part Description
Corolla	2003-2004	73970-02040-B0	AIR BAG ASSY, INSTR PNL PASS
		73970-02040-B1	
		73970-02040-E0	
2005-2008	73970-02051-B0		
	73970-02051-B1		
	73970-02051-E0		
Sequoia	2002-2004	73970-0C020-B0	
		73970-0C020-B1	
	2005-2007	73970-0C020-E0	
		73970-0C021-B0	
Tundra	2003-2004	73970-0C021-B1	
		73970-0C020-B0	
	2005-2006	73970-0C020-B1	
		73970-0C021-B0	
Matrix	2003-2004	73970-01030-B0	
	2005-2008	73970-01050-B0	

Toyota requires all dealers to return any parts listed above that still remain in dealer inventory by utilizing the Hazmat Part Return Program available. Dealers will be issued a refund for all part returns. This part return program is outlined in *PANT Bulletin 2014-042*.

Important Note:

In order to return the inflator, packages must **NOT** be opened/tampered with.


In the limited cases where the serial number is illegible, the Airbag Assembly will require replacement. Please contact your regional representative for further direction on vehicle repair and claim filing procedures.

Remedy Procedures

Please refer to TIS for Technical Instructions on inspection and repair.

Conduct all applicable, non-completed Safety Recall and Service Campaigns on the vehicle during the time of appointment.

Warranty Reimbursement Procedure



Model	Op. Code	Description	Flat Rate Hour
Tundra & Sequoia	AGG48B	Replace Airbag Inflator	1.2 hr/vehicle
Corolla	AGG48G	Replace Airbag Inflator	0.9 hr/vehicle
Matrix		Replace Airbag Assembly or Inflator	

In limited instances, a Sequoia vehicle may have an inflator utilizing a large retaining hex nut on the right side. These vehicles are not involved in this Safety Recall. **Refer to the Sequoia Technical Instructions Section VIII-2 for additional details.**

Model	Op. Code	Description	Flat Rate Hour
Sequoia (ONLY)	AGG48W	Large Retaining Hex Nut Found Vehicle not Involved Under this Safety Recall (Refer to the Sequoia Technical Instructions Section VIII-2)	0.3 hr/vehicle

- The flat rate times include 0.1 hours for administrative cost per unit for the dealership.
- Dealers may claim the cost for materials needed for inflator return shipping under opcodes AGG48B and AGG48G at a maximum rate of \$0.20 per vehicle as sublet type “ZZ.”
- Towing may be offered to the customer and can be claimed under Op. Code AGG48B, AGG48G, and AGG48W for a maximum of \$250 as sublet type “TW”. The customer may request vehicle pick up if they reside in areas where dealerships are not located within reasonable traveling distance or if the customer is not comfortable driving their vehicle

Loaner Vehicle Reimbursement Procedure

For customer convenience, one of the following alternative transportation options can be claimed for \$35 per day:

- Loaner vehicle through Toyota Rent-A-CAR (TRAC)
- Rental vehicle
- Other alternative transportation such as Uber, Lyft or a taxi

Op Code	Description
RNTDSF	Vehicle Rental 1 Day

If alternative transportation exceeds 1 day, due to part availability issues such as a backorder, then alternative transportation can be claimed as sublet type “RT” under the repair Op. Codes AGG48B or AGG48G.

NOTE:

- **Rental invoice *MUST* be attached to all rental claims. These claims may be subject to debit if rental invoice is not attached.**
- **Rentals greater than 3 days or \$35 per day requires DSPM authorization as per the Toyota Transportation Assistance Policy (TTAP)**

Dealer Transportation - Customer Vehicle Pickup and Delivery

- **Dealer Transportation Opcode is only to be used if the customer’s vehicle was delivered to and from the dealer. Transportation sublet is not to exceed \$120. These claims may be subject to debit if it is determined that the vehicle was not picked up or delivered.**
- Dealers will determine the transportation cost, which they are allowed to claim as sublet “DE”, under the Dealer Transportation op code by multiplying their dealer labor rate by 0.7 hours (ex. \$100 x 0.7 = \$70 Dealer Transportation).

Model	Dealer Transportation Op Code	Sublet	\$ Amount to be Included on Claim for Dealer Transportation Cost
Tundra & Sequoia	DSFTRA	DE	0.7hr x Dealer Labor Rate (ex: \$100 x 0.7 = \$70)
Corolla			
Matrix			


Unremedied VIN List:

Toyota is committed to increasing Safety Recall completion rates. Engaging dealerships in customer outreach efforts is of vital importance to achieving this goal. To this end, dealers who utilize the Service Opportunity Access for Retention (SOAR) system can access a list of incomplete VINs in their area for campaign DSF. This information is to be used to contact customers about open recalls ONLY. DO NOT use this information for any other purpose.

For the Takata recall, communications to customers are coordinated with the National Highway Traffic Safety Administration (NHTSA). To promote clear and consistent messages, Toyota has developed templates for dealers to use in communications with customers. Dealers may add their logos and contact information in the spaces provided on the templates. These templates have been provided to the OCPe NBP vendors and will also be available for download in SOAR.

Please refer to the special **Takata Unrepaired VINs for Dealers FAQ** included in the dealer package for further details.

Campaign Designation Decoder



Repair Quality Confirmation

The repair quality of covered vehicles is extremely important to Toyota. To help ensure that all vehicles have the repair performed correctly, please designate at least one associate (someone other than the individual who performed the repair) to verify the repair quality of every vehicle prior to customer delivery.

Media Contacts

It is imperative that all media contacts (local and national) receive a consistent message. In this regard, all media contacts must be directed to Tania Saldana (859) 815-9968 in Toyota Corporate Communications. Please do not provide this number to customers. Please provide this contact only to media associates.

Customer Contacts

Customers who receive the owner letter may contact your dealership with questions regarding the letter and/or the Safety Recall. Please welcome them to your dealership and answer any questions that they may have. A Q&A is provided to assure a consistent message is communicated.

Customers with additional questions or concerns are asked to please contact the Toyota Customer Experience Center (1-888-270-9371) - Monday through Friday, 7:00 am to 7:00 pm, Saturday 7:00 am to 4:30 pm Central Time.

Please review this entire package with your Service and Parts staff to familiarize them with the proper step-by-step procedures required to implement this Safety Recall.

Thank you for your cooperation.
 TOYOTA MOTOR SALES, U.S.A., INC.



Safety Recall DSF/E04 - Supplemental ASM Reference
Certain 2003-2008 Model Year Corolla and Corolla Matrix Vehicles
Certain 2003-2006 Model Year Tundra Vehicles
Certain 2002-2007 Model Year Sequoia Vehicles
Front Passenger Airbag Inflator Module


The following information is being provided to help dealership associates understand the differences between the multiple Takata actions Toyota has announced.

Safety Recall Overview:

In April, 2013, Toyota announced a nationwide Safety Recall (D0F) to inspect and, as necessary, replace front passenger airbag inflator modules manufactured for Toyota by Takata Corporation. In June, 2014, the recall remedy was revised to replace all inflators regardless of inspection results. The revision of the remedy was announced as a new Safety Recall DSF. All vehicles that did not receive a replacement inflator under D0F were included in DSF.



The geographic concentration of inflators with a higher risk of rupture in areas with consistently high absolute humidity warranted priority replacement in these areas. Therefore, Toyota has launched Safety Recall E04 which involves vehicles originally sold in, or currently/previously registered in, areas that are exposed to consistent High Absolute Humidity. These vehicles were previously included in Safety Recalls D0F/DSF and E0V.



In May, 2015, Toyota expanded Safety Recalls DSF and E04 to include additional vehicles.

- DSF expansion included certain 2003-2004 model year Tundra vehicles and 2004 model year Sequoia vehicles.
- E04 expansion included additional 2005-2007 model year Corolla, Corolla Matrix, Sequoia, and 2005-2006 model year Tundra vehicles.

Updated 5/12/2015

In June, 2015, Toyota expanded Safety Recalls DSF and E04 to include additional vehicles.

- DSF expansion included certain 2005-2007 model year Corolla, Corolla Matrix, Sequoia, and 2005-2006 model year Tundra vehicles.
- For E04, the high absolute humidity area is no longer limited to coastal areas of the specific states listed, and also now includes the state of South Carolina.

Updated 6/15/2015

In March, 2016, Toyota expanded Safety Recalls DSF and E04 to include 2008 model year Corolla and Corolla Matrix vehicles.

Updated 3/1/2016



Safety Recall DSF:

- 2003-2008 Corolla
- 2003-2008 Corolla Matrix
- 2003-2006 Tundra
- 2002-2007 Sequoia

Safety Recall E04:

- 2003-2008 Corolla
- 2003-2008 Corolla Matrix
- 2003-2006 Tundra
- 2002-2007 Sequoia

The map below provides a visual representation of the areas which have been included in Superseding Safety Recall E04 (Red Area). The yellow portion of the map represents an approximate geographic representation of vehicles covered by Safety Recall DSF.



Note: This map is provided for reference purposes only. The inclusion of vehicles in Safety Recall E04 and DSF may differ from the visual representation shown on the map. Always verify vehicle Safety Recall applicability using the Technical Information System (TIS).



Safety Recall DSF/E04 - Supplemental ASM Reference
Certain 2003-2008 Model Year Corolla and Corolla Matrix Vehicles
Certain 2003-2006 Model Year Tundra Vehicles
Certain 2002-2007 Model Year Sequoia Vehicles
Front Passenger Airbag Inflator Module



Q1: Is the remedy different between DSF and E04?

A1: No, all vehicles involved in DSF and E04 will receive a replacement passenger airbag inflator as parts become available. (For certain models, the front passenger airbag assembly may be replaced.) At this time Toyota has a limited number of inflators; therefore, we are first focusing on the E04 area, because testing of recovered inflators from High Absolute Humidity areas has indicated an elevated risk of rupture.

Q2: Is Toyota offering passenger airbag disablement?

A2: No. Toyota was only offering passenger airbag disablement as a temporary measure while sufficient parts were being produced. Toyota now has sufficient parts to support vehicles covered under E04. If the front passenger airbag was previously disabled due to unavailability of parts, please advise your customer that the dealer will promptly complete the remedy inflator replacement.

Q2a: Why was Toyota temporarily offering passenger airbag disablement under Safety Recall E04?

A2a: At the time, Toyota had a very limited supply of replacement airbag inflators to support vehicles covered under E04. This was only a temporary option for customers whose vehicles are covered under E04. While parts were being produced in sufficient quantity, the National Highway Traffic Safety Administration (NHTSA) granted Toyota permission to temporarily disable airbags only in High Absolute Humidity (E04) areas, but no others.

Updated 2/24/2015

Q3: Which vehicles from Safety Recall DSF are now covered by Safety Recall E04?

A3: Approximately 257,500 vehicles originally involved in DSF are now involved in Superseding Safety Recall E04. Vehicle transferred to E04 were originally sold in, or currently/previously registered in, areas of High Absolute Humidity, encompassing the following states: Texas, Alabama, Mississippi, Georgia, South Carolina, Florida, Hawaii, and Louisiana. In addition, it includes Puerto Rico, Guam, Saipan, American Samoa, and the U.S. Virgin Islands.

Q4: What is absolute humidity?

A4: The measure of the water vapor content in the air is known as absolute humidity, and it is displayed in grams of water vapor per cubic meter of air. Higher temperature, southern coastal-type climates consistently experience the greatest concentrations of water vapor in the air, as warmer ambient air can hold more water.

Note: relative humidity is simply a percentage value and is related to current or measured temperature; therefore, areas with high relative humidity do not necessarily have high absolute humidity



Safety Recall DSF - UPDATE
Certain 2003-2008 Model Year Corolla and Matrix Vehicles
Certain 2003-2006 Model Year Tundra Vehicles
Certain 2002-2007 Model Year Sequoia Vehicles
Front Passenger Airbag Inflator Module

Customer Frequently Asked Questions

◀ IMPORTANT UPDATE ▶

DATE	TOPIC
8/28/2019	<i>Q&A 9, 10, and 11 have been added to explain the availability of the remedy for certain 2005 – 2008 Matrix vehicles.</i>

We at Toyota care greatly about your safety. We are providing the following information to keep you informed of the details specific to this recall. Please check back frequently as this document will be updated.

On March 1, 2016, Toyota expanded Safety Recall DSF to include 2008 model year Corolla and Matrix vehicles.

Due to parts production capacity, Toyota recall #DSF has been launched in phases. **Toyota will notify owners of vehicles consistent with parts availability and dealer repair capacity.** Vehicles that already received a replacement passenger airbag inflator are not included in this Safety Recall.

Q1: What is the condition?

A1: The subject vehicles are equipped with front passenger airbag inflators which may have been manufactured in such a way as to have a potential for the intrusion of moisture over time. Depending on the circumstances, this could create excessive internal pressure when the airbag is deployed and cause the inflator to rupture. In the event of an inflator rupture, metal fragments could pass through the airbag cushion material, striking the vehicle occupants and potentially resulting in serious injury or death.

Q1a: What is the Inflator?

A1a: The inflator is a device contained within the airbag assembly. It contains solid propellant wafers which are ignited in the event airbag deployment is necessary. When ignited, the wafers expand into an inert gas, inflating the airbag.

Q2: How does my vehicle relate to the Takata and Toyota action for Areas of High Absolute Humidity?

A2: Toyota has two separate Safety Recall actions related to Takata inflators. One is a nationwide recall (Toyota recall #DSF) and a second (Toyota recall #E04) is focused on the gulf coast states and other areas with consistently high absolute humidity. Your vehicle is included in nationwide Takata recall activity, and your passenger airbag inflator will be replaced when parts become available.

Takata has tested parts recovered from recalled vehicles. Test results from the parts recovered from consistently high absolute humidity areas (such as Florida and the Gulf Coast) have shown a possible correlation with high absolute humidity areas and elevated risk for passenger airbag inflator rupture. Test results of parts from areas with lower absolute humidity than these coastal regions have shown less risk of rupture. The geographic concentration of inflators with the potential for rupture in these areas of consistently high absolute humidity warrants priority replacement in these areas. Therefore, Toyota is conducting a separate Safety Recall (Toyota recall #E04) for areas with High Absolute Humidity, and is prioritizing the remedy of vehicles in these areas.

Q2a: What is absolute humidity?

A2a: The measure of the water vapor content in the air is known as absolute humidity, and it is displayed in grams of water vapor per cubic meter of air. Higher temperature, southern coastal climates consistently experience the greatest concentrations of water vapor in the air, as warmer ambient air can hold more water.

Note: relative humidity is simply a percentage value and is related to current or measured temperature; therefore, areas with high relative humidity do not necessarily have high absolute humidity.

Q3: Until the remedy is performed on my vehicle, are there any steps I can take to minimize the occurrence of this condition?

A3: No, There are no steps you can take to minimize the occurrence of this condition. However, the condition does not cause the airbag to activate when it should not. Also, the front passenger airbag is designed to inflate only in certain moderate to severe crashes. To further minimize risk, Toyota recommends that you locate passengers into the rear seating positions.

Q4: What should you do?

A4: Please contact any authorized Toyota dealer to schedule an appointment to have your front passenger airbag inflator replaced free of charge. When taking your vehicle to the dealership for your service appointment, it is recommended that only the driver occupy the vehicle. If you are uncomfortable driving the vehicle to the dealership, please contact your local authorized Toyota dealer who will arrange for vehicle pick up. Until the remedy is performed, the front passenger seat should NOT be occupied.

If you do not follow the instructions in the owner letter, you should not drive your vehicle.

Q5: Are there concerns with other airbags in the vehicle?

A5: No, this condition only applies to the front passenger airbag inflator. Other airbags in the vehicle are not affected by this condition.

Q6: Will Toyota disconnect the involved airbag or the other airbags in my vehicle?

A6: Toyota dealers have sufficient quantities of replacement parts to complete remedy repairs. Owners should visit a Toyota dealer to receive their replacement airbag inflator and system check. Airbag assemblies are integral parts of the overall vehicle safety system and the integrity of the system should always be checked by drivers observing the dash mounted warning lights. Toyota dealers are not authorized to disconnect any airbag system as part of this Safety Recall action.

Q7: What is Toyota going to do?

A7: The remedy has been launched in phases due to limited parts availability.

Phase	Model	Location	Launch Date
1		Vehicles registered in Florida, Hawaii, Puerto Rico and U.S. Virgin Islands.	Late June, 2014
2	03-04MY Corolla	Vehicles registered in Gulf States Toyota (GST) and Southeast Toyota (SET). States: AL, AR, FL, LA, GA, MS, NC, OK, SC, and TX	Mid-February, 2015
	03-04MY Matrix		
3	03-04MY Tundra	Vehicles registered in Central Atlantic Toyota (CAT) States: DE, MD, PA, VA, and WV	Late March, 2015
4	02-04MY Sequoia	Vehicles registered in San Francisco and Los Angeles Regions State: CA	Early April, 2015
5		Vehicles registered in Boston and New York Regions States: CT, MA, ME, NH, NJ, NY, RI, and VT	Late April, 2015
6	03-04MY Corolla 03-04MY Matrix	Vehicles registered in Chicago, Cincinnati, Denver, Kansas City, and Portland Regions States: AK, AZ, CO, IA, ID, IL, IN, KS, KY, MI, MN, MO, MT, ND, NE, NM, NV, OH, OR, SD, TN, UT, WA, WI, and WY	Late September, 2015
7	03-04MY Tundra 02-04MY Sequoia		Late October, 2015
8	05-07MY Corolla 05-07MY Matrix	Vehicles registered in Gulf States Toyota (GST) and Southeast Toyota (SET). States: AR, NC, and OK (GST/SET states not listed are included in Safety Recall E04 – For Areas of High Absolute Humidity)	Mid-November, 2015
9	05-06MY Tundra 05-07MY Sequoia	Vehicles registered in Boston, Central Atlantic Toyota (CAT), Chicago, Cincinnati, Denver, Kansas City, Los Angeles, New York, Portland, and San Francisco Regions States: AK, AZ, CA, CO, CT, DE, IA, ID, IL, IN, KS, KY, MA, MD, ME, MI, MN, MO, MT, ND, NE, NH, NJ, NM, NV, NY, OH, OR, PA, RI, SD, TN, UT, VA, VT, WA, WI, WV, and WY	Mid-December 2015
10	08MY Corolla 08MY Matrix	All Locations Note: Vehicles originally sold in, or currently/previously registered in, areas of High Absolute Humidity are included in Safety Recall E04.	Early March, 2016

Toyota notified all owners of vehicles covered by Phases 1-8. The notification start and end dates varied based on the launch date of each phase. The owner letter notifications for these customers has been completed.

Toyota began notifying owners of vehicles covered by Phase 9 in early January, 2016. The owner letters will be mailed in quantities consistent with parts availability and dealer repair capacity, and is expected to complete by June 1, 2016.

Toyota will mail an interim letter to owners of vehicles covered by the March 2016 expansion (Phase 10) beginning in mid-March, 2016. Toyota will then mail a remedy letter to these owners beginning in early June, 2016.

Toyota dealers will replace the front passenger airbag inflator at **no charge** to the vehicle owner. (For certain models, the front passenger airbag assembly may be replaced.)

Q7a: How does Toyota obtain my mailing information?

A7a: Toyota uses an industry provider who works with each states Department of Motor Vehicles (DMV) to receive registration or title information, based upon the DMV records. Please make sure your registration or title information is correct.

Q7b: Do I need my owner letter to have the remedy performed?

A7b: You do not need an owner letter to have this recall completed; however, to assist the dealer in confirming vehicle eligibility, we request that you present this notice at the time of your service appointment.

Q8: Which and how many vehicles are covered by this Safety Recall?

A8: There are approximately 1,874,000 Toyota vehicles covered this Safety Recall.

Model	Model Year	Appx. UIO	Production Range
Corolla	2003-2008	1,150,000	Mid-December, 2001 - Late December, 2007
Matrix	2003-2008	242,000	Mid-December, 2001 - Mid-December, 2007
Tundra	2003-2006	309,000	Late May, 2002 - Late December, 2006
Sequoia	2002-2007	173,000	Early April, 2002 - Early November, 2007

Q8a: Are there any other Toyota/Lexus/Scion vehicles covered by this Safety Recall in the U.S.?

A8a: Yes. There are approximately 34,000 Lexus SC430 vehicles (certain 2002-2010 MY) covered by Lexus recall #DSC in the U.S.

Q9: Is the remedy available for all vehicles?

A9: No. The remedy is NOT available for Certain 2005 – 2008 model year Matrix models at this time.

Model	Model Year	DSF Remedy Availability
Corolla	2003 – 2008	Remedy Available
Matrix	2003 – 2004	Remedy Available
	2005 - 2008	Remedy NOT Available at this time
Tundra	2003 – 2006	Remedy Available
Sequoia	2002 – 2007	Remedy Available

Q10: Why is the remedy no longer available for my vehicle?

A10: Toyota is currently producing parts of an improved design for certain 2005 – 2008 model year Matrix vehicles. When they are available Toyota will resume the remedy for these vehicles and notify customers.

Q11: What should you do if the remedy is NOT available for your vehicle?

A11: To minimize risk, Toyota recommends that no passengers sit in the front passenger seat. If this recommendation is not feasible for the customer's personal or business needs, alternative transportation may be made available.

Q12: What if I previously paid for repairs to my vehicle for this condition?

A12: Reimbursement consideration instruction will be provided in the remedy owner letter.

Q13: What if I have additional questions or concerns?

A13: If you have additional questions or concerns, please contact the Toyota Customer Experience Center at 1-888-270-9371 Monday through Friday, 5:00 am to 6:00 pm, or Saturday 7:00 am to 4:00 pm Pacific Time.



Safety Recalls E04, DSF, F0L – Takata Unrepaired VINs for Dealers

Frequently Asked Questions

Q1: Why is Toyota providing unrepaired VINs to dealers?

A1: Toyota is making every effort to increase the completion rate for the Takata recall. Engaging dealerships in this effort is of vital importance. Toyota recognizes that dealers have local expertise for their market areas and need to know what unrepaired vehicles are in their area in order to provide assistance in our efforts.

Q2: How will Toyota provide unrepaired VINs to dealers?

A2: Toyota is developing an integration within the Service Opportunity Access for Retention (SOAR) system to provide unrepaired VINs and customer contact information to dealers.

Q2a: What if my dealership doesn't use SOAR today?

A2a: At this time, we can only provide this data through the SOAR system. However, SOAR is free to access for all dealers. If your dealership would like to obtain access, find and click the SOAR link on the Service menu in Dealer Daily and follow the instructions to sign up. Note that SET dealers are not involved in the SOAR program.

Q2b: What if I don't have access to SOAR?

A2b: If your dealership is not a current SOAR user, please contact the Dealer Daily administrator within your dealership to gain access. Only users who have a business need to access the data within SOAR should be provided access.

Q3: Are there any special conditions or terms of use involved with this data?

A3: Yes, each time a dealer accesses the data in SOAR, they will be required to agree to a series of terms and conditions. The use of this data is strictly prohibited for any purpose other than contacting customers about the incomplete recall on their vehicle. It cannot be used for marketing of any kind.

Q4: Can I download the data and provide to members of my dealership to reach out to customers?

A4: Yes, we encourage you to use the data to reach customers in your area for the purpose of informing them about an open recall. We ask that you keep in mind that Terms and Conditions state that you may not load this data into any other database and you may not retain the data for longer than is necessary to reach out to customers for that purpose.

Q5: Will I be able to use my OCPe National Business Partner (Epsilon, AutoPoint, Gulf States Marketing) to reach out to customers in my area?

A5: Yes. A similar integration with National Business Partners which exists today in SOAR will be available for the Takata unrepaired VINs.

Q5a: Can I provide the data to other Third-Party Vendors?

A5a: Yes, but any Third-Party Vendor which receives this data must be contractually bound in writing to the same Terms and Conditions which dealers agree to when accessing the data.

Q6: Will Toyota purge the list of unrepaired VINs in my area as they are repaired?

A6: Yes, each night SOAR will be purged of any VINs for which repair warranty claims were received on the previous day.

Q7: What data will be available in SOAR?

A7: VIN, customer name, address, phone number, and email address. Note that phone number and email address may not be available for all VINs.

Q8: What can I send to customers to notify them about their open recall?

A8: Toyota has created specific templates. Dealers MUST use these templates for all communications. These communications have been designed so that dealers can incorporate their own logo, contact information, and links to online scheduling systems.

Q8a: Where can I obtain the communication templates?

A8a: Communication templates will be available within SOAR for download.

Q8b: Can I change the content of the templates?

A8b: No. These specific templates have been reviewed as part of the National Highway Traffic Safety Administration's (NHTSA) Coordinated Remedy Program. Consistent messaging in communications about the Takata recalls is important. Dealers should not change the content of the template aside from adding their dealer logo and contact information. Links to online appointment scheduling can be added as well as service hours if desired by the dealer.

Q9: What are the terms and conditions of use?

A9: Terms and conditions are shown below. Dealers will be required to agree to these terms and conditions each time they access this data on VINs with unrepaired Takata inflators in SOAR. Failure to adhere to any of these terms can result in being denied access to unrepaired VIN information.

I (in my capacity as a representative of my dealership, and in my individual capacity) specifically agree and acknowledge that:

- a. I am authorized to download and use the Recall Customer Data solely in connection with Toyota, Lexus, and Scion recalls and only to call Customers or send Customers direct mail or email reminders to notify them there is an open recall for their Toyota, Lexus or Scion vehicle (the "Permitted Purpose").
- b. Recall Customer Data means customer first and last name, physical address, phone number, email address and VIN associated with an open recall.
- c. I will not use any Recall Customer Data information for marketing of any kind and I will not include any sales, service or other retail marketing messages in recall reminder communications.
- d. I understand that all Recall Customer Data is confidential and proprietary to Toyota Motor Sales, U.S.A., Inc. and its designees ("Toyota"), and I shall not disclose it to any person or entity, unless approved in advance and in writing by Toyota.
- e. I shall protect and will not share my access credentials to this Recall Customer Data with anyone (other than, if necessary, with our dealership's systems administrator solely for the limited purpose of supporting the Permitted Purpose).
- f. I will not access or use this Recall Customer Data for unauthorized, fraudulent or malicious purposes, or in a manner that could damage, disable, overburden or impair any of the systems in which the Recall Customer Data is being provided.
- g. I understand that storage of the Recall Customer Data within any database or other methodology (including on printed materials) for any activity beyond the Permitted Purpose is prohibited. In particular, none of the Recall Customer Data shall be shared, stored, published, sold or used for any marketing purposes (including not used to 'cleanse' or validate information in any marketing or customer database).
- h. I understand that retention of the Recall Customer Data must not exceed a period of time necessary to ensure completion of the applicable open recall.
- i. I am authorized to share the Recall Customer Data with third party vendors acting on behalf of my dealership solely for the Permitted Purpose so long as each such vendor complies with these same limitations and restrictions that apply to me and my dealership (and has committed to do so under a binding written agreement).
- j. I will follow all other specific instructions that Toyota may issue from time to time about the use of the Recall Customer Data.

Certain 2003-2008 Model Year Corolla and Corolla Matrix,
Certain 2003-2006 Model Year Tundra, and
Certain 2002-2007 Model Year Sequoia Vehicles
Front Passenger Airbag Inflator Module
SAFETY RECALL NOTICE (Remedy Notice)

This notice applies to your vehicle [VIN]
NHTSA Recall No. 15V-285 and 16V-127

**URGENT SAFETY
RECALL**

This is an important
Safety Recall
Notification. **The remedy
will be performed at NO
CHARGE to you.**

Dear Toyota Owner:

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Toyota has decided that a defect, which relates to motor vehicle safety, exists in certain 2003-2008 model year Corolla and Corolla Matrix, 2003-2006 model year Tundra, and 2002-2007 model year Sequoia vehicles.

You received this notice because our records, which are based primarily on state registration and title data, indicate that you are the current owner.

What is the condition?

The subject vehicles are equipped with front passenger airbag inflators which may have been manufactured in such a way as to have a potential for the intrusion of moisture over time. Depending on the circumstances, this could create excessive internal pressure when the airbag is deployed and cause the inflator to rupture. In the event of an inflator rupture, metal fragments could pass through the airbag cushion material, striking the vehicle occupants and potentially resulting in serious injury or death.

What will Toyota do?

Any authorized Toyota dealer will replace the passenger airbag inflator module at **no charge** to you. (For certain models, the front passenger airbag assembly may be replaced.)

What should you do?

This is an important Safety Recall.

Toyota has completed parts preparation for vehicles in your geographic area. Please contact any authorized Toyota dealer to schedule an appointment to have this remedy performed as soon as possible. The repair will take approximately 2 hours. However, depending on the dealer's work schedule, it may be necessary to make your vehicle available for a longer period of time.

Until the remedy is performed, we recommend that you do not operate the vehicle with an occupant in the front passenger seat. We sincerely apologize for any inconvenience this will cause, but we are taking this action to ensure your safety.

You do not need an owner letter to have this recall completed; however, to assist the dealer in confirming vehicle eligibility, we request that you present this notice at the time of your service appointment.

If you would like to update your vehicle ownership or contact information, you may do so by registering at www.toyota.com/ownersupdate. You will need your full 17-digit Vehicle Identification Number (VIN) to input the new information.

What if you have other questions?

- ***Your local Toyota dealer will be more than happy to answer any of your questions and set up an appointment to perform the repair.***
- You can find additional information and locate a Toyota dealer in your area by going online and visiting www.toyota.com/recall.
- If you require further assistance, you may contact the Toyota Customer Experience Center at 1-888-270-9371 Monday through Friday, 5:00 am to 6:00 pm, Saturday 7:00 am to 4:00 pm Pacific Time.

- If you believe that the dealer or Toyota has failed or is unable to remedy the defect within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue S.E., Washington, D.C. 20590, or call the toll free Vehicle Safety Hot Line at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>.

•
What if you have previously paid for repairs to your vehicle for this specific condition?

If you have previously paid for repairs to address this specific condition, please mail all required paperwork* to the following address for reimbursement consideration and allow 6-8 weeks for processing:

Toyota Motor Sales, U.S.A., Inc
Toyota Customer Experience, WC10
19001 South Western Avenue, Torrance, CA 90509

* Please refer to the attached Reimbursement Checklist for required paperwork details.

Please note that the dealer must complete the Safety Recall remedy before reimbursement consideration request can be processed.

If you are a vehicle lessor, Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

We have sent this notice in the interest of your continued satisfaction with our products, and we sincerely regret any inconvenience this condition may have caused you.

Thank you for driving a Toyota.

Sincerely,
TOYOTA MOTOR SALES, U.S.A., INC.

SAMPLE



Published October 13, 2016

Toyota Motor Sales, USA, Inc.
19001 South Western Avenue
Torrance, CA 90501
(310) 468-4000

PRE-OWNED – SAFETY RECALL CUSTOMER CONTACT & VEHICLE DISCLOSURE FORM

Pre-Owned Vehicles **ONLY** (Not Applicable for TCUV units)

This vehicle is involved in a Safety Recall. At this time, remedy parts are not available and the remedy has **NOT** been performed. I understand that the vehicle will need to be returned to an authorized Toyota dealer to have the remedy performed at **NO CHARGE** when the remedy is available.

Customer Signature _____

Toyota recommends that you register with the Toyota Owners Community at <http://www.toyota.com/owners/> and regularly check recall applicability using www.toyota.com/recall or www.safercar.gov. You will need to input your 17-digit Vehicle Identification Number (VIN).

VIN

Campaign Code

Model _____ Model Year _____

Customer Information

Customer Name _____	Customer Email _____
Customer Address _____	Home Phone # _____
_____	Mobile Phone # _____
_____	Date _____

Please provide this information so that Toyota or your dealer can notify you when the remedy becomes available. This information will only be used for Safety Recall and other campaign communications. If you'd like to update your preferred contact information in the future, visit www.toyota.com/ownersupdate or contact us at 1-888-270-9371.

Dealer Information

Dealer Name/Address _____	Dealer Code _____
_____	Dealer Phone Number _____
_____	Dealer Staff Name _____
_____	Dealer Staff Signature _____