

GLOBAL SAFETY FIELD INVESTIGATIONS  
DCS4816  
URGENT - DISTRIBUTE IMMEDIATELY

Date: November 9, 2017

Subject: 15240D - Safety Recall Revised  
Power Lift Gate Prop Rod Recovery  
  
15299C – Safety Recall Revised  
Driver Side Rear Pillar Interior Fires  
  
21510A - Safety Recall Revised  
Loss of Power Steering Assist  
  
51230-02 – Safety Recall Revised  
Manual Service Disconnect Not Seated

Models: Bulletin 15240D: 2007-2010 Saturn Outlook, 2007-2012 GMC  
Acadia, 2009-2012 Chevrolet Traverse, 2008-2012 Buick Enclave  
Equipped with Power Lift Gate and Built Prior to March 10, 2012  
  
Bulletin 15299C: 2013-2016 Cadillac ATS Sedan  
  
Bulletin 21510A: 2016 Buick Regal All-Wheel Drive with Equipped  
Electric Power Steering  
  
Bulletin 51230-02: 2016 Chevrolet Malibu Hybrid

To: All General Motors Dealers

The Service Procedure and the Warranty Information sections have been revised. Effective immediately, technicians MUST record the SPS Warranty Claim Code on the job card. To avoid warranty transaction rejection, this information must be entered when submitting the transaction. Please discard all previous copies of the subject bulletins.

END OF MESSAGE  
GLOBAL SAFETY FIELD INVESTIGATIONS