



Campaign #2A46




SAFETY RECALL NOTICE



2 *****AUTO**SCH 3-DIGIT 191

PRSRT 1ST CLASS
U.S. POSTAGE
PAID
Whittier, CA
Permit No. 175

SUZUKI
SUZUKI MOTOR OF AMERICA, INC.
P.O. Box 1100
Brea, California 92822-1100



IMPORTANT SAFETY RECALL NOTICE
This Notice Applies to Your Motorcycle VIN: XXXXXXXXXXXXXXXXX

July 17, 2015

Dear Suzuki Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Suzuki Motor Corporation has decided that a defect which relates to motor vehicle safety exists in certain Suzuki Genuine Accessory backrest mounting hardware kits (Part Number 990A0-75148 or Part Number 990A0-75148-BLK). These mounting hardware kits may have been used to install accessory backrests on 2006 - 2015 VZR1800 (Boulevard M109R) motorcycles.

What is the problem?

The mounting hardware for installing the Suzuki Genuine Accessory backrest P/N 990A0-75148 and P/N 990A0-75148-BLK on 2006 - 2015 Suzuki VZR1800 (Boulevard M109R) motorcycles may contain 110mm mounting bolts, which is an incorrect length. Under certain loads and riding conditions, it may be possible for the mounting bolts to contact the rear tire, damaging it and/or causing loss of control, increasing the risk of a crash.

WARNING

If the backrest mounting bolts come into contact with the rear tire, the rider could lose control, increasing the risk of a crash.
If your motorcycle has the affected backrest mounting hardware described below, contact your Suzuki dealer to have the mounting bolts replaced.

Continued next page.

IMPORTANT: If you have sold or traded your Suzuki vehicle, please enter the owner's name and address, if known, on the attached "Change of Information" postcard, tear off at both perforations, and drop it in the mail. Postage has already been paid. We will contact the new owner.
Federal law requires that any vehicle lessor receiving this campaign notice must forward a copy of this notice to the lessee within ten days. Lessor means a person or entity that is the owner, as reflected on the vehicle title, of any five or more leased vehicles.

Tear Here

We're looking to the future by recycling today.



NAME OR ADDRESS CORRECTION

If you own the vehicle shown in the box below, and the name and address is incorrect, please enter your correct name and address here.

NAME _____
ADDRESS _____
CITY _____
STATE _____ ZIP _____

Change Of Ownership/Address
Suzuki Genuine Accessory
Backrest Mounting Hardware Recall



If you do not own the vehicle shown in the box above, please fill in the following information as applicable

- ☐ Never owned this vehicle ☐ Vehicle stolen ☐ Vehicle scrapped / Total loss
☐ Vehicle sold / transfered/ traded ☐ Vehicle exported ☐ Other

If you have sold or traded the vehicle and know the name of the new owner, please enter the name and address in the space above.


Campaign #2A46

Tear Here

Continued from prior page.


How to identify if your motorcycle needs this repair:

If the motorcycle is equipped with early model backrest mounting brackets with cutouts as shown below, no action is needed.




Early Model Brackets
NO REPAIR NEEDED
Because it is equipped with two 75mm and two 95mm mounting bolts.

If the motorcycle is equipped with late model backrest mounting brackets without cutouts and it does NOT have saddlebag supports, the mounting bolts must be replaced.



Late Model Bracket
without saddlebag supports NEEDS REPAIR
Because it is equipped with incorrect four 110mm mounting bolts — these bolts must be replaced with correct 75mm (two) and 95mm (two) mounting bolts.

If the motorcycle is equipped with late model backrest mounting brackets without cutouts and it is equipped with Suzuki Genuine saddlebag supports (P/N 990A0-75049), no action is needed.



Late Model Bracket
with saddlebag supports NO REPAIR NEEDED
Because it is equipped with longer four 110mm mounting bolts required for the saddlebag supports. Shorter 75mm (two) and 95mm (two) bolts are not required.
SEE WARNING BELOW.

⚠ WARNING

If the Suzuki Genuine saddlebag supports (P/N 990A0-75049) are removed and the saddlebag support bolts are used to install only the backrest, these bolts are an incorrect length and may come into contact with the rear tire. This may cause the rider to lose control, increasing the risk of a crash.

If the saddlebag supports are removed, the mounting bolts must be replaced using Suzuki bolt kit P/N 990A0- 75048-002 or P/N 990A0-75048-003 (black). Please contact an authorized Suzuki dealer before removing the saddlebag supports. Your Suzuki dealer will remove the saddlebag supports and replace the mounting bolts.

Continued next page.

Continued from prior page.

What is Suzuki Motor of America, Inc., doing to solve the problem?

If your backrest was installed with the incorrect mounting bolts, your Suzuki dealer will replace them with the correct mounting bolts. This procedure will take approximately 10 minutes to complete. Parts are available now, and there will be no charge to you for any recall service-related parts or labor.

What you should do:

- Make sure you are prepared for the recall service by taking the following steps:
- Before taking your vehicle to your dealer, contact them as soon as possible to set up an appointment for the recall service.
 - We suggest that you bring this letter to your dealer to help your dealer process your claim.

What to do if you receive this letter in error:

This notice was mailed to you according to the most current information we have available. If you no longer own the Suzuki vehicle described in this letter, please complete and return the attached postage-paid card to Suzuki Motor of America, Inc., and forward this recall information to the current owner (if known).

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Customer reimbursement for remedies prior to recall notification:

If your motorcycle is included in the recall and you have paid for replacement of the backrest mounting bolts or other repairs to address the defect that led to this recall, you may be eligible for full or partial reimbursement. **To request reimbursement for a previous repair, contact your Suzuki dealer.**

Please note the following conditions for reimbursement:

- Only repairs made to address the defect that led to this recall are reimbursable. Additional expenses such as towing, car rental, accommodations, damage repairs, etc., will not be reimbursed. Reimbursement will not be provided for routine scheduled maintenance.
- Reimbursement may be limited to the suggested list price for parts, the Suzuki published flat rate time allowance for the repair, and the labor rate that an authorized Suzuki dealer in the same area would charge for the same repair.
- An owner will not be eligible for reimbursement if the expenses for repairs are incurred more than 10 days after the
- date of the last owner notification letter sent by Suzuki Motor of America, Inc.
- Reimbursement claims may also be excluded when inadequate documentation is not submitted by the claimant. This includes a proof of ownership, a repair order, and proof of payment for the repair.

Who to contact if you experience problems:

Your Suzuki dealer can provide you the fastest response to your questions or concerns about the VZR1800 (Boulevard M109R) Backrest Mounting Bolts Safety Recall. If you have any difficulty with this recall campaign, you may contact the Suzuki Motor of America, Inc., Customer Service Department for assistance at (714) 572-1490 during the hours of 7:00 AM to 4:30 PM Pacific Time. Please have your Vehicle Identification Number (VIN) ready when calling. You may also leave a brief message at (800) 444-5077 and a representative from the Suzuki Motor of America, Inc., Customer Service Department will contact you.

If you believe that Suzuki Motor of America, Inc., has failed to provide the Recall service without charge or is unable to do so within a reasonable time, you may submit a complaint to the Administrator of the National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington D.C., 20590 or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-888-424-9153) or go to: www.safercar.gov

We apologize for any inconvenience this recall campaign causes you. We hope you understand that your safety, satisfaction and riding pleasure are important priorities for Suzuki.

Sincerely,

Suzuki Motor of America, Inc.

To mail card, tear at both perforations & remove this piece.

← Tear Here →

← Tear Here →

**NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES**

BUSINESS REPLY MAIL
FIRST-CLASS MAIL PERMIT NO 107 BREA CA
POSTAGE WILL BE PAID BY ADDRESSEE

**MOTORCYCLE DIVISION / WARRANTY
SUZUKI MOTOR OF AMERICA, INC.
PO BOX 1100
BREA, CA 92822-9988**

Vertical bars for postage identification

Horizontal bars for postage identification

Barcode for postage identification