



Revised January 2016

Dealer Service Instructions for:

Safety Recall R06 / NHTSA 15V-046 Occupant Restraint Control Module

NOTE: The service procedure has been updated to address KJ models without side curtain airbags (pages 10 and 11).

Models

- 2002 – 2003 (KJ) Jeep® Liberty**
- 2002 – 2004 (WJ) Jeep® Grand Cherokee**
- 2003 – 2004 (ZB) Dodge Viper**

IMPORTANT: Some of the involved vehicles may be in dealer used vehicle inventory. Dealers should complete this recall service on these vehicles before retail delivery. Dealers should also perform this recall on vehicles in for service. Involved vehicles can be determined by using the VIP inquiry process.

Subject

The airbag system Occupant Restraint Control (ORC) module on about 745,800 of the above vehicles may experience a front airbag and/or seatbelt pretensioner inadvertent deployment. An inadvertent deployment while driving could distract the driver and cause a crash without warning.

Repair

The ORC module must be replaced on all involved vehicles.

Also, vehicles that had **Safety Recall M35/N13 - Occupant Restraint Control Module Filter Circuit** completed must also have the ORC module filter circuit removed.

Parts Information

ORC Module Packages with Impact Sensors:

<u>Part Number</u>	<u>Description</u>
CBSZR062AA	Module, ORC (2002 KJ models)
CBSZR064AA	Module, ORC (2003 KJ models)
CBSZR067AA	Module, ORC (WJ models <u>with</u> Supplemental Side Airbags / with sales code CGS)

NOTE: To better manage required inventory for this recall, only approximately 10% of involved vehicles are expected to require impact sensor replacement.

ORC Module Packages without Impact Sensors:

<u>Part Number</u>	<u>Description</u>
CBSZR065AA	Module, ORC (WJ models <u>without</u> Supplemental Side Airbags / without sales code CGS)
CBSZR066AA	Module, ORC (WJ models <u>with</u> Supplemental Side Airbags / sales code CGS)
CBSZR061AA	Module, ORC (2002 KJ models)
CBSZR063AA	Module, ORC (2003 KJ models)

NOTE: The ORC module packages (without impact sensors) above are only compatible with the impact sensors that originally came on the vehicle.

SPECIAL NOTE: For all (WJ) Jeep Grand Cherokee models, the new ORC modules provided in this recall do not require front impact sensors to operate correctly. The front impact sensors are permanently disabled. Do not order or replace the front impact sensors on WJ models.

<u>Part Number</u>	<u>Description</u>
CBXTM352AA	Switch, Transfer Case

Parts Information (Continued)

<u>Part Number</u>	<u>Description</u>
CBSZR068AA	Module, ORC (All ZB models)

<u>Part Number</u>	<u>Description</u>
68065586AA	Tape, Abrasion (one roll of abrasion tape will repair 10 vehicles)

NOTE: The abrasion tape is only required for repairing WJ models.

Dealers should determine which ORC module is required for each vehicle at the time appointments are scheduled to assure that the correct part is available when the customer arrives. The ORC module for the vehicle to be serviced may be determined by:

- Using GRS, enter DealerCONNECT, click on the “**Service**” tab, click on “**Global Recall System,**” enter the **recall number** in the “Recall Code:” box, and select “**VIN**” in the “List By:” drop down menu.
- Using VIP, enter DealerCONNECT, click on the “**Service**” tab, click on “**Single VIN Inquiry,**” enter the **VIN and mileage**, click “**View,**” and click on the “**Recall**” tab.

Parts Return

No parts return required for this campaign.

Special Tools

The following special tools are required to perform this repair:

- NPN wiTECH VCI Pod Kit
- NPN Laptop Computer
- NPN wiTECH Software

Service Procedure**A. Determine ORC Module Package Required (All Models)**

1. Connect the wiPOD to the vehicle data link connector.

CAUTION: Do not use a MicroPOD II while using the wiTECH DRBIII emulator. A VCI pod should be used to connect to the vehicle.

2. Start a wiTECH session.
3. Select (1) “DRB III Standalone”.
4. Select (1) “1998-2007 Diagnostics”.
5. Select (1) “All (Except Below)”.
6. Select (6) “Passive Restraints”
7. Select (1) “Airbags”.
8. Select (2) “Read DTC’s”.
9. Select (1) “Active”.
10. Select “Page Back” and then select (2) “Stored”.
11. Record active and stored Diagnostic Trouble Codes (DTC’s) for right and left front impact sensors on KJ models and right and left side impact sensors on WJ models:

- If there are no Impact Sensor DTC’s, replace the Occupant Restraint Control (ORC) module.

NOTE: Install a new ORC module package that does not contain impact sensors.

- If there are Impact Sensor DTC’s, replace the Occupant Restraint Control (ORC) module and both impact sensors.

NOTE: Install a new ORC module package that contains new impact sensors.

CAUTION: If only the ORC module requires replacement at this time and at some point in the future an impact sensor(s) requires replacement, the ORC module and both impact sensors will require replacement. The ORC module packages (without impact sensors) in this recall contain an ORC module that is not compatible new impact sensors.

SPECIAL NOTE: If after completing this recall the airbag warning light is still illuminated, the cost to make additional repairs to other airbag system components is the responsibility of the vehicle owner.

Service Procedure**B. Replace ORC Module (KJ Models)**

WARNING: TO AVOID SERIOUS OR FATAL INJURY ON VEHICLES WITH AIRBAGS, DISABLE THE SUPPLEMENTAL RESTRAINT SYSTEM (SRS) BEFORE ATTEMPTING THIS REPAIR PROCEDURE. DISCONNECT AND ISOLATE THE BATTERY NEGATIVE (GROUND) CABLE, THEN WAIT TWO MINUTES FOR THE SYSTEM CAPACITOR TO DISCHARGE BEFORE PERFORMING SERVICE. THIS IS THE ONLY SURE WAY TO DISABLE THE SRS. FAILURE TO TAKE THE PROPER PRECAUTIONS COULD RESULT IN ACCIDENTAL AIRBAG DEPLOYMENT.



Figure 1 – Center Console Bezel and Shift Boot

1. Open the hood and disconnect the negative battery cable from the battery.
2. Remove and save the gear shift lever center console bezel (Figure 1).
3. Apply the park brake and place gear shift lever in the neutral position.
4. **For vehicles equipped with four wheel drive**, place the four wheel drive selector handle in the “four wheel low” position.
5. **For vehicles equipped with four wheel drive**, remove and save the four wheel drive lever shift handle boot (Figure 1).
6. **For vehicles with power windows**, remove and save the front window switch assembly (Figure 2).



Figure 2 – Front Window Switch Assembly

Service Procedure (Continued)

- 7. Remove and save the rear window switch assembly from the center console (Figure 3).
- 8. Remove and save the four center console retaining screws.
- 9. Carefully remove and save the center console assembly.
- 10. **For vehicles that had Safety Recall M35 performed**, remove and discard the foil mastic patch from the ORC module rubber cover (Figure 4).



Figure 3 – Rear Window Switch Assembly

- 11. Remove and save the ORC module rubber cover (Figure 4).




Figure 4 – Remove and Discard Foil Mastic Patch

Service Procedure (Continued)

12. For vehicles that had Safety Recall M35 performed, disconnect the ORC module jumper harness electrical connector from the body wire harness (Figure 5).
13. Remove and save the three ORC module mounting bolts.
14. Carefully pull the ORC module out of the vehicle and disconnect filter circuit jumper harness electrical connector (Figure 6).
15. Discard the original filter circuit jumper harness (Figure 6).




Figure 5 – Disconnect Electrical Connector




Figure 6 – Disconnect and Discard the ORC Module Filter Jumper Harness

Service Procedure (Continued)

- 16. Disconnect the small ORC module electrical connector (Figure 7).
- 17. Destroy and discard the original ORC module.
- 18. Connect the large and small body harness electrical connectors to the new ORC module and place the module into position (Figure 7).
- 19. Install the three retaining bolts. Tighten the two large retaining bolts to 26 ft. lbs. (36 N·m). Tighten the small retaining bolt to 105 in. lbs. (12 N·m) (Figure 8).




Figure 7 – Disconnect Small ORC Module Electrical Connector





Figure 8 – Install Three ORC Module Retaining Bolts

Service Procedure (Continued)

20. Clean off any residual glue on the ORC module rubber cover left behind by the foil mastic patch.
21. Place the ORC module rubber cover into position over the ORC module (Figure 9).
22. Install the center console assembly into position.

**Figure 9 – ORC Module Rubber Cover**

23. Install the four center console retaining screws.
24. Install the rear window switch assembly (Figure 3).
25. Install the front window switch assembly (Figure 2).
26. **For vehicles equipped with four wheel drive**, install the four wheel drive lever shift handle boot (Figure 1).
27. Install the gear shift lever center console bezel (Figure 1).

Service Procedure (Continued)

28. **For vehicles that require front impact sensors**, continue with **Section C, Front Impact Sensor Replacement**.
29. **For vehicles that do not require front impact sensors**, continue with Step 30 of this procedure.
30. Turn the ignition key to the “RUN” position, with no one inside the vehicle, connect the negative battery cable to the battery.
31. Reset the clock on the radio.
32. Start the vehicle.
33. Connect the wiTECH scan tool and check for impact sensor and/or ORC module DTC’s:
 - If there are no impact sensor and/or ORC module DTC’s, continue with Step 34 of this procedure.
 - If there are impact sensor and/or ORC module DTC’s, make repairs to sensor and/or ORC module as required, then continue with Step 34 of this procedure.

NOTE: All replacement ORC Modules for this recall are configured for the optional side curtain airbag feature.

If a new ORC module is installed in a vehicle that is not equipped with the optional side curtain airbags, the airbag indicator lamp will illuminate and “No Right SIACM” and “No Left SIACM” DTC’s will be registered.

The new ORC module must be configured to disable the side curtain airbag feature using a DRBIII® scan tool or wiTECH DRBIII emulator. Continue with Step 34 of this procedure.

Service Procedure (Continued)

34. **For vehicles without side curtain airbags**, use the following procedure to configure ORC Module:

NOTE: This procedure should only be performed on vehicles with active DTC's "No Right SIACM and No Left SIACM".

- a. From the "SELECT FUNCTION" Screen on the DRBIII select (9) "Miscellaneous" button.
- b. Select (1) "Configure for Side Airbag"
- c. Screen Prompt : "Do you want to continue?" Select "Enter"
- d. Verify Current Status is set to: "ACM with Side Airbags"
- e. Select (2) "ACM without Side Airbags" then "Enter"
- f. Verify Current Status a second time, should now read: "ACM without Side Airbags"
- g. Select **BACK PAGE** to exit.
- h. Select (2) Read DTC's.
- i. Select (1) Active.
- j. Verify No DTC's are Detected.

SPECIAL NOTE: If after completing this recall the airbag warning light is still illuminated, the cost to make additional repairs to other airbag system components is the responsibility of the vehicle owner.

Service Procedure (Continued)

35. **For vehicles equipped with four wheel drive**, place the four wheel drive lever shift handle into the “2 Hi” position.

36. **For vehicles equipped with four wheel drive**, check to insure that the four wheel drive indicator light is not illuminated.
 - If the four wheel drive indicator light is not illuminated, no further action is required. Continue with Step 37 of this procedure.
 - If the four wheel drive indicator light remains on, continue with **Section F. Replace the Four Wheel Drive Indicator Light Switch.**

37. Remove the wiTECH scan tool and return the vehicle to the customer.

Service Procedure (Continued)**C. Front Impact Sensor Replacement**

1. Locate the front impact sensors.

NOTE: The front impact sensors are located to the right and left of the radiator on the radiator support vertical member (Figure 10).

2. Remove and save the two mounting bolts on the front impact sensor.
3. Disconnect the electrical connector from the front impact sensor.
4. Remove and discard the original front impact sensor.



Figure 10 – Front Impact Sensor Location

Service Procedure (Continued)

5. Connect the vehicle wire harness connector to the new front impact sensor.
6. Place the new front impact sensor into position and install the mounting bolts. Tighten the mounting bolts to 65 in. lbs. (7 N·m).
7. Repeat Steps 1 through 6 to replace the second front impact sensor.
8. Turn the ignition key to the “RUN” position, with no one inside the vehicle, connect the negative battery cable to the battery.
9. Reset the clock on the radio.
10. Connect the wiTECH scan tool and check for impact sensor and/or ORC module DTC's:
 - If there are no impact sensor and/or ORC module DTC's, continue with Step 11 of this procedure.
 - If there are impact sensor and/or ORC module DTC's, make repairs to sensor and/or ORC module as required, then continue with Step 11 of this procedure.
- SPECIAL NOTE: If after completing this recall the airbag warning light is still illuminated, the cost to make additional repairs to other airbag system components is the responsibility of the vehicle owner.**
11. **For vehicles equipped with four wheel drive**, place the four wheel drive lever shift handle into the “2 Hi” position.
12. **For vehicles equipped with four wheel drive**, check to insure that the four wheel drive indicator light is not illuminated.
 - If the four wheel drive indicator light is not illuminated, continue with Step 13 of this procedure.
 - If the four wheel drive indicator light remains on, continue with **Section F. Replace the Four Wheel Drive Indicator Light Switch.**
13. Remove the wiTECH scan tool and return the vehicle to the customer.

Service Procedure (Continued)**D. Replace ORC Module (WJ Models)**

WARNING: TO AVOID SERIOUS OR FATAL INJURY ON VEHICLES EQUIPPED WITH AIRBAGS, DISABLE THE SUPPLEMENTAL RESTRAINT SYSTEM (SRS) BEFORE ATTEMPTING THIS REPAIR PROCEDURE. DISCONNECT AND ISOLATE THE BATTERY NEGATIVE (GROUND) CABLE, THEN WAIT TWO MINUTES FOR THE AIRBAG SYSTEM CAPACITOR TO DISCHARGE BEFORE PERFORMING SERVICE. THIS IS THE ONLY SURE WAY TO DISABLE THE SRS. FAILURE TO TAKE THE PROPER PRECAUTIONS COULD RESULT IN ACCIDENTAL AIRBAG DEPLOYMENT.

**Figure 11 – Storage Bin Screws**

1. Disconnect the negative battery cable.
2. Remove and save the center console using the following procedure:
 - a. Remove and save the two retaining screws in the console storage bin (Figure 11).
 - b. Remove and save the cup holder insert from the console (Figure 11).
 - c. Remove and save the two screws under the cup holder insert (Figure 12).

**Figure 12 – Cup Holder Screws**

Service Procedure (Continued)

d. Open the center console and remove and save the two screws at the bottom of the console storage bin (Figure 13).

e. Remove and save the center console assembly (Figure 14).




Figure 13 – Console Storage Bin Screws




Figure 14 – Remove/Install Center Console

Service Procedure (Continued)




Figure 15 – Remove and Discard the ORC Module Filter Circuit Jumper Harness

3. For all vehicles that had Safety Recall M35 previously performed, remove and discard the ORC module filter circuit jumper harness (Figure 15).

NOTE: Only vehicles that had Safety Recall M35 completed will have an ORC module filter circuit jumper harness.

4. Remove, destroy, and discard the original ORC module (Figure 16).




Figure 16 – Remove and Discard Original ORC Module

Service Procedure (Continued)

5. Using Mopar glass cleaner or equivalent, clean the ORC module mounting surface (Figure 17).
6. Place the new ORC module into position and install the mounting bolts (Figure 18). Tighten the bolts to 95 in. lbs. (11 N·m).




Figure 17 – Clean ORC Module Mounting Surface




Figure 18 – Install New ORC Module

Service Procedure (Continued)

7. Using the supplied tape, wrap the wire harness with tape to protect the wires (Figure 19).
8. Connect the yellow ORC module wire harness electrical connectors to the ORC module (Figure 20).
9. Route the wires as shown in Figure 20 and secure them with two plastic tie straps.

CAUTION: Make sure that all wire harnesses are routed to prevent chafing and/or wire harness damage.




Figure 19 – Wrap Wiring with Tape




Figure 20 – Wire Routing and Tie Strap Location

Service Procedure (Continued)

10. Install the center console.
11. **For vehicles that require side impact sensor replacement,** perform the following steps:
 - a. Remove and save the seat belt anchor bolt (Figure 21).
 - b. Remove and save the “B” pillar trim panel (Figure 21).
 - c. Remove and discard the original side impact sensor (Figure 22).
 - d. Install the new side impact sensor. Tighten the retaining bolts to 105 in. lbs. (12 N·m).



Figure 21 – Seat Belt Anchor Bolt



Figure 22 – Side Impact Sensor Location

Service Procedure (Continued)

- e. Install the “B” pillar trim panel.
- f. Install the seat belt anchor bolt (Figure 21).
- g. Repeat Steps 11a. through 11f. on the opposite side of the vehicle to replace the second side impact sensor.

SPECIAL NOTE: On all (WJ) Grand Cherokee models, all of the new ORC modules provided in this recall do not require front impact sensors to operate correctly. The front impact sensors are permanently disabled.

- 12. Turn the ignition key to the “RUN” position, with no one inside the vehicle, connect the negative battery cable to the battery.
- 13. Reset the clock on the radio.
- 14. Connect the wiTECH scan tool to the vehicle and check for impact sensor and/or ORC module DTC’s:
 - If there are no impact sensor and/or ORC module DTC’s, continue with Step 15 of this procedure.
 - If there are impact sensor and/or ORC module DTC’s, make repairs to sensor and/or ORC module as required, then continue with Step 15 of this procedure.

SPECIAL NOTE: If after completing this recall the airbag warning light is still illuminated, the cost to make additional repairs to other airbag system components is the responsibility of the vehicle owner.

- 15. Remove the wiTECH scan tool from the vehicle.
- 16. Return the vehicle to the customer.

Service Procedure (Continued)**E. Replace ORC Module (ZB Models)**

WARNING: DISCONNECT AND ISOLATE THE NEGATIVE BATTERY CABLE AT THE NEGATIVE BATTERY POST BEFORE BEGINNING AIRBAG SYSTEM COMPONENT REMOVAL OR INSTALLATION PROCEDURES. THIS WILL DISABLE THE AIRBAG SYSTEM. FAILURE TO DISCONNECT THE BATTERY COULD RESULT IN ACCIDENTAL AIRBAG DEPLOYMENT AND POSSIBLE PERSONAL INJURY.

WARNING: ALLOW THE SYSTEM CAPACITOR TO DISCHARGE FOR TWO MINUTES BEFORE REMOVING ANY AIRBAG COMPONENTS.

1. Roll down both windows.
2. Open the rear deck lid.
3. Remove and save the battery access cover located in the trunk.
4. Disconnect and isolate the negative battery cable from the battery (Figure 23).




Figure 23 – Battery Location

Service Procedure (Continued)**Figure 24 – Center Console Top Cover**

5. Disengage the center console top cover from the center console (Figure 24).
6. Reaching under the center console top cover, loosen the jam nut that retains the gear shift lever extension to the transmission shifter shaft (Figure 24).
7. Unscrew and save the gear shift lever extension and gear shift ball as an assembly (Figure 24).
8. Remove and save the center console top cover (Figure 24).

Service Procedure (Continued)

9. Remove and save the eight instrument panel center stack bezel retaining screws and then remove the center stack bezel and HVAC control panel as an assembly (Figure 25).




Figure 25 – Center Stack Bezel

10. Carefully remove and save the radio (Figure 26).



Figure 26 – Radio Remove/Install

Service Procedure (Continued)

11. Remove and save the left side knee bolster (Figure 27).



Figure 27 – Knee Bolster

12. Remove and save the left instrument panel speaker cover (Figure 28).



Figure 28 – Left Speaker Cover

13. Remove and save the four steering column nuts and carefully lower the steering column.

Service Procedure (Continued)

14. Remove and save the instrument cluster bezel (Figure 29).
15. Remove and save the instrument panel center stack white gauge cluster (Figure 30).
16. Remove and save the instrument panel black plastic frame retaining screws (Figure 30).
17. Temporarily reinstall the steering column.



Figure 29 – Instrument Cluster Bezel





Figure 30 – Instrument Panel Center Stack Gauge Cluster and Frame Retaining Screws

Service Procedure (Continued)

18. Carefully relocate all of the disconnected instrument panel electrical connectors located near the ORC module.
19. Disengage the center console wire harness at the floor stud on the floor board (Figure 31).
20. Disconnect the ORC module yellow connectors.

**Figure 31 – Floor Stud**

21. Remove and save the ORC module mounting bolts.
22. Remove, destroy, and discard the original ORC module.
23. **For vehicles that had Safety Recall N13 performed**, remove and discard the ORC module filter circuit harness and box.
24. Install the new ORC module.
25. Install the ORC module mounting bolts. Tighten the bolts to 95 in. lbs. (11 N·m).
26. Connect the yellow body wire harness to the ORC module connectors.
27. Secure the center console wire harness to the floor stud on the floor board (Figure 24).
28. Install the instrument panel black plastic frame retaining screws. Tighten the screws securely (Figure 30).
29. Install the instrument panel center stack white gauge cluster (Figure 30).

Service Procedure (Continued)

30. Install the radio assembly (Figure 26).
31. Lower the steering column.
32. Install the instrument cluster bezel (Figure 29).
33. Install the left instrument panel speaker cover (Figure 28).
34. Install the steering column. Tighten the four steering column retaining nuts to 150 in. lbs. (17 N·m).
35. Install the left side knee bolster (Figure 27).
36. Install the instrument panel center stack bezel (Figure 25).
37. Place the center console top cover partially into position (Figure 24).
38. Screw the gear shift lever extension onto the transmission shifter shaft.


Service Procedure (Continued)

Figure 32 – Install Gear Shift Extension and Tighten Jam Nut

39. Reaching under the center console top cover, tighten the jam nut that retains the gear shift lever extension to the transmission shifter shaft (Figure 32).

NOTE: Be sure that the gear shift knob gear shift pattern indicator is correctly orientated before tightening the jam nut.

40. Snap the center console top cover into position.
41. Place the ignition to the run position.
42. After checking that no one is inside the vehicle, connect the negative battery cable.
43. Install the battery access panel and close the deck lid (Figure 23).

Service Procedure (Continued)


44. Connect the wiTECH scan tool to the vehicle and check for ORC module DTC's:
- If there are no ORC module DTC's, continue with Step 45 of this procedure.
 - If there are ORC module DTC's, make repairs to the ORC module as required, then continue with Step 45 of this procedure.

SPECIAL NOTE: If after completing this recall the airbag warning light is still illuminated, the cost to make additional repairs to other airbag system components is the responsibility of the vehicle owner.

45. Remove the wiTECH scan tool from the vehicle.
46. Reset the clock on the radio.
47. Return the vehicle to the customer.

Service Procedure (Continued)**F. Replace the Four Wheel Drive Indicator Light Switch**

1. Carefully lift the vehicle on an appropriate hoist.
2. Disconnect the transfer case shift cable at the transfer case lever on the transfer case.
3. Remove and save the three transfer case shift cable bracket mounting bolts on the side of the transfer case.
4. Relocate the transfer case shift cable bracket and shift cable to gain access to the transfer case four wheel drive indicator light switch (Figure 33).

**Figure 33 – Shift Cable and Bracket**

5. Using a 1 ½ inch socket, remove and discard the original transfer case four wheel drive indicator light switch (Figure 34).
6. Install the new transfer case four wheel drive indicator light switch. Tighten the switch to 20 ft. lbs. (27 N·m).
7. Place the transfer case shift cable bracket and shift cable into position.
8. Install the three transfer case shift cable bracket mounting bolts. Tighten the bolts securely.
9. Connect the transfer case shift cable to the transfer case lever on the transfer case.
10. Lower the vehicle from the hoist.

**Figure 34 – Transfer Case Switch**

Completion Reporting and Reimbursement

Claims for vehicles that have been serviced must be submitted on the DealerCONNECT Claim Entry Screen located on the Service tab. Claims submitted will be used by FCA to record recall service completions and provide dealer payments.

Use one of the following labor operation numbers and time allowances:

	Labor Operation Number	Time Allowance
Replace ORC module (KJ models)	08-R0-61-82	0.9 hours
Replace ORC module (WJ models)	08-R0-61-83	0.5 hours
Replace ORC Module (ZB models)	08-R0-61-84	1.7 hours

Related Operation (KJ Only)

Replace 4x4 transfer case switch	08-R0-61-50	0.4 hours
Replace front impact sensors	08-R0-61-51	0.2 hours

Optional Equipment (WJ Only)

Replace side airbag sensors	08-R0-61-60	0.5 hours
-----------------------------	-------------	-----------

Add the cost of the recall parts package plus applicable dealer allowance to your claim.

NOTE: See the Warranty Administration Manual, Recall Claim Processing Section, for complete recall claim processing instructions.

Dealer Notification

To view this notification on DealerCONNECT, select “Global Recall System” on the Service tab, then click on the description of this notification.

Owner Notification and Service Scheduling

All involved vehicle owners known to FCA are being notified of the service requirement by first class mail. They are requested to schedule appointments for this service with their dealers. A generic copy of the owner letter is attached.

Enclosed with each owner letter is an Owner Notification postcard to allow owners to update our records if applicable.

Vehicle Lists, Global Recall System, VIP and Dealer Follow Up

All involved vehicles have been entered into the DealerCONNECT Global Recall System (GRS) and Vehicle Information Plus (VIP) for dealer inquiry as needed.

GRS provides involved dealers with an updated VIN list of their incomplete vehicles. The owner's name, address and phone number are listed if known. Completed vehicles are removed from GRS within several days of repair claim submission.

To use this system, click on the “**Service**” tab and then click on “**Global Recall System.**” Your dealer's VIN list for each recall displayed can be sorted by: those vehicles that were unsold at recall launch, those with a phone number, city, zip code, or VIN sequence.

Dealers must perform this repair on all unsold vehicles before retail delivery. Dealers should also use the VIN list to follow up with all owners to schedule appointments for this repair.

Recall VIN lists may contain confidential, restricted owner name and address information that was obtained from the Department of Motor Vehicles of various states. Use of this information is permitted for this recall only and is strictly prohibited from all other use.

Additional Information

If you have any questions or need assistance in completing this action, please contact your Service and Parts District Manager.

Customer Services / Field Operations
FCA US LLC

IMPORTANT SAFETY RECALL

R06 / NHTSA 15V-046

This notice applies to your vehicle (VIN: xxxxxxxxxxxxxxxxx).

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Dear: (Name)

FCA US LLC has decided that a defect, which relates to motor vehicle safety, exists in certain **2002 and 2003 model year Jeep Liberty models; 2002 through 2004 model year Jeep Grand Cherokee models; and 2003 and 2004 model year Dodge Viper models.**

The problem is... **The airbag system Occupant Restraint Control (ORC) module on your vehicle may experience a front airbag and/or seatbelt pretensioner inadvertent deployment. An inadvertent deployment while driving could distract the driver and cause a crash without warning.**

What your dealer will do... **FCA will repair your vehicle free of charge.** To do this, your dealer will replace the Occupant Restraint Control module. The work will take about two hours to complete. However, additional time may be necessary depending on service schedules.

What you must do to ensure your safety... Simply **contact your Chrysler, Jeep, Dodge or RAM dealer** right away to schedule a service appointment. **Please bring this letter with you to your dealer.**

If you need help... If you have questions or concerns which your dealer is unable to resolve, please contact the FCA Group Recall Assistance Center at either **fcarecalls.com** or 1-800-853-1403.

Please help us update our records by filling out the attached prepaid postcard if any of the conditions listed on the card apply to you or your vehicle. If you have further questions go to **fcarecalls.com**.

If you have already experienced this specific condition and have paid to have it repaired, you may visit **www.fcarecallreimbursement.com** to submit your reimbursement request online or you can mail your original receipts and proof of payment to the following address for reimbursement consideration: **FCA Customer Assistance, P.O. Box 21-8004, Auburn Hills, MI 48321-8007, Attention: Recall Reimbursement.** Once we receive and verify the required documents, reimbursement will be sent to you within 60 days. If you've had previous repairs and/or reimbursement you may still need to have the recall repair performed on your vehicle.

If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, DC 20590, or you can call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to **safercar.gov**.

We're sorry for any inconvenience, but we are sincerely concerned about your safety. Thank you for your attention to this important matter.

Customer Services / Field Operations
FCA US LLC

Note to lessors receiving this recall: Federal regulation requires that you forward this recall notice to the lessee within 10 days.