

Page 1 of 6

SUBJECT:			No:	SR-15-003
-	NT BLOWER MOTO	-	DATE	June, 2015
SAFE	TY RECALL CAMP	AIGN	MODE	EL: See Below
CIRCULATE TO:	[X] GENERAL MANAGER	[X] PARTS MANAGER		[X] TECHNICIAN
[X] SERVICE ADVISOR	[X] SERVICE MANAGER	[X] WARRANTY PROCES	SOR	[X] SALES MANAGER

## PURPOSE

Due to a manufacturing error, the shaft and bearing inside the front blower motor on affected vehicles may have been improperly centered. If use continues under this condition, the shaft and bearing could ultimately seize resulting in total loss of blower performance.

This campaign bulletin instructs dealers to inspect the part number label on the front blower motor and replace it with a countermeasure unit if necessary.

## AFFECTED VEHICLES

Certain 2009 - 2011 Lancers built March 16, 2009 to March 30, 2011 Certain 2009 – 2011 Lancer Ralliarts built June 17, 2009 to December 1, 2010 Certain 2010 - 2011 Lancer Sportbacks built June 17, 2009 to December 1, 2010 Certain 2010 - 2011 Lancer Sportback Ralliarts built June 17, 2009 to November 23, 2010 Certain 2010 – 2011 Lancer Evolutions built July 14, 2009 to January 7, 2011 Certain 2009 - 2011 Outlanders built February 10, 2009 to June 22, 2011 Certain 2011 Outlander Sport/RVRs built August 26, 2010 to November 19, 2010

# IMPORTANT

Affected new or used inventory vehicles must be repaired before the vehicle is delivered. Dealers must check their inventory vehicles' VINs on the Warranty Super Screen to verify whether the vehicle is involved in this recall campaign. It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or noncompliance is remedied.

### CUSTOMER NOTIFICATION

A letter will be sent to all owners of affected vehicles telling them to contact their local Authorized Mitsubishi Motors dealer to have the front blower motor inspected and replaced if necessary. A copy of the customer notification letter appears at the end of this bulletin.

## **REQUIRED OPERATIONS**

Before starting this campaign procedure, CHECK THE WARRANTY SUPERSCREEN to verify if the vehicle is an affected VIN for this campaign and this campaign procedure has not already been completed.

Copyright 2015, Mitsubishi Motors North America, Inc.

Continued

The information contained in this bulletin is subject to change. For the latest version of this document, go to the Mitsubishi Dealer Link, MEDIC, or the Mitsubishi Service Information website (www.mitsubishitechinfo.com) (4293)

# **INSPECTION AND REPAIR PROCEDURE**

- 1. Turn the ignition switch to the "ON" position or press the engine start/stop switch twice until the LED indicator illuminates green.
- 2. Turn on the blower motor to the "MAX" position. Notate if the blower motor is able to achieve "MAX" performance.
- 3. Turn the vehicle "OFF."
- 4. Move the front passenger seat to the full rearward position and remove the front passenger side floor mat (if equipped).
- 5. Remove the passenger compartment bottom cover assembly (located below glove box).
- 6. With a flashlight, inspect the part number label on the blower motor.





- a. If the part number <u>is not CSA431D214 or</u> <u>CSA431D214A</u>, inspection is complete. <u>Re-</u> <u>placement is not required</u>. Reinstall the passenger compartment bottom cover assembly and front passenger floor mat (if removed) and return vehicle to customer.
- b. If the part number <u>is CSA431D214 or</u> <u>CSA431D214A</u>, proceed to the next step.
- 7. Replace the blower motor with the corresponding part indicated in the **Parts Information** section.

- 8. If noted in Step 2 that the blower motor is unable to achieve "MAX" performance, replace the power transistor.
- 9. Turn the ignition switch to the "ON" position or press the engine start/stop switch twice until the LED indicator illuminates green.
- 10. Turn on the blower motor to the "MAX" position. Confirm the blower motor is able to achieve "MAX" performance.
- 11. Reinstall the passenger compartment bottom cover assembly and front passenger side floor mat (if removed).

## PARTS INFORMATION

Use the genuine Mitsubishi Part listed below:

Description	Vehicle Applicability	Part Number	Qty
Blower Motor	2009–11 Lancer 2009–11 Lancer Ralliart 2010–11 Lancer Sportback with F.A.S.T–key 2010–11 Lancer Sportback Ralliart with F.A.S.T.–key 2009–11 Outlander with F.A.S.T–key	7802A217	1
Blower Motor with Noise Filter	2010–11 Lancer Sportback without F.A.S.T-key 2010–11 Lancer Sportback Rallliart without F.A.S.T-key 2010–11 Lancer Evolution 2009–11 Outlander without F.A.S.T-key 2011 Outlander Sport/RVR	7802A218	1
Power Transistor	All	7802A006	1*

\*If required

## WARRANTY INFORMATION

There are four possible Blower Motor repair scenarios. Review the scenario selection chart to choose the correct operation scenario. You may only claim 1 Scenario.

#	Check Blower Motor	Operation No.	Models
1	Check Blower Motor Label = OK	C1503T01	All Involved Models
2	Check Blower Motor Label = Not OK Replace Blower Motor	C1503T02	Outlander and Out- lander Sport
3	Check Blower Motor Label = Not OK Replace Blower Motor	C1503T03	Lancer, Lancer Sportback, Lancer Ralliart, Lancer Sportback Ralliart and Lancer Evolu- tion
4	Check Blower Motor – if found to be non–functional = Not OK Replace Blower Motor <u>and</u> Power Transistor	C1503T04	All Involved Models

### **Replaced Parts Retention**

Retain all replaced parts for at least 5 days beyond the date the claim appears as paid on your warranty claim statement.

#### WARRANTY / RECALL CAMPAIGN CLAIM INFORMATION

Enter all claims as claim type 'C' – Recall/Campaign Claims

Please follow the campaign instructions when entering each claim in order to select the operation code that correctly matches up with the work that was actually performed. A claim example is provided below.

Certain 2009–2011MY – Lancer, Lancer Sportback, Lancer Ralliart, Lancer Ralliart Sportback, Lancer Evolution, Outlander and Outlander Sport models

Claim Header Section: Blower Motor Inspection and Replacement if Necessary

			Service Warranty			Help		
		20	Enter in the first <b>6</b> characters of this campaign labor operation: <u>C1503T</u>		ampaign			
Clain	n Entry	Vehicle Inform	ation				/QR	
Campaig	n Inforr	nation						<u> </u>
Campaigr Operation No Miles/Km	-		nece Lanc art S	campaign is for ssary of the blo er, Lancer Spor portback, Lance er Sport models	wer moto tback, La er Evoluti	or on certain 2 ncer Ralliart,	2009–2011M Lancer Rall	Y
VIN Service	JA	Emp	each spec	k the "Open Re time to be certa ific VINs showir campaign.	ain of a v	ehicle's eligib	ility. Only	
Technicia	n j	•		Scivice A				
Spec Valu	e *				Duplic	ate Recall *		
Dealer:	99320	Ref No:			820	VIN:		
Claim No:	o: Adj:		Claim Status: Incomplete Model and Year:			·		

After entering the required customer data, vehicle information and applicable campaign labor operation number on the "Repair Performed" scenario that is selected from the menu, hitting the "<u>Save and Continue</u>" button will automatically fill–in several fields. Please note that only 1 repair scenario may be selected from the 4 available.

CAMPAIGN INFORMATION					C1503T01
					C1503T02
					C1503T03
Campaign Operation No	C1503T		Lancer, Lancer Sportback, Lancer Ralliart, Lancer	Repair Performed	С1503Т04
			Ralliart Sportback, Lancer Evolution and Outlander	Repair Order No	EX12345
Miles / KM	85,000				
VIN		Repair Date In	7 / 30 / 2015	Repair Date Out	7 / 31 / 2015

#### Campaign Claim Example:

Follow these instructions to claim for performing the inspection of the Blower Motor label and replacement if necessary.

#### PARTS:

Replacement is only necessary if the Blower Motor's label dictates and/or the Blower motor is no longer functioning. If a replacement is needed, only these part numbers are allowed to be claimed. No other parts are involved.

7802A217 = Front Blower Motor or 7802A218 = Front Blower Motor with noise filter

and

7802A006 = Power Transistor (only needed if blower motor no longer functions)

#### LABOR:

Follow the chart below to select the appropriate campaign labor operation and labor time that matches the repair that was actually performed. These operations will appear on the drop-down.

	Campaign Number: C1503T Blower Motor				
	Campaign Operations - Select from Claim Drop Down M	Labor Times by Model			
	Select the repair actually performed and the corresponding operation scenarios and times shown below. Check the repair order to be sure you are selecting the correct repair.				
	Repair Descriptions	Operation Scenarios	Outlander and Outlander Sport	Lancer, Lancer Sportback, Lancer Ralliart, Lancer Ralliart Sportback, Lancer Evolution.	
	Blower Motor Label Inspection - If Blower Motor is non-functional skip to #4 - C1503T04				
#1	Check Blower Motor Label = OK	C1503T01	.3 hrs	.3 hrs	
#2	Check Blower Motor Label = Not OK - Replace Blower Motor	С1503Т02	.3 hrs		
#3	Check Blower Motor Label = Not OK - Replace Blower Motor	С1503Т03		.4 hrs	
	Check Blower Motor Label - if found to be non-functional = Not OK Replace Blower Motor <u>and</u> Power Transistor	C1503T04	.4 hrs	.4 hrs	

#### OTHER CHARGES:

In rare cases, towing and/or a rental car may be necessary. The lower portion of the labor page has the fields that must be filled in if there are such charges.

Special Sublet Selection					
Select	Labor Operation	Labor Operation Description		Amount	
	SHO	SPECIAL HANDLING ORDER	SHO Parts Order		
	RENTACAR	RENTAL CAR CHARGES	Days Reason <select one=""> ← Rental Company Invoice Number</select>		
	95300040	FREIGHT CHARGES	Freight Company Invoice Number		
	95200040	TOWING CHARGES	Towing Company Invoice Number		



#### Mitsubishi Motors North America, Inc.

6400 Katella Avenue Cypress, CA 90630 Telephone: 714-372-6000 www.mitsubishicars.com

This notice applies to your vehicle, \_

This notice has been sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Date: June, 2015

Dear Mitsubishi Owner,

Reason for notice:	Mitsubishi Motors North America, Inc. (MMNA) has decided that a defect which relates to motor vehicle safety exists in certain 2009 - 2011 Lancer, 2010 – 2011 Lancer Sportback, 2010 - 2011 Lancer Evolution, 2009 – 2011 Outlander, and 2011 Outlander Sport vehicles. Due to a manufacturing error, the shaft and bearing inside the front blower motor may have been improperly centered, potentially causing premature wear and reduced blower performance. If use continues under this condition, the shaft and bearing could ultimately seize resulting in total loss of blower performance.
	If a driver experiences reduced or complete loss of blower performance and defrosting of the windshield is required, this may affect driver visibility and increase the risk of a crash. Prior to failure, the blower motor may emit an unusual noise from the passenger side compartment and blower performance will decrease.
What you should do:	Please contact your local Authorized Mitsubishi Motors dealer and schedule an appointment to have the recall remedy performed on your vehicle. When you bring your vehicle in, please show the dealer this letter. (If you misplace this letter, the dealer will still make this inspection/repair to your vehicle, free of charge.)
What your dealer will do:	The dealership will inspect the front blower motor and replace it if necessary.
How long will it take?	The time needed for this remedy is approximately <b>0.5</b> hr. The dealer may need your vehicle for a longer period of time due to service scheduling issues, but every effort will be made to minimize your inconvenience.

If you experience any problem having your vehicle repaired promptly and/or at no charge, please inform us by calling the Mitsubishi Customer Relations Department at 888-648-7820. Hours: Monday through Friday 7 a.m. to 4 p.m. (Pacific Time)

If, after contacting Mitsubishi Customer Relations, you still have a problem getting this repair made promptly and/or without charge, write to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE, Washington, D.C. 20590, or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153), or go to http://www.safercar.gov.

If you have already encountered a problem with the front blower motor and had it replaced as a result of this specific condition and have paid for the repair, you may send your original repair order or invoice, and original receipt/proof of payment to the following address for reimbursement consideration:

Mitsubishi Customer Relations Department, P.O. Box 6400, Cypress, CA 90630-0064

If you are the lessor of this vehicle, please forward a copy of this notice to the lessee within ten days to comply with federal regulations.

We appreciate your prompt attention to this matter.

Sincerely,

Mitsubishi Motors North America, Inc.

C1503T