

Service Information

Page 1 of 3 July 2015 Technical Service

Body Equipment

M51 03 15

This Service Information bulletin supersedes SI M51 03 15 dated July 2015.

Changes to this revision are identified by a black bar.

<u>SUBJECT</u>

Recall Campaign 15V-450: Side Impact Performance

MODEL

F56 (Cooper S, JCW Hardtop 2 Door)

Produced from December 2013 to March 2015

SITUATION

A Recall Campaign has been issued on certain F56 Cooper S and JCW models.

The vehicle's side structure is designed to help absorb energy in the event of a side collision. Due to vehicle build variation, some of the vehicles may marginally exceed a NHTSA test requirement. MINI is performing a voluntary upgrade to these vehicles. Additional energy-absorbing material between the rear interior side panels and the vehicle structure will be added to help enhance occupant protection in the event of a side collision.

AFFECTED VEHICLES

This Recall Campaign involves F56 (Cooper S, JCW Hardtop 2 Door) models produced from December 2013 to March 2015.

Vehicles which require this Recall Campaign to be completed will show it as "Open" when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System) or with the Key Reader.

Customers will be notified of this Recall via US First Class Mail when a sufficient supply of parts is available.

CORRECTION



Install a molded structural foam pad to both the left and right rear side trim panels.

The pad is applied to the inside surface of the panel, and is not visible either from inside the vehicle nor from the outside.

The general location is indicated on this passenger side panel by the dotted line.

<u>PROCEDURE</u>

Refer to Attachment 1, Repair Instruction 51 43 002, "Removing and installing (replacing) the rear left or right side trim panel."

Necessary preliminary tasks:

- Remove trim panel for door post (B-pillar)
- Remove trim panel for roof pillar at rear (C-pillar)
- Remove load bar
- Remove luggage compartment floor trim panel

Refer to Attachment 2 to modify the side panels and install the structural foam pads.

PARTS INFORMATION

Part Number	Description	Quantity
51 43 7 436 519	Left structural foam pad	1
51 43 7 436 520	Right structural foam pad	1

Sublet - Bulk Material

Part Number	Description	Quantity
83 19 2 409 987	BMW Group Weld Hot Melt Adhesive 3731 Q (Qty 1 = 15 adhesive sticks, sufficient for 15 vehicles)	As needed

Sublet - One-Time Claimable Item

Part Number	Description	Quantity
83 19 2 409 988	BMW Group Weld Hot Melt Applicator	1 (one time only)
	TC (Tool)	

WARRANTY INFORMATION

Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop.

Reimbursement for this Recall Campaign will be via normal claim entry utilizing the following information:

Defect Code:	00 51 70 03 00

Before vehicle delivery to the customer or the vehicle is already in the workshop

Labor Operation:	Labor Allowance:	Description:
00 62 635	20 FRU	Retrofit the structural molded foam pads to both the
		left and right rear side trim panels (Plus work)

And:

Sublet – Bulk Materials: Adhesive Sticks

Sublet Code 4	See sublet reimbursement calculation below	Reimbursement for the used quantity of BMW Group Weld Hot Melt Adhesive 3731 Q (Adhesive sticks – Bulk P/N 83 19 2 409 987: Qty 1 = 15 adhesive
		sticks).

Sublet calculation: Reimbursement for used quantities of Weld Hot Melt Adhesive 3731 Q sticks (bulk P/N 83 19 2 409 987: Qty 1 = 15 adhesive sticks) at dealer net plus handling.

Enter this material cost in sublet and itemize the amount in the claim comment section.

And:

Sublet – One-Time Claimable Item: Applicator Tool

Sublet Code 4 See sublet reimbursement calculation below	Reimbursement for one (1) BMW Group Weld Hot Melt Applicator TC (Tool P/N 83 19 2 409 988).
--	--

Sublet reimbursement calculation for one (1) BMW Group Weld Hot Melt Applicator TC (Tool P/N 83 19 2 409 988) at cost, **no handling.**

Enter this material cost in sublet one time and itemize the amount in the claim comment section.

Refer to the Attachments:

1. ISTA repair

2. L pad repair

3. Legal notice

4. Q&A