



RECALL CAMPAIGN BULLETIN

Reference:

NTB15-105

Date:

November 19, 2015

VOLUNTARY SAFETY RECALL CAMPAIGN 2016 MAXIMA AND 2015 ALTIMA; FRONT CALIPER TORQUE MEMBER BOLTS

CAMPAIGN ID #: PC412

APPLIED VEHICLES: 2016 Maxima (A36)
2015 Altima (L33)

Check Service COMM to confirm campaign eligibility.

INTRODUCTION

Nissan is conducting a Voluntary Safety Recall Campaign on certain specific Model Year 2016 Maxima and 2015 Altima vehicles to re-torque the front torque member bolts. The total population of vehicles covered by this campaign is approximately 112. This service will be performed at no charge for parts or labor.

IDENTIFICATION NUMBER

Nissan has assigned identification number PC412 to this campaign. This number must appear on all communications and documentation of any nature dealing with this campaign.

DEALER RESPONSIBILITY

It is the dealer's responsibility to check Service Comm for the campaign status on each vehicle falling within the range of this voluntary safety recall which for any reason enters the service department. This includes vehicles purchased from private parties or presented by transient (tourist) owners and vehicles in a dealer's inventory. **Federal law requires that new vehicles in dealer inventory which are the subject of a safety recall must be corrected prior to sale. Failure to do so can result in civil penalties by the National Highway Traffic Safety Administration.** While federal law applies only to new vehicles, Nissan strongly encourages dealers to correct any used vehicles in their inventory before they are retailed.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

SERVICE PROCEDURE

1. Lift the vehicle.
2. Locate and re-torque both torque member bolts on each front wheel hub assembly (see Figure 1).
 - Figure 1 shows the Driver side; the passenger side is a mirror image.
 - Turning the wheel to the left (for the left side), or to the right (for the right side), will give better access to the torque member bolts.
 - Torque to 144.5 N·m (15 kg-m, 107 ft-lb).

NOTE:

- Make sure to perform the above torque procedure on BOTH (driver and passenger side) front torque members.
- If a bolt is found missing, replace it with a new bolt and washer.




Figure 1

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY
Bolt	41044-6P01B	If needed
Washer	08044-4501A	If needed

NOTE

- The above bolt and washer are needed ONLY if they are missing.
- The total population of vehicles covered by this campaign is approximately 112. It is expected that no bolts or washers will be found missing.

CLAIMS INFORMATION

Submit a Campaign (CM) line claim using the following claims coding:

CAMPAIGN (CM) ID #	DESCRIPTION	OP CODE	FRT
PC412	Torque left and right front torque member bolts; replace bolt if missing	PC4120	0.2 hrs.