OMB Control No.: 2127-0004

Part 573 Safety Recall Report

16E-039

Manufacturer Name: Chrysler (FCA US LLC)

NHTSA Recall No.: 16E-039

Manufacturer Recall No.: S29



Manufacturer Information:

Manufacturer Name: Chrysler (FCA US LLC)

Address: 800 Chrysler Drive

CIMS 482-00-91 Auburn Hills MI

48326-2757

Company phone: 1-800-853-1403

Population:

Number of potentially involved : 2,291 Estimated percentage with defect : 100%

Equipment Information:

Brand / Trade 1: RAM

Model: ProMaster Part No.: 68229650AB

Size: N/A

Function: Trlr Light Mod

Descriptive Information: This is an equipment recall. Some 2014-2016 MY RAM ProMaster ("VF") vehicles

may have received the Trailer Tow Lighting Control Module (Part Number

68229650AB).

Production Dates: JUL 24, 2015 - FEB 15, 2016

Brand / Trade 2: RAM

Model: ProMaster City Part No.: 68229650AB

Size: N/A

Function: Trlr Light Mod

Descriptive Information: This is an equipment recall. Some 2015-2016 MY RAM ProMaster City ("VM")

vehicles may have received the Trailer Tow Lighting Control Module (Part

Number 68229650AB).

Production Dates: AUG 15, 2014 - FEB 01, 2016

Description of Defect:

Description of the Defect: Per FMVSS 571.108, stop lamps are required on the rear of all trailers with

steady burning activated upon application of the service brakes. The Trailer Tow Lighting Control Module may contain a software error that could cause a

The information contained in this report was submitted pursuant to 49 CFR §573

noncompliance with FMVSS 571.108. The software error may result in a processing issue preventing the illumination of the trailer brake lights after first actuation of the brake.

FMVSS 1: 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2: NR

Description of the Safety Risk: This condition may result in inoperative trailer brake lights.

Description of the Cause: NR Identification of Any Warning NR that can Occur:

Supplier Identification:

Component Manufacturer

Name: NR Address: NR

NR

Country: NR

Chronology:

FCA US' investigation found the VM brake signal was modified from Direct Current ("DC") to Pulse Width Modulation ("PWM") at the start of production for the 2015 MY. A read across to the VF was initiated based on the common use of the Trailer Tow Lighting Control Module. The Mopar Upfit Center at Saltillo Van Assembly Plant ("SVAP") found brake lights for the Mopar Trailer Tow Group kit were not functioning after the first brake actuation. Software level change history of the trailer tow lamp module indicated that changes made to implement best practices to minimize battery drain resulted in altering the PWM detection rate. This change resulted in a processing issue that may not illuminate the trailer tow brake lights on VF vehicles after the first actuation of the brake. The 2015 start of production change from DC to PWM signals on the VM vehicle resulted in a processing issue that may not illuminate the trailer tow brake lights.

Description of Remedy:

Description of Remedy Program: FCA US will conduct a Voluntary Safety Recall to replace the Trailer Tow Light Control Module. An equipment recall notice will be mailed to all other VF and VM vehicle owners who may have purchased a suspect Mopar Trailer Tow Group kit.

> FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or

other adequate proof of payment to the company for confirmation of the

expense.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule : $**2016\ 06\ 09$ - 2016 06 16 Dealer Instruction and 2016 06 20 Owner

Letter.

FCA US will provide a dealer notification and owner notification schedule

once established.

Planned Dealer Notification Date: NR - NR

Planned Owner Notification Date: NR - NR

Purchaser Information:

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name: NR

Address: NR

NR

Country: NR

Country. NK

Company Phone: NR

^{*} NR - Not Reported