

Part 573 Safety Recall Report**16V-002**

Manufacturer Name : HME, Inc.
Submission Date : JAN 04, 2016
NHTSA Recall No. : 16V-002
Manufacturer Recall No. : NR

**Manufacturer Information :**

Manufacturer Name : HME, Inc.
 Address : 1950 Byron Center Ave.
 Wyoming MI 49519
 Company phone : 616-534-1463

Population :

Number of potentially involved : 1
 Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2015-2015 HME Inc. SFO
 Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES
 Body Style : 4-DOOR
 Power Train : DIESEL
 Descriptive Information : Fire Service Chassis
 Production Dates : JUL 31, 2015 - JUL 31, 2015

VIN (Vehicle Identification Number) Range

Begin : 44KFT4484FWZ22778

End : 44KFT4484FWZ22778

 Not sequential VINs**Description of Defect :**

Description of the Defect : Hex nuts on the flange yoke may not have been properly tightened.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the nuts are not tightened to specification, the driveshaft may disconnect from the drive axle resulting in a loss of propulsion and increasing the risk of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Marmon-Herrington

Address : 13001 Magisterial Drive
Louisville KENTUCKY 40223

Country : United States

Chronology :

NR

Description of Remedy :

Description of Remedy Program : Standard Repair Time is 0.25 hours for checking torque and tightening Bolts

How Remedy Component Differs from Recalled Component : None

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported