OMB Control No.: 2127-0004

Part 573 Safety Recall Report

16V-075

Manufacturer Name: Toyota Motor Engineering & Manufacturing

Submission Date : FEB 09, 2016 **NHTSA Recall No. :** 16V-075 **Manufacturer Recall No. :** G0E



Manufacturer Information:

Manufacturer Name: Toyota Motor Engineering & Manufact

Address: 19001 South Western Avenue

Torrance CA 90501 Company phone : 13104681946

Population:

Number of potentially involved: 25,706 Estimated percentage with defect: 0

Vehicle Information:

Vehicle: 2013-2016 Toyota Scion FR-S

Vehicle Type : Body Style :

Power Train: NR

Descriptive Information: (1) Although the involved vehicles are within the above Production Period

range, not all vehicles in this range were sold in the U.S.

(2) Only the vehicles of Scion FR-S equipped with an automatic transmission

and ignition key but not an ignition button are involved in this recall.

(3) Other Toyota and Lexus vehicles are not equipped with the unique delivery mode connectors. Therefore, other Toyota and Lexus vehicles are not included in

this recall.

Production Dates: MAR 13, 2012 - JAN 14, 2016

VIN (Vehicle Identification Number) Range

Description of Noncompliance:

Description of the Noncompliance: The subject vehicles are equipped with an automatic transmission key

interlock system to prevent ignition key removal unless the gear selection control is in "Park". In order to prevent automatic transmission damage during rail transport, the key interlock is disabled by leaving the delivery mode connectors unconnected at the assembly plant. The connectors on some vehicles may not have been connected during pre-delivery service at dealers or distributors. If not connected, the ignition key can be removed in gear selection controls other than "Park". Therefore the requirements of S5.2 of FMVSS 114 are not met, and there is an increased risk of vehicle rollaway and a crash.

FMVSS 1:114 - Theft protection

FMVSS 2:NR

Description of the Safety Risk: If not connected, the ignition key can be removed in gear selection controls

other than "Park". Therefore the requirements of S5.2 of FMVSS 114 are not

met, and there is an increased risk of vehicle rollaway and a crash.

Description of the Cause: NR

Identification of Any Warning that can Occur: NR

Supplier Identification:

Component Manufacturer

Name : NR Address : NR

NR

Country: NR

Chronology:

Toyota received field reports indicating that the ignition key may be removed in the "Drive" gear position. Toyota inspected the vehicles and found the delivery mode wire harness connectors were apparently not connected during pre-delivery service (PDS) as specified by Toyota. Toyota investigated and found that not all port facilities or dealer technicians, who were conducting the PDS, understood or were following the specified procedure. On February 2, 2016, Toyota determined that some vehicles in the field may not meet the requirements of S5.2 FMVSS 114.

Description of Remedy:

Description of Remedy Program: All known owners of the subject vehicles will be notified by first class mail to

return their vehicles to a Toyota dealer to have the delivery mode

connectors inspected and, if necessary, connected at no charge. The owner letter will instruct vehicle owners who have paid to have this condition remedied prior to this campaign to seek reimbursement pursuant to

Toyota's General Reimbursement Plan.

How Remedy Component Differs from Recalled Component: NR

Identify How/When Recall Condition was Corrected in Production: NR

Recall Schedule:

Description of Recall Schedule: Mailing of owner notifications will begin in early March, 2016. A draft of the

owner notification letter will be submitted as soon as it is available.

Notification to distributors/dealers will be sent on February 9, 2016. Copies

of the dealer communications will be submitted as they are issued.

Planned Dealer Notification Date: FEB 09, 2016 - FEB 09, 2016

Planned Owner Notification Date: MAR 01, 2016 - APR 09, 2016

Part 573 Safety Recall Report	16V-075	Page 3
* NR - Not Reported		
•		
The information contained in this report	t was submitted pursuant to 49 CFR §573	