

Part 573 Safety Recall Report**16V-109****Manufacturer Name :** Honda (American Honda Motor Co.)**Submission Date :** MAR 09, 2016**NHTSA Recall No. :** 16V-109**Manufacturer Recall No. :** JY3**Manufacturer Information :**

Manufacturer Name : Honda (American Honda Motor Co.)

Address : 1919 Torrance Blvd.

Torrance CA 90501

Company phone : 1-800-999-1009

Population :

Number of potentially involved : 1,984

Estimated percentage with defect : NR

Vehicle Information :

Vehicle : 2014-2014 Honda NSS300

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records. The VIN range reflects all possible vehicles that could potentially experience the problem.

Production Dates : JUN 18, 2013 - SEP 12, 2013

VIN (Vehicle Identification Number) Range

Begin : MLHNF0403E5000001

End : MLHNF0404E5001786

 Not sequential VINs

Vehicle : 2014-2014 Honda NSS300A

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records. The VIN range reflects all possible vehicles that could potentially experience the problem.

Production Dates : JUN 19, 2013 - SEP 12, 2013

VIN (Vehicle Identification Number) Range

Begin : MLHNF0412E5000001

End : MLHNF0413E5000198

 Not sequential VINs**Description of Defect :**

Description of the Defect : During assembly of the rear brake line, the rear brake line joint may have been improperly torqued. If the rear brake line joint is improperly torqued, brake fluid may leak from the loose connection causing a reduction or loss of rear brake pressure.

FMVSS 1 :NR
FMVSS 2 :NR
Description of the Safety Risk : A reduction or loss of rear brake pressure increases the risk of a crash.
Description of the Cause : NR
Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : NR
Address : NR
NR
Country : NR

Chronology :

See document titled "Chronology NSS300 Rear Brake Line Torque.pdf".

Description of Remedy :

Description of Remedy Program : The owners of all affected vehicles will be contacted by mail and asked to take their scooter to a Honda motorcycle dealer. The dealer will torque the rear brake line joint to specification and, if necessary, fill the rear brake reservoir, free of charge.

How Remedy Component Differs from Recalled Component : NR
Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : FEB 19, 2016 - FEB 19, 2016

Planned Owner Notification Date : MAR 21, 2016 - MAR 21, 2016

* NR - Not Reported