

**Part 573 Safety Recall Report****16V-137****Manufacturer Name :** Jaguar Land Rover North America, LLC**Submission Date :** MAR 03, 2016**NHTSA Recall No. :** 16V-137**Manufacturer Recall No. :** J061**Manufacturer Information :**

Manufacturer Name : Jaguar Land Rover North America, LLC

Address : 555 MACARTHUR BOLULEVARD  
MAHWAH NJ 07430

Company phone : 201-760-8534

**Population :**

Number of potentially involved : 6,938

Estimated percentage with defect : 100

**Vehicle Information :**

Vehicle : 2013-2015 Jaguar XF

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : 2013-2015 MY Jaguar XF Vehicles in select VIN range

Production Dates : MAY 16, 2012 - JUN 15, 2015

**VIN (Vehicle Identification Number) Range**

Begin : SAJWA0ES3DPS51675

End : SAJWA0FS7FPU88784

 Not sequential VINs**Description of Noncompliance :**

Description of the Noncompliance : Jaguar Land Rover has identified a concern with certain Jaguar XF 2013 to 2015 Model Year 2.0L GTDi engine vehicles where a bolt retaining a Front End Auxiliary Drive (FEAD) idler pulley may fail leading to a loss of FEAD drive. As a result, the driver may experience battery charge warning lamp illumination, air conditioning failure and engine overheat warnings through coolant pump loss of drive. They may also notice a Malfunction Indicator Light (MIL) on the Instrument Cluster followed by a reduction in steering assistance; however vehicle steering will remain functional with increased steering effort required.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the driver experiences a sudden increase in steering effort they may not be able to react to a maneuver as quickly as required. This could increase the risk of a vehicle crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : Dayco Europe S.r.l.

Address : Phoenix House

Christopher Martin Road Basildon, Essex FOREIGN STATES SS14 3EZ

Country : United Kingdom

**Chronology :**

See Document "JLR J061 Chronology".

**Description of Remedy :**

Description of Remedy Program : Owners will be notified and instructed to take their vehicle to a Jaguar dealer who will replace the FEAD pulley assembly with the latest design FEAD pulley assembly and fixing. There will be no charge to owners for this repair.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : Mailing of owner notification letters will occur on or before May 2, 2016.  
Notifications to dealers will occur on March 8, 2016.

Planned Dealer Notification Date : MAR 08, 2016 - MAR 08, 2016

Planned Owner Notification Date : MAY 02, 2016 - MAY 02, 2016

\* NR - Not Reported