OMB Control No.: 2127-0004

Part 573 Safety Recall Report

16V-209

Manufacturer Name: General Motors LLC

Submission Date : APR 11, 2016 **NHTSA Recall No. :** 16V-209 **Manufacturer Recall No. :** 15822



Manufacturer Information:

Manufacturer Name: General Motors LLC

Address: 30001 VAN DYKE

MAIL CODE 480-210-2V WARREN MI 48090

Company phone: 5961733

Population:

Number of potentially involved: 895,232 Estimated percentage with defect: 100

Vehicle Information:

Vehicle: 2014-2014 Chevrolet Silverado 1500

Vehicle Type : Body Style :

Power Train: NR

Descriptive Information: Certain 2014 Chevrolet Silverado light duty trucks

Production Dates : JAN 29, 2013 - SEP 04, 2014

VIN (Vehicle Identification Number) Range

 $\begin: NR \\ \begin : NR \\ \$

Vehicle: 2015-2015 GMC Sierra 1500

Vehicle Type : Body Style : Power Train : NR

Descriptive Information: Certain 2015 GMC Sierra light duty trucks

Production Dates : APR 21, 2014 - JAN 21, 2015

VIN (Vehicle Identification Number) Range

Vehicle: 2015-2015 Chevrolet Silverado 1500

Vehicle Type : Body Style : Power Train : NR

Descriptive Information: Certain 2015 Chevrolet Silverado light duty trucks

Production Dates: APR 21, 2014 - JAN 21, 2015

Chronology:

See Attached

Description of Remedy Program: For used and customer vehicles, dealers will enlarge the side shield opening,

install a pusher bracket on the tensioner, and if necessary, replace the tensioner assembly. For unsold new vehicles, dealers will replace the retractor assembly. Pursuant to 49 C.F.R. § 573.13(d)(1), all covered vehicles are under warranty so reimbursement is not applicable.

How Remedy Component Differs from Recalled Component: On used and customer vehicles, the added pusher

bracket and the larger side shield opening will reposition the tensioner out of the path of the occupant while entering the vehicle. On new unsold vehicles, the replacement retractor rewind spring is more fully capable of retracting the seat belt and pulling the tensioner out of the driver's entry path.

Identify How/When Recall Condition was Corrected in Production : The front outboard seat belt retractor

rewind spring was changed on vehicles built after January 21, 2015. This change made the spring more capable of fully retracting the seat belt and pulling the tensioner cable out of the driver's entry path.

Recall Schedule:

Description of Recall Schedule: General Motors will provide dealer bulletin and owner letter notification dates

when available.

Planned Dealer Notification Date: APR 11, 2016 - APR 11, 2016

Planned Owner Notification Date: NR - NR

* NR - Not Reported