

Part 573 Safety Recall Report

16V-238

Manufacturer Name : Winnebago Industries, Inc

Submission Date : MAY 16, 2016

NHTSA Recall No. : 16V-238

Manufacturer Recall No. : FL-704



Manufacturer Information :

Manufacturer Name : Winnebago Industries, Inc

Address : PO BOX 152
605 W. Crystal Lake Rd. Forest City IA
50436

Company phone : 1-641-585-3535

Population :

Number of potentially involved : 56

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2014-2014 Winnebago Tour

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Daimler recall FL-704 / NHTSA 16V-204 Brake Activation Signal

Production Dates : MAY 23, 2013 - AUG 09, 2013

VIN Range 1 : Begin : NR **End :** NR Not sequential

Vehicle 2 : 2014-2014 Itasca Ellipse

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Daimler Recall FL-704 (NHTSA 16V-204) Brake Activation Signal

Production Dates : MAY 23, 2013 - AUG 09, 2013

VIN Range 1 : Begin : NR **End :** NR Not sequential

Description of Defect :

Description of the Defect : The brake activation signal to certain towed devices may not deactivate when the motorhome service brakes are released.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the brake activation signal to a towed device remains active when the motor home brakes are released, the brakes on a towed device may remain engaged.

Description of the Cause : NR

Identification of Any Warning NR
that can Occur :

Supplier Identification :

Component Manufacturer

Name : NR
Address : NR
NR
Country : NR

Chronology :

April 21, 2016 - received e-mail from Daimler

Description of Remedy :

Description of Remedy Program : Daimler will add a torsion spring the affected assembly. Repairs will be performed by Daimler Trucks North America authorized service facilities. Winnebago will assist Daimler by providing them with the currant names and address of where the affected VINs are located.

How Remedy Component Differs from Recalled Component : A torsion new spring will be added to the to the pedal assembly

Identify How/When Recall Condition NR
was Corrected in Production :

Recall Schedule :

Description of Recall Schedule : Daimler will notify affected owners via customer notification letter
Planned Dealer Notification Date : JUN 07, 2016 - JUN 07, 2016
Planned Owner Notification Date : JUN 07, 2016 - JUN 07, 2016

* NR - Not Reported