OMB Control No.: 2127-0004

Part 573 Safety Recall Report

16V-248

Manufacturer Name: Ford Motor Company

Submission Date: SEP 01, 2016 NHTSA Recall No.: 16V-248 Manufacturer Recall No.: 16S19



Manufacturer Information:

Manufacturer Name: Ford Motor Company

Address: 330 Town Center Drive

Suite 500 Dearborn MI 48126-2738

Company phone: 1-866-436-7332

Population:

Number of potentially involved: 153,581 Estimated percentage with defect: NR

Vehicle Information:

Vehicle 1: 2011-2012 Ford F-150

Vehicle Type: LIGHT VEHICLES Body Style: PICKUP TRUCK

Power Train: GAS

Descriptive Information: Affected vehicles are equipped with a 6R80 automatic transmission.

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service

Information System (OASIS) database.

Production Dates: FEB 11, 2011 - JAN 31, 2013

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 2: 2012-2012 Ford Expedition

Vehicle Type: LIGHT VEHICLES

Body Style: SUV Power Train: GAS

Descriptive Information: Affected vehicles are equipped with a 6R80 automatic transmission.

Production Dates: AUG 26, 2011 - SEP 10, 2012

Vehicle 3: 2012-2012 Lincoln Navigator

Vehicle Type: LIGHT VEHICLES

Body Style : SUV Power Train : GAS

Descriptive Information: Affected vehicles are equipped with a 6R80 automatic transmission.

Production Dates: AUG 26, 2011 - FEB 29, 2012

 Vehicle 4: 2012-2012 Ford Mustang

Vehicle Type: LIGHT VEHICLES

Body Style: ALL Power Train: GAS

Descriptive Information: Affected vehicles are equipped with a 6R80 automatic transmission.

Production Dates: AUG 09, 2011 - JUN 11, 2012

Description of Defect:

Description of the Defect: Some vehicles may experience an intermittent loss of the Transmission Output

Speed Sensor (OSS) signal to the Powertrain Control Module, potentially resulting in a temporary, unintended downshift into first gear. In some cases, the OSS signal could recover while driving and the vehicle will resume normal function; in other cases the vehicle may need to be stopped and restarted to

regain normal transmission operation.

Ford is aware of three reports of accidents and no injuries related to this

condition on the affected vehicles.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Depending on vehicle speed at the time of the downshift, an unintended

downshift into first gear may occur causing the rear tires to slide or lock up until the vehicle slows. This may result in a loss of vehicle control without

warning, increasing the risk of a crash.

Description of the Cause: NR Identification of Any Warning NR

that can Occur:

Supplier Identification:

Component Manufacturer

Name: Continental Automotive Systems Address: Luis Bleriot 6720 Parque IND

Juarez FOREIGN STATES 32695

Country: Mexico

Chronology:

see attached

Description of Remedy:

Description of Remedy Program: Owners will be notified by mail and instructed to take their vehicle to a

Ford or Lincoln dealer to have the Powertrain Control Module

reprogrammed with updated software. There will be no charge for this

service.

Ford is excluding reimbursement for costs because the original warranty

program would provide for a free repair for this concern.

Ford will forward a copy of the notification letters to dealers to the agency

when available.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: Notification to dealers is expected to occur on April 26, 2016. Mailing of

owner notification letters is expected to begin May 23, 2016 and is

expected to be completed by May 27, 2016.

Planned Dealer Notification Date: APR 26, 2016 - APR 26, 2016

Planned Owner Notification Date: MAY 23, 2016 - MAY 27, 2016

^{*} NR - Not Reported