

Part 573 Safety Recall Report**16V-270****Manufacturer Name :** Newmar Corporation**Submission Date :** MAY 03, 2016**NHTSA Recall No. :** 16V-270**Manufacturer Recall No. :** 16V 208**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Population :

Number of potentially involved : 59

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2015-2016 Newmar Ventana

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain Freightliner brand motorhome chassis, the front sway bar mounting bracket may not fit flush on the axle mounting surface and cause the mounting bolts to bend or become loose. Loose sway bar mounting bolts could potentially result in a detached sway bar. A detached sway bar on a motorhome may result in higher than expected vehicle sway or reduced handling potentially increasing the risk of a crash. Correction: The sway bar mounting will be modified on affected vehicles.

Production Dates : MAR 27, 2015 - FEB 08, 2016

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2015-2016 Newmar Ventana LE

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain Freightliner brand motorhome chassis, the front sway bar mounting bracket may not fit flush on the axle mounting surface and cause the mounting bolts to bend or become loose. Loose sway bar mounting bolts could potentially result in a detached sway bar. A detached sway bar on a motorhome may result in higher than expected vehicle sway or reduced handling potentially increasing the risk of a crash. Correction: The sway bar mounting will be modified on affected

vehicles.

Production Dates : MAR 27, 2015 - FEB 08, 2016

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Description of Defect :

Description of the Defect : On certain Freightliner brand motorhome chassis, the front sway bar mounting bracket may not fit flush on the axle mounting surface and cause the mounting bolts to bend or become loose. Loose sway bar mounting bolts could potentially result in a detached sway bar. A detached sway bar on a motorhome may result in higher than expected vehicle sway or reduced handling potentially increasing the risk of a crash. Correction: The sway bar mounting will be modified on affected vehicles.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Loose sway bar mounting bolts could potentially result in a detached sway bar. A detached sway bar on a motorhome may result in higher than expected vehicle sway or reduced handling potentially increasing the risk of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

On Tuesday, May 03, 2016; Newmar Corporation was made aware of a potential equipment defect relating to motor vehicle safety that may exist in the listed vehicles.

05/03/2016 Newmar sent notice of defect to NHTSA.

Description of Remedy :

Description of Remedy Program : The sway bar mounting will be modified on affected vehicles. Repairs will be performed by Daimler Trucks North America authorized service facilities at no cost to the customer.

How Remedy Component Differs from Recalled Component : NR
Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : JUL 02, 2016 - JUL 02, 2016

Planned Owner Notification Date : JUL 02, 2016 - JUL 02, 2016

* NR - Not Reported