

Part 573 Safety Recall Report**16V-280****Manufacturer Name :** Newmar Corporation**Submission Date :** MAY 09, 2016**NHTSA Recall No. :** 16V-280**Manufacturer Recall No. :** 16V-121**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Population :

Number of potentially involved : 93

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2014-2015 Newmar Essex

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes built on Freightliner chassis, the power steering fluid temperature may exceed the hose material rating on certain rear engine chassis built with certain 18k and 20k front axles used in motorhomes applications. The failure mode on these systems may result in loss of power steering during low-speed driving conditions. Sudden loss of steering assist on this vehicle without warning could lead to a vehicle crash. Correction: The suspect hose will be replaced with a hose with a higher temperature rating, this will be done at no cost to the customer.

Production Dates : MAY 20, 2013 - APR 09, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2015-2015 Newmar Mountain Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes built on Freightliner chassis, the power steering fluid temperature may exceed the hose material rating on certain rear engine chassis built with certain 18k and 20k front axles used in motorhomes applications. The failure mode on these systems may result in loss of power steering during low-speed driving conditions. Sudden loss of steering assist on this vehicle without warning could lead to a vehicle crash. Correction: The suspect hose will be replaced

with a hose with a higher temperature rating, this will be done at no cost to the customer.

Production Dates : MAY 20, 2013 - APR 09, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Vehicle : 2015-2015 Newmar London Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes built on Freightliner chassis, the power steering fluid temperature may exceed the hose material rating on certain rear engine chassis built with certain 18k and 20k front axles used in motorhomes applications. The failure mode on these systems may result in loss of power steering during low-speed driving conditions. Sudden loss of steering assist on this vehicle without warning could lead to a vehicle crash. Correction: The suspect hose will be replaced with a hose with a higher temperature rating, this will be done at no cost to the customer.

Production Dates : MAY 20, 2013 - APR 09, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Description of Defect :

Description of the Defect : On certain motorhomes built on Freightliner chassis, the power steering fluid temperature may exceed the hose material rating on certain rear engine chassis built with certain 18k and 20k front axles used in motorhomes applications. The failure mode on these systems may result in loss of power steering during low-speed driving conditions. Sudden loss of steering assist on this vehicle without warning could lead to a vehicle crash. Correction: The suspect hose will be replaced with a hose with a higher temperature rating, this will be done at no cost to the customer.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The failure mode on these systems may result in loss of power steering during low-speed driving conditions. Sudden loss of steering assist on this vehicle without warning could lead to a vehicle crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

On May 4, 2016, Newmar Corporation was notified by Daimler Trucks North America giving notice of a potential defect.

Description of Remedy :

Description of Remedy Program : The suspect hose will be replaced with a hose with a higher temperature rating, this will be done at no cost to the customer.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : JUL 03, 2016 - JUL 03, 2016

Planned Owner Notification Date : JUL 03, 2016 - JUL 03, 2016

* NR - Not Reported