#### OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

## 16V-364

**Manufacturer Name:** BMW of North America, LLC

Submission Date: JUN 23, 2016 NHTSA Recall No.: 16V-364 Manufacturer Recall No.: NR



#### **Manufacturer Information:**

Manufacturer Name: BMW of North America, LLC

Address: P.O. Box 1227

Westwood NJ 07675-1227

Company phone: 18005257417

## **Population:**

Number of potentially involved : 95,872Estimated percentage with defect : 1%

## **Vehicle Information:**

Vehicle 1: 2007-2011 BMW X5 xDrive30i, X5 xDrive35i, X5 xDrive48i, X5 xDrive50i, X5 M

Vehicle Type: LIGHT VEHICLES

Body Style: SUV Power Train: GAS

Descriptive Information: 77,745 vehicles were equipped with a Takata PSPI-2 passenger's front air bag inflator.

Production Dates: MAY 09, 2006 - AUG 11, 2011

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 2: 2009-2011 BMW X5 xDrive35d

Vehicle Type: LIGHT VEHICLES

Body Style : SUV Power Train : DIESEL

Descriptive Information: 8,364 vehicles were equipped with a Takata PSPI-2 passenger's front air bag inflator.

Production Dates: MAR 31, 2008 - SEP 28, 2011

Vehicle 3: 2008-2011 BMW X6 xDrive35i, X6 xDrive50i, X6 M

Vehicle Type: LIGHT VEHICLES

Body Style : SUV Power Train : GAS

Descriptive Information: 9,558 vehicles were equipped with a Takata PSPI-2 passenger's front air bag inflator.

Production Dates: JUL 05, 2007 - MAR 28, 2011

 Vehicle 4: 2010-2011 BMW X6 ActiveHybrid

Vehicle Type: LIGHT VEHICLES

Body Style: SUV

Power Train: HYBRID ELECTRIC

Descriptive Information: 205 vehicles were equipped with a Takata PSPI-2 passenger's front air bag inflator.

Production Dates: MAR 25, 2009 - SEP 12, 2011

VIN Range 1 : Begin : NR End : NR Not sequential

## **Description of Defect:**

Description of the Defect: This safety recall involves the passenger's front air bag. Approximately 95,872

affected vehicles were equipped with a Takata PSPI-2 inflator. For the defect description refer to Takata's Defect Information Reports, 16E-042, 16E-043

and 16E-044.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Takata addressed the safety risk in its Defect Information Reports 16E-042,

16E-043 and 16E-044.

Description of the Cause: BMW does not have independent information on which to base a complete root

cause assessment. However, according to Takata's Defect Information Report

16E-042, 16E-043 and 16E-044, its investigation to date indicates that

propellant wafers in some of the subject inflators may experience an alteration over time due to several years of exposure to persistent conditions of high

absolute humidity.

Based upon Takata's investigation to date, the potential for ruptures occurs in

some of the subject inflators after several years of exposure to persistent conditions of high absolute humidity, high temperatures, and high temperature

cycling. The potential for rupture may also be influenced by other factors, including the specific vehicle environment, the inflator and propellant

configuration, and manufacturing variability.

BMW is not aware of any test ruptures in ballistic testing or confirmed field incidents of the subject non-desiccated ammonium nitrate inflator PSPI-2

neither at vehicles in the field nor in conformity of production testing.

Identification of Any Warning NR that can Occur:

The information contained in this report was submitted pursuant to 49 CFR §573

## **Supplier Identification:**

## **Component Manufacturer**

Name: Takata AG Address: Bahnweg 1

Aschaffenburg FOREIGN STATES 63743

Country: Germany

## **Chronology:**

Please refer to BMW's 573 filing for Recall 16V-071 dated February 5, 2016.

In the Defect Information Reports filed with NHTSA on May 16, 2016 (16E-042, 16E-043 and 16E-044), Takata reported that it had determined that a defect related to motor vehicle safety may arise in some PSPI-2 inflators. BMW decided in an abundance of caution to conduct a safety recall to replace the frontal airbag(s) on the affected vehicles, based solely on the information provided by Takata.

BMW has not received any reports, nor is BMW otherwise aware, of any injuries or deaths related to this issue.

## **Description of Remedy:**

Description of Remedy Program: The passenger's front air bag module or inflator will be replaced.

However, due to the large volume of new inflators needed to repair vehicles, the necessary parts will not be immediately available. As a result, owners of affected vehicles will be informed of the recall in an initial notification letter. Once replacement parts become available BMW will send a second notification letter to owners, beginning with older model year vehicles located in BMW's previously defined HAH region and

expanding accordingly as more parts become available.

How Remedy Component Differs The final remedy component will incorporate a different inflator or air bag

from Recalled Component: module.

Identify How/When Recall Condition NR

was Corrected in Production:

### **Recall Schedule:**

Description of Recall Schedule: NR

Planned Dealer Notification Date: MAY 25, 2016 - NR Planned Owner Notification Date: JUL 18, 2016 - NR

Part 573 Safety Recall Report	16V-364	Page 4
* NR - Not Reported		
The information contained in this report was submitted	d pursuant to 49 CFR §573	