

Part 573 Safety Recall Report

16V-658

Manufacturer Name : Daimler Trucks North America LLC**Submission Date :** SEP 09, 2016**NHTSA Recall No. :** 16V-658**Manufacturer Recall No. :** FL-722**Manufacturer Information :****Population :**

Manufacturer Name : Daimler Trucks North America LLC

Number of potentially involved : 251

Address : 4747 N. Channel Avenue

Estimated percentage with defect : 100 %

Portland OR 97217-3849

Company phone : 800-745-8000

Vehicle Information :

Vehicle 1 : 2016-2017 Freightliner M2 Business Class

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Vehicles equipped with certain Meritor disc brakes.

Production Dates : MAR 10, 2015 - JUL 11, 2016

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 2 : 2016-2017 Freightliner 114 SD

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Vehicles equipped with certain Meritor disc brakes.

Production Dates : MAR 10, 2015 - JUL 11, 2016

VIN Range 1 : Begin : NR End : NR

 Not sequential**Description of Defect :**

Description of the Defect : On certain trucks, the brake caliper mounting bolts may be incorrectly torqued. This could result in caliper bolts loosening. A caliper with loose bolts may lead to detachment.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Insufficiently torqued fasteners may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduce brake effectiveness. Reduced brake effectiveness could lead to a vehicle crash.

Description of the Cause : NR
Identification of Any Warning NR
that can Occur :

Supplier Identification :

Component Manufacturer

Name : NR
Address : NR
NR
Country : NR

Chronology :

July 2016, DTNA was notified of reports for loose caliper mounting bolts. September 2016, DTNA decided to initiate a voluntary safety campaign to recall affected vehicles.

Description of Remedy :

Description of Remedy Program : Potentially affected vehicles will be inspected. If loose bolts are identified, the vehicle will be repaired. Repairs will be performed by Daimler Trucks North America authorized service facilities. Copies of the reimbursement plan will be submitted as a supplemental report when available.

How Remedy Component Differs NR
from Recalled Component :

Identify How/When Recall Condition NR
was Corrected in Production :

Recall Schedule :

Description of Recall Schedule : Customer notification will be made by first class mail using Daimler Trucks North America records to determine the customers affected.

Planned Dealer Notification Date : NOV 07, 2016 - NOV 07, 2016
Planned Owner Notification Date : NOV 07, 2016 - NOV 07, 2016

* NR - Not Reported