

Part 573 Safety Recall Report

16V-713

Manufacturer Name : Jayco, Inc.

Submission Date : OCT 04, 2016

NHTSA Recall No. : 16V-713

Manufacturer Recall No. : 9901321



Manufacturer Information :

Manufacturer Name : Jayco, Inc.

Address : 903 South Main Street

PO Box 460 Middlebury IN 46540

Company phone : 800-283-8267

Population :

Number of potentially involved : NR

Estimated percentage with defect : NR

Vehicle Information :

Vehicle 1 : 2017-2017 Travel Trailer Seismic

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Circuit for the Awning LED lights and wireless control board is not protected with correct fuse.

Production Dates : MAY 17, 2016 - AUG 19, 2016

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : Incrct polyfuse used 1.1amp hold /2.2 amp trip when correct polyfuse required is 1.85 amp hold /3.70amp trip.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : improper circuit protection could lead to electrical short which may result in fire causing personal injury

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

September 27, 2016 Electrical Engineer reported that during routine line audit he discovered production line was not installing the correct fuse to provide circuit protection required for the awning with LED lights.

Description of Remedy :

Description of Remedy Program : Change type of fuse to 1.85 amp hold /3.70 amp trip.

How Remedy Component Differs NR
from Recalled Component :Identify How/When Recall Condition NR
was Corrected in Production :**Recall Schedule :**

Description of Recall Schedule : Jayco will provide appropriate fuse to protect the circuit at no cost to current owner

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported