#### The information contained in this report was submitted pursuant to 49 CFR §573

### OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

Manufacturer Name :	Ford Motor Company
Submission Date :	OCT 07, 2016
<b>NHTSA Recall No. :</b>	16V-733
Manufacturer Recall No. :	16C14

### **Manufacturer Information :**

Manufacturer Name : Ford Motor Company Address: 330 Town Center Drive Suite 500 Dearborn MI 48126-2738 Company phone : 1-866-436-7332

### Vehicle Information :

Vehicle 1:	2015-2016 Ford Edge
Vehicle Type :	LIGHT VEHICLES
Body Style :	
Power Train :	NR
Descriptive Information :	Affected vehicles that have visited the dealership for service and may have received an incorrect software update.
	These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.
Production Dates :	FEB 09, 2015 - AUG 12, 2016
VIN Range 1:	Begin : NR End : NR

### **Description of Noncompliance :**

Description of the An incorrect Antilock Brake System\_Electronic Stability Control (ABS\_ESC) Noncompliance : strategy software file may have been used to update vehicles that had been brought to a dealer for service. The incorrect software file disables the engine torque control of the Electronic Stability Control (ESC) system; does not display a warning lamp/indicator if a fault occurs in the stability control system, including Antilock Brake System (ABS), Traction Control (T/C), and ESC; does not display a warning lamp/indicator when T/C is disabled; and does not display a warning lamp/indicator when the Electric Park Brake (EPB) is applied. With the incorrect service software loaded, the vehicle would not comply with the requirements defined by FMVSS 126 Section 4, Section 5.3, Section 5.4 and FMVSS 135 Section 5.5.

**Population**:

Number of potentially involved :	53
Estimated percentage with defect :	NR

云 🔨 🕰 🕁

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

16V-733

## Part 573 Safety Recall Report

16V-733

Page 2

Identification of Any Warning that can Occur :	was made available for dealerships to download. The Brake System warning lamp will not illuminate when the EPB is applied.
Description of the Cause :	crash. The incorrect service software file was provided by the supplier, which in turn
	be no warning to the driver. Without ESC engine torque control, ESC performance may be adversely affected which could increase the risk of a
Description of the Safety Risk :	If a fault occurs in the stability control system (ABS, T/C, or ESC), there would
FMVSS 2 :	135 - Light vehicle brake systems
FMVSS 1 :	126 - Electronic stability control systems
	Ford is not aware of any reports of accident or injury related to this condition.

### **Supplier Identification :**

### **Component Manufacturer**

Name : Continental Automotive Systems Inc

Address : 1103 Jamestown Road Morganton NORTH CAROLINA 28655

Country: United States

### **Chronology** :

September 2016 – Ford received a field report indicating the parking brake indicator in the cluster did not illuminate with application of the parking brake. Further investigation of the report determined that the incorrect ABS\_ESC strategy software file had been flashed into the vehicle during service. This issue was brought to Ford's Critical Concern Review Group (CCRG) for review. Evaluation found that if the incorrect ABS module software file was loaded into a vehicle in service, it could affect ESC engine torque control, T/C, warning lamp/indicator if a system fault occurs in the stability control system, EPB is applied light, and the EPB drive away release function. Engineering verified that ABS and Electronic Brake Distribution (EBD) remain fully functional and that the EPB could still be applied.

On September 30, 2016, Ford's Field Review Committee reviewed the concern and approved a field action.

### **Description of Remedy :**

Description of Remedy Program :	Owners will be notified by mail and instructed to take their vehicle to a
	Ford or Lincoln dealer to have the ABS module replaced. An updated
	service software file is expected to be available mid-4th quarter, which will
	allow dealers to reprogram rather than replace the ABS module. There
	will be no charge for this service.

# Part 573 Safety Recall Report

Planned Owner Notification Date : NOV 28, 2016 - DEC 02, 2016

	Ford will forward a copy of the notification letters to dealers to the agency when available.
How Remedy Component Differs from Recalled Component :	NR
Identify How/When Recall Condition was Corrected in Production :	NR
was Corrected in Production :	
Recall Schedule :	
Recall Schedule :	Notification to dealers is expected to occur on October 10, 2016. Mailing of owner notification letters is expected to begin November 28, 2016 and is expected to be completed by December 2, 2016

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573