

Part 573 Safety Recall Report

16V-940

Manufacturer Name : Jaguar Land Rover North America, LLC

Submission Date : FEB 17, 2017

NHTSA Recall No. : 16V-940

Manufacturer Recall No. : J081



Manufacturer Information :

Population :

Manufacturer Name : Jaguar Land Rover North America, LLC

Number of potentially involved : 2,394

Address : 555 MACARTHUR BOULEVARD

Estimated percentage with defect : 1 %

MAHWAH NJ 07430

Company phone : 8188500

Vehicle Information :

Vehicle 1 : 2017-2017 Jaguar F-TYPE

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : NR

Descriptive Information : 2017 MY Jaguar F-TYPE Vehicles in select VIN range

Production Dates : JUL 14, 2016 - DEC 16, 2016

VIN Range 1 : Begin : SAJWA6AT4H8K41657 **End :** SAJWA6ET0H8K46350 Not sequential

Description of Defect :

Description of the Defect : On certain 2017 Model Year (MY) Jaguar F-TYPE vehicles, the front seatbelt pre-tensioners may not function properly due to a deviation in generant mix ratio.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : In the event of a crash of sufficient severity, the front seatbelt pre-tensioner may fail to operate when required. Failure to operate can lead to increased injuries to the front seat occupants.

Description of the Cause : NR

Identification of Any Warning NR
that can Occur :

Supplier Identification :**Component Manufacturer**

Name : NCS Pyrotechnie et Technologies SAS
Address : Rue de la Cartoucherie
BP 90010 Survilliers Fosses FOREIGN STATES
Country : France

Chronology :

See Document "JLR J081 Chronology".

Description of Remedy :

Description of Remedy Program : Owners will be notified and instructed to take their vehicle to an approved Jaguar dealer who will inspect both front seatbelt assemblies for identification of the production date. If the seatbelt production date is from the specified production dates at risk, it will be replaced. If the seatbelt production date is not from the specified production dates at risk, no further action is required. There will be no charge to owners for this repair.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Distribution of owner notification letters will occur on or before February 20, 2017. Notifications to dealers will occur on or before December 28, 2016.

Planned Dealer Notification Date : DEC 28, 2016 - DEC 28, 2016

Planned Owner Notification Date : FEB 20, 2017 - FEB 20, 2017

* NR - Not Reported