

# TOYOTA

## ◀ IMPORTANT UPDATE ▶

### PRODUCT SUPPORT DIVISION

*The attached Dealer Letter has been updated. Refer to the details below.*

| DATE            | TOPIC                                                                                                                                    |
|-----------------|------------------------------------------------------------------------------------------------------------------------------------------|
| 8/11/14         | Update to Operation Codes regarding Sequoia Large Retaining Hex Nut and Sample Owner Letter Added                                        |
| 10/24/14        | FAQ updated with additional information related to E04                                                                                   |
| 11/13/14        | ASM Reference Guide Added and UIO Updated                                                                                                |
| 02/09/15        | Update to UIO                                                                                                                            |
| 04/09/15        | Important Reminder Added                                                                                                                 |
| 04/30/15        | Phase 5 Launch                                                                                                                           |
| 05/12/15        | Additional 2003-2004MY Tundra and 2004MY Sequoia Vehicles Added                                                                          |
| 06/15/15        | 05-07MY Corolla, Corolla Matrix, Sequoia, and 05-06MY Tundra Vehicles Added to D3F – Interim Phase                                       |
| 07/01/15        | Update to Rental Information, Warranty Sublet, and Return Parts Shipping                                                                 |
| 09/30/15        | Phase 6 Launch                                                                                                                           |
| 10/29/15        | Phase 7 Launch                                                                                                                           |
| 11/12/15        | Phase 8 Launch                                                                                                                           |
| 12/17/15        | Phase 9 Launch                                                                                                                           |
| 03/01/15        | Expanded to include 08MY Corolla and Corolla Matrix (Phase 10)                                                                           |
| 03/10/16        | An additional repair procedure to replace the airbag assembly is now available for Corolla Matrix vehicles.                              |
| 05/09/16        | An additional airbag inflator Part Number is now available for 2005-2008 Model Year Corolla vehicles.                                    |
| <b>08/08/16</b> | <b><i>An additional airbag inflator Part Number is now available for 2005-2007 Model Year Sequoia and 2005-2006 Tundra vehicles.</i></b> |

***The most recent update in the attached Dealer Letter will be highlighted with a red box.***

Please review this notification with your staff to assure that all relevant personnel have been briefed regarding this subject.

Thank you for your cooperation.

To: All Toyota Dealer Principals, Service Managers, and Parts Managers

Subject: Safety Recall **DSF Remedy Update**  
Certain 2003-2008 Model Year Corolla and Corolla Matrix Vehicles  
Certain 2003-2006 Model Year Tundra Vehicles  
Certain 2002-2007 Model Year Sequoia Vehicles  
Front Passenger Airbag Inflator Module

## **Background**

The original remedy for Safety Recall D0F launched in early April, 2013, included an inspection and, if necessary, replacement of the airbag inflator module.

- In early June, 2014, supplemental Safety Recall DSF was announced with a revised remedy which involved replacement of the passenger inflator module regardless of inspection results.
- In early May, 2015, Toyota expanded Safety Recall DSF to include certain 2003-2004 model year Tundra vehicles and 2004 model year Sequoia vehicles.
- In mid-June, 2015, Toyota expanded Safety Recall DSF to include certain 2005-2007 model year Corolla, Corolla Matrix, Sequoia, and 2005-2006 model year Tundra vehicles.

*Toyota has completed the remedy and owner mailing preparations for Phases 1-9. **Owners of vehicles covered by the March 2016 expansion (Phase 10) will be mailed an interim owner letter beginning in mid-March, 2016. Toyota will then mail a remedy owner letter to these owners beginning in early June, 2016. All affected vehicles are eligible for an inflator replacement.***

## **Condition**

The subject vehicles are equipped with front passenger airbag inflators which may have been manufactured in such a way as to have a potential for the intrusion of moisture over time. Depending on the circumstances, this could create excessive internal pressure when the airbag is deployed and cause the inflator to rupture. In the event of an inflator rupture, metal fragments could pass through the airbag cushion material, striking the vehicle occupants and potentially resulting in serious injury or death.

## Remedy

The remedy has been launched in phases due to limited parts availability.

| Phase | Model                                                                          | Location                                                                                                                                                                                                                                                                                                                                     | Launch Date          |
|-------|--------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|
| 1     | 03-04MY Corolla<br>03-04MY Corolla Matrix<br>03-04MY Tundra<br>02-04MY Sequoia | Vehicles registered in Florida, Hawaii, Puerto Rico and U.S. Virgin Islands.                                                                                                                                                                                                                                                                 | Late June, 2014      |
| 2     |                                                                                | Vehicles registered in Gulf States Toyota (GST) and Southeast Toyota (SET).<br>States: AL, AR, FL, LA, GA, MS, NC, OK, SC, and TX                                                                                                                                                                                                            | Mid-February, 2015   |
| 3     |                                                                                | Vehicles registered in Central Atlantic Toyota (CAT)<br>States: DE, MD, PA, VA, and WV                                                                                                                                                                                                                                                       | Late March, 2015     |
| 4     |                                                                                | Vehicles registered in San Francisco and Los Angeles Regions<br>State: CA                                                                                                                                                                                                                                                                    | Early April, 2015    |
| 5     |                                                                                | Vehicles registered in Boston and New York Regions<br>States: CT, MA, ME, NH, NJ, NY, RI, and VT                                                                                                                                                                                                                                             | Late April, 2015     |
| 6     | 03-04MY Corolla<br>03-04MY Corolla Matrix                                      | Vehicles registered in Chicago, Cincinnati, Denver, Kansas City, and Portland Regions<br>States: AK, AZ, CO, IA, ID, IL, IN, KS, KY, MI, MN, MO, MT, ND, NE, NM, NV, OH, OR, SD, TN, UT, WA, WI, and WY                                                                                                                                      | Late September, 2015 |
| 7     | 03-04MY Tundra<br>02-04MY Sequoia                                              |                                                                                                                                                                                                                                                                                                                                              | Late October, 2015   |
| 8     | 05-07MY Corolla<br>05-07MY Corolla Matrix                                      | Vehicles registered in Gulf States Toyota (GST) and Southeast Toyota (SET).<br>States: AR, NC, and OK<br>(GST/SET states not listed are involved in Safety Recall E04 – For Areas of High Absolute Humidity)                                                                                                                                 | Mid-November, 2015   |
| 9     | 05-06MY Tundra<br>05-07MY Sequoia                                              | Vehicles registered in Boston, Central Atlantic Toyota (CAT), Chicago, Cincinnati, Denver, Kansas City, Los Angeles, New York, Portland, and San Francisco Regions<br>States: AK, AZ, CA, CO, CT, DE, IA, ID, IL, IN, KS, KY, MA, MD, ME, MI, MN, MO, MT, ND, NE, NH, NJ, NM, NV, NY, OH, OR, PA, RI, SD, TN, UT, VA, VT, WA, WI, WV, and WY | Mid-December 2015    |
| 10    | 08MY Corolla<br>08MY Corolla Matrix                                            | All Locations<br>Note: Vehicles originally sold in, or currently/previously registered in, areas of High Absolute Humidity are included in Safety Recall E04.                                                                                                                                                                                | Early March, 2016    |

Toyota dealers are requested to replace the front passenger airbag inflator at **no charge** to the vehicle owner. (For certain models, the front passenger airbag assembly may be replaced.)

The following information is provided to inform you of the owner notification timing and your degree of involvement.

### 1. Owner Letter Mailing

Toyota notified all owners of vehicles covered by Phases 1-8. The notification start and end dates vary based on the launch date of each phase. The owner letter notifications for these customers has been completed.

Toyota began notifying owners of vehicles covered by Phase 9 in early January, 2016. The owner letters will be mailed in quantities consistent with parts availability and dealer repair capacity, and is expected to complete by June 1, 2016.

Toyota will mail an interim letter to owners of vehicles covered by the March 2016 expansion (Phase 10) beginning in mid-March, 2016. Toyota will then mail a remedy letter to these owners beginning in early June, 2016.

*Toyota makes significant effort to obtain current customer name and address information when mailing owner letters. In the event your dealership receives a notice for a vehicle that was sold prior to the Safety Recall announcement, it is the dealership's responsibility to forward the owner letter to the customer who purchased the vehicle.*

If a dealer is contacted by an owner who has not yet received the notification, please instruct the dealer to **verify coverage by confirming through TIS**. Dealers should perform the procedure as outlined in the Technical Instructions located on TIS.

**2. Pre-Owned Vehicles in Dealer Stock**

All vehicles in dealership stock that are covered by this Safety Recall must have the passenger airbag inflator replaced before customer delivery.

**3. Number and Identification of Covered Vehicles**

There are approximately 1,874,000 Toyota vehicles covered by this Safety Recall. Vehicles covered by Safety Recall DOF that previously received a replacement airbag inflator module are not included in either action.

| Model          | Model Year | Appx. UIO | Production Range                         |
|----------------|------------|-----------|------------------------------------------|
| Corolla        | 2003-2008  | 1,150,000 | Mid-December, 2001 - Late December, 2007 |
| Corolla Matrix | 2003-2008  | 242,000   | Mid-December, 2001 - Mid-December, 2007  |
| Tundra         | 2003-2006  | 309,000   | Late May, 2002 - Late December, 2006     |
| Sequoia        | 2002-2007  | 173,000   | Early April, 2002 - Early November, 2007 |

**4. Campaign Special Service Tools**

In a shipment which was scheduled to arrive on July 31, 2013, your dealership was sent a package containing special service tools for Safety Recall DOF which will also be used for this campaign.

These tools are needed when performing the front passenger airbag inflator module campaign. These tools **ARE NOT** available through normal parts or tools channels. There is a very limited supply of tools, but if additional tools are needed, contact your regional representative.

| Name                               | Sample Image | Qty |
|------------------------------------|--------------|-----|
| Airbag Mounting Bracket & hardware |              | 1   |
| Barcode Scanner                    |              | 1   |

**5. Technician Training Requirements**

The repair quality of covered vehicles is extremely important to Toyota. All dealership technicians performing this repair are required to successfully complete the most current version of the E-Learning course “Safety Recall and Service Campaign Essentials”. To ensure that all vehicles have the repair performed correctly; technicians performing this repair must also complete **SC13B** and be certified to one or more of the following levels:

- **Toyota Expert - Electrical**
- **Master Technician**
- **Master Diagnostic Technician (MDT)**

It is the dealership’s responsibility to select technicians with the above certification level or greater to perform this Safety Recall repair. Carefully review your resources, the technician skill level, and ability before assigning technicians to this repair. It is important to consider technician days off and vacation schedules to ensure there are properly trained technicians available to perform this repair at all times.

## 6. Campaign Specific Part Associate E- Learning Training Requirement

The Airbag Inflator Assembly being replaced during this campaign is a Class 9 Hazmat part. Therefore Parts Associates involved in this recall are required to complete E-Learning Module (**E2140** “Safety Recall D0F – Front Passenger Airbag Inflator” found on [www.utodealer.com](http://www.utodealer.com)) This E-Learning module will explain the proper procedure for documenting and returning the Airbag Inflator Assembly to TK Holdings Incorporated.

## 7. Shipping Information for Removed Inflators and Airbag Assemblies

***Important:** For the Continental 48 states, airbag assemblies are now included in the return shipping process. Refer to the updated Shipment Preparation Job Aid on TIS.  
Updated: 3/10/2016*

### *New Parts Return Shipping Process – Effective July 1, 2015*

NOTE: This updated inflator recovery program only applies to the Continental 48 States. Alaska, Hawaii, and the US Territories will continue to use the current program.

**IMPORTANT:** Effective July 1, 2015, the current inflator part return process, **using Fed-Ex as the shipper will be discontinued.** A procedure has been developed by Takata. This part return procedure also includes removed airbag assembly. With this process, each dealer will be required to perform the following:

- Apply a return address label to the outside of each returned airbag/inflator box (**Label provided by Takata in the new part box**).
- Store the old inflators on a pallet until they accumulate 100 inflators/airbag assemblies or whatever amount is collected after 30 days.
- **Keep a running log of how many of each type (Driver or Passenger) inflators and airbag assemblies are on the pallet.**
- Secure the inflators on the pallet with shrink wrap.
- Contact Takata at 1-877-650-9409 to arrange LTL pick-up.
- Place an over-pack label on the palletized load and provide the LTL driver with the pre-filled out documentation that will be sent to the dealer by Takata.

The process will not require the dealer to fill out any paperwork. All documents will be filled out by Takata and returned to the dealer.

Starting June 2015, during part production, Takata started replacing the current FedEx documentation in the airbag/inflator box with the new return labels and updated instructions. To support this new process, in late June 2015, each dealer will receive:

- 4 laminated Job Aids to help you understand the new process.
- 1 roll (125) of the new return labels to use until the new inflators start to arrive with the correct labels in the box. More labels will be available from Takata if needed.

Refer to the Job Aid available on TIS for more details on the new process and how to get more labels.

In addition, to compensate dealers for purchasing pallets and shrink wrap, a sublet claim of 0.20 cents per vehicle may be applied to each inflator replacement warranty claim starting July 1, 2015.

**8. Parts Ordering Process**

An additional airbag inflator Part Number is now available for 2005-2007 Model Year Sequoia and 2005-2006 Tundra vehicles.

Updated: 08/08/2016

**Non SET and GST Parts Ordering Process**

Due to limited availability, the parts have been placed on either Manual Allocation Control (MAC) or Dealer Ordering Solutions (DOS). As the parts inventory improves, the ordering process may change. Please check the Toyota Special Activities MAC/DOS report on Dealer Daily for the most up-to-date parts ordering information.

| Model          | Model Year | Part Number                      | Part Description           | Qty. |
|----------------|------------|----------------------------------|----------------------------|------|
| Corolla Matrix | 2003-2004  | 04003-28101                      | INFLATOR ASSY KIT, AIR BAG | 1    |
|                | 2005-2008  | 04004-75201                      | INFLATOR ASSY KIT, AIR BAG | 1    |
| Corolla        | 2003-2004  | 04003-28102                      | INFLATOR ASSY KIT, AIR BAG | 1    |
|                | 2005-2008  | 04004-75202<br>Or<br>04006-06102 | INFLATOR ASSY KIT, AIR BAG | 1    |
| Sequoia        | 2002-2004  | 04003-2810C                      | INFLATOR ASSY KIT, AIR BAG | 1    |
|                | 2005-2007  | 04004-7520C<br>Or<br>04006-0620C | INFLATOR ASSY KIT, AIR BAG | 1    |
| Tundra         | 2003-2004  | 04003-2810C                      | INFLATOR ASSY KIT, AIR BAG | 1    |
|                | 2005-2006  | 04004-7520C<br>Or<br>04006-0620C | INFLATOR ASSY KIT, AIR BAG | 1    |

**Important Note** The current airbag inflator for 2005-2007 Model Year Sequoia and 2005-2006 MY Tundra vehicles, part number 04004-7520C, is still available at some PDCs. **Please continue to order and utilize this Airbag Inflator until your facing PDC and dealer inventory is out of stock.** Orders placed for 04004-7520C will substitute to 04006-0620C once inventory at your facing PDC has been depleted.

An additional repair procedure to replace the airbag assembly is now available for Corolla Matrix vehicles.

**Important Note:** The current repair to replace the inflator is still available. If the vehicle is repaired with an airbag assembly and connector listed below, the inflator DOES NOT need to be replaced.

| Model          | Model Year | Part Number | Part Description            | Qty. |
|----------------|------------|-------------|-----------------------------|------|
| Corolla Matrix | 2003-2004  | 04005-22601 | AIRBAG ASSEMBLY W/ INFLATOR | 1    |
|                | 2005-2008  | 04005-22901 | AIRBAG ASSEMBLY W/ INFLATOR | 1    |
| - AND -        |            |             |                             |      |
| Corolla Matrix | ALL        | 04005-28112 | AIRBAG CONNECTOR            | 1    |

In the limited cases where the serial number is illegible, the Airbag Assembly will require replacement. **Please contact your regional representative for further direction on vehicle repair and claim filing procedures.**

**IMPORTANT PARTS ORDERING UPDATE**


All Safety Recall, Service Campaign (SSC/LSC) and Customer Support Program (CSP) parts are eligible for the Monthly Parts Return Program. Please refer to PANT Bulletin 2011-087 for campaign parts that are currently returnable under the Monthly Parts Return Program and additional details.

**9. Remedy Procedures**

Please refer to TIS for Technical Instructions on inspection and repair.

Conduct all applicable, non-completed Safety Recall and Service Campaigns on the vehicle during the time of appointment.

**10. Warranty Reimbursement Procedure**




| Model            | Op. Code | Description                         | Flat Rate Hour |
|------------------|----------|-------------------------------------|----------------|
| Tundra & Sequoia | AGG48B   | Replace Airbag Inflator             | 1.2 hr/vehicle |
| Corolla          | AGG48G   | Replace Airbag Inflator             | 0.9 hr/vehicle |
| Matrix           |          | Replace Airbag Assembly or Inflator |                |

- The flat rate times include 0.1 hours for administrative cost per unit for the dealership.
- Dealers may claim the cost for materials needed for inflator return shipping under opcodes AGG48B and AGG48G at a maximum rate of \$0.20 per vehicle as sublet type “ZZ.”
- If parts are not available due to back order, a loaner vehicle or alternative transportation through the Toyota Rent-A-CAR (TRAC) can be claimed for \$35 per day for a maximum of 4 days. Per day expense exceeding \$35 or loaners exceeding 4 days, requires DSPM authorization. For additional information, reference the Toyota Transportation Assistance Program (TTAP) guidelines.
- Towing can be claimed under Op. Code AGG48B, AGG48G, and AGG48W for a maximum of \$250 as sublet type “TW” in the event the customer requested vehicle pick up.

In limited instances, a Sequoia vehicle may have an inflator utilizing a large retaining hex nut on the right side. These vehicles are not involved in this Safety Recall. **Refer to the Sequoia Technical Instructions Section VIII-2 for additional details.**

| Model          | Op. Code | Description                                                                                                                                    | Flat Rate Hour |
|----------------|----------|------------------------------------------------------------------------------------------------------------------------------------------------|----------------|
| Sequoia (ONLY) | AGG48W   | Large Retaining Hex Nut Found<br>Vehicle not Involved Under this Safety Recall<br>(Refer to the Sequoia Technical Instructions Section VIII-2) | 0.3 hr/vehicle |

### 11. Campaign Designation Decoder



### 12. Repair Quality Confirmation

The repair quality of covered vehicles is extremely important to Toyota. To help ensure that all vehicles have the repair performed correctly, please designate at least one associate (someone other than the individual who performed the repair) to verify the repair quality of every vehicle prior to customer delivery.

### 13. Media Contacts

If you are a dealership associate and have any questions, please contact your District Service/Parts Manager. ***In the event you are contacted by the News media***, it is imperative that all media contacts (local and national) receive a consistent message. In this regard, all media contacts must be directed to Cindy Knight, (310) 468-2170 in Toyota Corporate Communications. (Please do not provide this number to customers.)

### 14. Customer Contacts

A FAQ is attached to help respond to any customer concerns. If the customer has any further questions, they are requested to contact the Toyota Customer Experience Center. The Toyota Customer Experience Center can be reached at 1-888-270-9371 Monday through Friday, 5:00 am to 6:00 pm, or Saturday 7:00 am to 4:00 pm Pacific Time.

*Please note the attached FAQ is published on the [www.Toyota.com](http://www.Toyota.com) website for customer viewing.*

***Please review this entire package with your Service and Parts staff to familiarize them with the proper step-by-step procedures required to implement this Safety Recall.***

Thank you for your cooperation.  
TOYOTA MOTOR SALES, U.S.A., INC.






**Safety Recall DSF/E04 - Supplemental ASM Reference**  
**Certain 2003-2008 Model Year Corolla and Corolla Matrix Vehicles**  
**Certain 2003-2006 Model Year Tundra Vehicles**  
**Certain 2002-2007 Model Year Sequoia Vehicles**  
**Front Passenger Airbag Inflator Module**


**The following information is being provided to help dealership associates understand the differences between the multiple Takata actions Toyota has announced.**

**Safety Recall Overview:**

In April, 2013, Toyota announced a nationwide Safety Recall (D0F) to inspect and, as necessary, replace front passenger airbag inflator modules manufactured for Toyota by Takata Corporation. In June, 2014, the recall remedy was revised to replace all inflators regardless of inspection results. The revision of the remedy was announced as a new Safety Recall DSF. All vehicles that did not receive a replacement inflator under D0F were included in DSF.



The geographic concentration of inflators with a higher risk of rupture in areas with consistently high absolute humidity warranted priority replacement in these areas. Therefore, Toyota has launched Safety Recall E04 which involves vehicles originally sold in, or currently/previously registered in, areas that are exposed to consistent High Absolute Humidity. These vehicles were previously included in Safety Recalls D0F/DSF and E0V.



In May, 2015, Toyota expanded Safety Recalls DSF and E04 to include additional vehicles.

- DSF expansion included certain 2003-2004 model year Tundra vehicles and 2004 model year Sequoia vehicles.
- E04 expansion included additional 2005-2007 model year Corolla, Corolla Matrix, Sequoia, and 2005-2006 model year Tundra vehicles.

**Updated 5/12/2015**

In June, 2015, Toyota expanded Safety Recalls DSF and E04 to include additional vehicles.

- DSF expansion included certain 2005-2007 model year Corolla, Corolla Matrix, Sequoia, and 2005-2006 model year Tundra vehicles.
- For E04, the high absolute humidity area is no longer limited to coastal areas of the specific states listed, and also now includes the state of South Carolina.

**Updated 6/15/2015**

In March, 2016, Toyota expanded Safety Recalls DSF and E04 to include 2008 model year Corolla and Corolla Matrix vehicles.

**Updated 3/1/2016**



**Safety Recall DSF:**

- 2003-2008 Corolla
- 2003-2008 Corolla Matrix
- 2003-2006 Tundra
- 2002-2007 Sequoia

**Safety Recall E04:**

- 2003-2008 Corolla
- 2003-2008 Corolla Matrix
- 2003-2006 Tundra
- 2002-2007 Sequoia

The map below provides a visual representation of the areas which have been included in Superseding Safety Recall E04 (Red Area). The yellow portion of the map represents an approximate geographic representation of vehicles covered by Safety Recall DSF.



*Note: This map is provided for reference purposes only. The inclusion of vehicles in Safety Recall E04 and DSF may differ from the visual representation shown on the map. Always verify vehicle Safety Recall applicability using the Technical Information System (TIS).*



**Safety Recall DSF/E04 - Supplemental ASM Reference**  
**Certain 2003-2008 Model Year Corolla and Corolla Matrix Vehicles**  
**Certain 2003-2006 Model Year Tundra Vehicles**  
**Certain 2002-2007 Model Year Sequoia Vehicles**  
**Front Passenger Airbag Inflator Module**

**Q1: Is the remedy different between DSF and E04?**

A1: No, all vehicles involved in DSF and E04 will receive a replacement passenger airbag inflator as parts become available. (For certain models, the front passenger airbag assembly may be replaced.) At this time Toyota has a limited number of inflators; therefore, we are first focusing on the E04 area, because testing of recovered inflators from High Absolute Humidity areas has indicated an elevated risk of rupture.

**Q2: Is Toyota offering passenger airbag disablement?**

A2: No. Toyota was only offering passenger airbag disablement as a temporary measure while sufficient parts were being produced. Toyota now has sufficient parts to support vehicles covered under E04. If the front passenger airbag was previously disabled due to unavailability of parts, please advise your customer that the dealer will promptly complete the remedy inflator replacement.

**Q2a: Why was Toyota temporarily offering passenger airbag disablement under Safety Recall E04?**

A2a: At the time, Toyota had a very limited supply of replacement airbag inflators to support vehicles covered under E04. This was only a temporary option for customers whose vehicles are covered under E04. While parts were being produced in sufficient quantity, the National Highway Traffic Safety Administration (NHTSA) granted Toyota permission to temporarily disable airbags only in High Absolute Humidity (E04) areas, but no others.

*Updated 2/24/2015*

**Q3: Which vehicles from Safety Recall DSF are now covered by Safety Recall E04?**

A3: Approximately 257,500 vehicles originally involved in DSF are now involved in Superseding Safety Recall E04. Vehicle transferred to E04 were originally sold in, or currently/previously registered in, areas of High Absolute Humidity, encompassing the following states: Texas, Alabama, Mississippi, Georgia, South Carolina, Florida, Hawaii, and Louisiana. In addition, it includes Puerto Rico, Guam, Saipan, American Samoa, and the U.S. Virgin Islands.

**Q4: What is absolute humidity?**

A4: The measure of the water vapor content in the air is known as absolute humidity, and it is displayed in grams of water vapor per cubic meter of air. Higher temperature, southern coastal-type climates consistently experience the greatest concentrations of water vapor in the air, as warmer ambient air can hold more water.

Note: relative humidity is simply a percentage value and is related to current or measured temperature; therefore, areas with high relative humidity do not necessarily have high absolute humidity

Certain 2003-2008 Model Year Corolla and Corolla Matrix,  
Certain 2003-2006 Model Year Tundra, and  
Certain 2002-2007 Model Year Sequoia Vehicles  
Front Passenger Airbag Inflator Module  
**SAFETY RECALL NOTICE (Remedy Notice)**

This notice applies to your vehicle [VIN]  
NHTSA Recall No. 15V-285 and 16V-127

**URGENT SAFETY  
RECALL**

This is an important  
Safety Recall  
Notification. **The remedy  
will be performed at NO  
CHARGE to you.**

Dear Toyota Owner:

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Toyota has decided that a defect, which relates to motor vehicle safety, exists in certain 2003-2008 model year Corolla and Corolla Matrix, 2003-2006 model year Tundra, and 2002-2007 model year Sequoia vehicles.

You received this notice because our records, which are based primarily on state registration and title data, indicate that you are the current owner.

**What is the condition?**

The subject vehicles are equipped with front passenger airbag inflators which may have been manufactured in such a way as to have a potential for the intrusion of moisture over time. Depending on the circumstances, this could create excessive internal pressure when the airbag is deployed and cause the inflator to rupture. In the event of an inflator rupture, metal fragments could pass through the airbag cushion material, striking the vehicle occupants and potentially resulting in serious injury or death.

**What will Toyota do?**

Any authorized Toyota dealer will replace the passenger airbag inflator module at **no charge** to you. (For certain models, the front passenger airbag assembly may be replaced.)

**What should you do?**

***This is an important Safety Recall.***

Toyota has completed parts preparation for vehicles in your geographic area. Please contact any authorized Toyota dealer to schedule an appointment to have this remedy performed as soon as possible. The repair will take approximately 2 hours. However, depending on the dealer's work schedule, it may be necessary to make your vehicle available for a longer period of time.

**Until the remedy is performed, we recommend that you do not operate the vehicle with an occupant in the front passenger seat.** We sincerely apologize for any inconvenience this will cause, but we are taking this action to ensure your safety.

You do not need an owner letter to have this recall completed; however, to assist the dealer in confirming vehicle eligibility, we request that you present this notice at the time of your service appointment.

If you would like to update your vehicle ownership or contact information, you may do so by registering at [www.toyota.com/ownersupdate](http://www.toyota.com/ownersupdate). You will need your full 17-digit Vehicle Identification Number (VIN) to input the new information.

**What if you have other questions?**

- ***Your local Toyota dealer will be more than happy to answer any of your questions and set up an appointment to perform the repair.***
- You can find additional information and locate a Toyota dealer in your area by going online and visiting [www.toyota.com/recall](http://www.toyota.com/recall).
- If you require further assistance, you may contact the Toyota Customer Experience Center at 1-888-270-9371 Monday through Friday, 5:00 am to 6:00 pm, Saturday 7:00 am to 4:00 pm Pacific Time.

- If you believe that the dealer or Toyota has failed or is unable to remedy the defect within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue S.E., Washington, D.C. 20590, or call the toll free Vehicle Safety Hot Line at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>.

•  
**What if you have previously paid for repairs to your vehicle for this specific condition?**

If you have previously paid for repairs to address this specific condition, please mail all required paperwork\* to the following address for reimbursement consideration and allow 6-8 weeks for processing:

Toyota Motor Sales, U.S.A., Inc  
Toyota Customer Experience, WC10  
19001 South Western Avenue, Torrance, CA 90509

\* Please refer to the attached Reimbursement Checklist for required paperwork details.

Please note that the dealer must complete the Safety Recall remedy before reimbursement consideration request can be processed.

If you are a vehicle lessor, Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

We have sent this notice in the interest of your continued satisfaction with our products, and we sincerely regret any inconvenience this condition may have caused you.

Thank you for driving a Toyota.

Sincerely,  
TOYOTA MOTOR SALES, U.S.A., INC.

SAMPLE



## Safety Recall DSF - **UPDATE**

Certain 2003-2008 Model Year Corolla and Corolla Matrix Vehicles

Certain 2003-2006 Model Year Tundra Vehicles

Certain 2002-2007 Model Year Sequoia Vehicles

Front Passenger Airbag Inflator Module

## Customer Frequently Asked Questions

Updated – March 1, 2016

We at Toyota care greatly about your safety. We are providing the following information to keep you informed of the details specific to this recall. Please check back frequently as this document will be updated.

**On March 1, 2016, Toyota expanded Safety Recall DSF to include 2008 model year Corolla and Corolla Matrix vehicles.**

Due to parts production capacity, Toyota recall #DSF has been launched in phases. **Toyota will notify owners of vehicles consistent with parts availability and dealer repair capacity.** Vehicles that already received a replacement passenger airbag inflator are not included in this Safety Recall.

### **Q1: What is the condition?**

A1: The subject vehicles are equipped with front passenger airbag inflators which may have been manufactured in such a way as to have a potential for the intrusion of moisture over time. Depending on the circumstances, this could create excessive internal pressure when the airbag is deployed and cause the inflator to rupture. In the event of an inflator rupture, metal fragments could pass through the airbag cushion material, striking the vehicle occupants and potentially resulting in serious injury or death.

### **Q1a: What is the Inflator?**

A1a: The inflator is a device contained within the airbag assembly. It contains solid propellant wafers which are ignited in the event airbag deployment is necessary. When ignited, the wafers expand into an inert gas, inflating the airbag.

### **Q2: How does my vehicle relate to the Takata and Toyota action for Areas of High Absolute Humidity?**

A2: Toyota has two separate Safety Recall actions related to Takata inflators. One is a nationwide recall (Toyota recall #DSF) and a second (Toyota recall #E04) is focused on the gulf coast states and other areas with consistently high absolute humidity. Your vehicle is included in nationwide Takata recall activity, and your passenger airbag inflator will be replaced when parts become available.

Takata has tested parts recovered from recalled vehicles. Test results from the parts recovered from consistently high absolute humidity areas (such as Florida and the Gulf Coast) have shown a possible correlation with high absolute humidity areas and elevated risk for passenger airbag inflator rupture. Test results of parts from areas with lower absolute humidity than these coastal regions have shown less risk of rupture. The geographic concentration of inflators with the potential for rupture in these areas of consistently high absolute humidity warrants priority replacement in these areas. Therefore, Toyota is conducting a separate Safety Recall (Toyota recall #E04) for areas with High Absolute Humidity, and is prioritizing the remedy of vehicles in these areas.

**Q2a: What is absolute humidity?**

A2a: The measure of the water vapor content in the air is known as absolute humidity, and it is displayed in grams of water vapor per cubic meter of air. Higher temperature, southern coastal climates consistently experience the greatest concentrations of water vapor in the air, as warmer ambient air can hold more water.

Note: relative humidity is simply a percentage value and is related to current or measured temperature; therefore, areas with high relative humidity do not necessarily have high absolute humidity.

**Q3: Until the remedy is performed on my vehicle, are there any steps I can take to minimize the occurrence of this condition?**

A3: No, There are no steps you can take to minimize the occurrence of this condition. However, the condition does not cause the airbag to activate when it should not. Also, the front passenger airbag is designed to inflate only in certain moderate to severe crashes. To further minimize risk, Toyota recommends that you locate passengers into the rear seating positions.

**Q4: What should you do?**

A4: Please contact any authorized Toyota dealer to schedule an appointment to have your front passenger airbag inflator replaced free of charge. When taking your vehicle to the dealership for your service appointment, it is recommended that only the driver occupy the vehicle. If you are uncomfortable driving the vehicle to the dealership, please contact your local authorized Toyota dealer who will arrange for vehicle pick up. Until the remedy is performed, the front passenger seat should NOT be occupied.

If you do not follow the instructions in the owner letter, you should not drive your vehicle.

**Q5: Are there concerns with other airbags in the vehicle?**

A5: No, this condition only applies to the front passenger airbag inflator. Other airbags in the vehicle are not affected by this condition.

**Q6: Will Toyota disconnect the involved airbag or the other airbags in my vehicle?**

A6: Toyota dealers have sufficient quantities of replacement parts to complete remedy repairs. Owners should visit a Toyota dealer to receive their replacement airbag inflator and system check. Airbag assemblies are integral parts of the overall vehicle safety system and the integrity of the system should always be checked by drivers observing the dash mounted warning lights. Toyota dealers are not authorized to disconnect any airbag system as part of this Safety Recall action.

**Q7: What is Toyota going to do?**

A7: The remedy has been launched in phases due to limited parts availability.

| Phase | Model                                       | Location                                                                                                                                                                                                     | Launch Date                                                                                                                                                                                                                                                                                                                                  |
|-------|---------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1     | 03-04MY Corolla                             | Vehicles registered in Florida, Hawaii, Puerto Rico and U.S. Virgin Islands.                                                                                                                                 | Late June, 2014                                                                                                                                                                                                                                                                                                                              |
| 2     |                                             | Vehicles registered in Gulf States Toyota (GST) and Southeast Toyota (SET).<br>States: AL, AR, FL, LA, GA, MS, NC, OK, SC, and TX                                                                            | Mid-February, 2015                                                                                                                                                                                                                                                                                                                           |
| 3     | 03-04MY Corolla Matrix                      | Vehicles registered in Central Atlantic Toyota (CAT)<br>States: DE, MD, PA, VA, and WV                                                                                                                       | Late March, 2015                                                                                                                                                                                                                                                                                                                             |
| 4     | 03-04MY Tundra                              | Vehicles registered in San Francisco and Los Angeles Regions<br>State: CA                                                                                                                                    | Early April, 2015                                                                                                                                                                                                                                                                                                                            |
| 5     | 02-04MY Sequoia                             | Vehicles registered in Boston and New York Regions<br>States: CT, MA, ME, NH, NJ, NY, RI, and VT                                                                                                             | Late April, 2015                                                                                                                                                                                                                                                                                                                             |
| 6     | 03-04MY Corolla<br>03-04MY Corolla Matrix   | Vehicles registered in Chicago, Cincinnati, Denver, Kansas City, and Portland Regions<br>States: AK, AZ, CO, IA, ID, IL, IN, KS, KY, MI, MN, MO, MT, ND, NE, NM, NV, OH, OR, SD, TN, UT, WA, WI, and WY      | Late September, 2015                                                                                                                                                                                                                                                                                                                         |
| 7     | 03-04MY Tundra<br>02-04MY Sequoia           |                                                                                                                                                                                                              | Late October, 2015                                                                                                                                                                                                                                                                                                                           |
| 8     | 05-07MY Corolla<br>05-07MY Corolla Matrix   | Vehicles registered in Gulf States Toyota (GST) and Southeast Toyota (SET).<br>States: AR, NC, and OK<br>(GST/SET states not listed are included in Safety Recall E04 – For Areas of High Absolute Humidity) | Mid-November, 2015                                                                                                                                                                                                                                                                                                                           |
| 9     |                                             | 05-06MY Tundra<br>05-07MY Sequoia                                                                                                                                                                            | Vehicles registered in Boston, Central Atlantic Toyota (CAT), Chicago, Cincinnati, Denver, Kansas City, Los Angeles, New York, Portland, and San Francisco Regions<br>States: AK, AZ, CA, CO, CT, DE, IA, ID, IL, IN, KS, KY, MA, MD, ME, MI, MN, MO, MT, ND, NE, NH, NJ, NM, NV, NY, OH, OR, PA, RI, SD, TN, UT, VA, VT, WA, WI, WV, and WY |
| 10    | <b>08MY Corolla<br/>08MY Corolla Matrix</b> | <b>All Locations</b><br>Note: Vehicles originally sold in, or currently/previously registered in, areas of High Absolute Humidity are included in Safety Recall E04.                                         | <b>Early March, 2016</b>                                                                                                                                                                                                                                                                                                                     |

Toyota notified all owners of vehicles covered by Phases 1-8. The notification start and end dates varied based on the launch date of each phase. The owner letter notifications for these customers has been completed.

Toyota began notifying owners of vehicles covered by Phase 9 in early January, 2016. The owner letters will be mailed in quantities consistent with parts availability and dealer repair capacity, and is expected to complete by June 1, 2016.

Toyota will mail an interim letter to owners of vehicles covered by the March 2016 expansion (Phase 10) beginning in mid-March, 2016. Toyota will then mail a remedy letter to these owners beginning in early June, 2016.

Toyota dealers will replace the front passenger airbag inflator at **no charge** to the vehicle owner. (For certain models, the front passenger airbag assembly may be replaced.)

**Q7a: How does Toyota obtain my mailing information?**

A7a: Toyota uses an industry provider who works with each states Department of Motor Vehicles (DMV) to receive registration or title information, based upon the DMV records. Please make sure your registration or title information is correct.

**Q7b: Do I need my owner letter to have the remedy performed?**

A7b: You do not need an owner letter to have this recall completed; however, to assist the dealer in confirming vehicle eligibility, we request that you present this notice at the time of your service appointment.

**Q8: Which and how many vehicles are covered by this Safety Recall?**

A8: There are approximately 1,874,000 Toyota vehicles covered this Safety Recall.

| Model          | Model Year | Appx. UIO | Production Range                         |
|----------------|------------|-----------|------------------------------------------|
| Corolla        | 2003-2008  | 1,150,000 | Mid-December, 2001 - Late December, 2007 |
| Corolla Matrix | 2003-2008  | 242,000   | Mid-December, 2001 - Mid-December, 2007  |
| Tundra         | 2003-2006  | 309,000   | Late May, 2002 - Late December, 2006     |
| Sequoia        | 2002-2007  | 173,000   | Early April, 2002 - Early November, 2007 |

**Q8a: Are there any other Toyota/Lexus/Scion vehicles covered by this Safety Recall in the U.S.?**

A8a: Yes. There are approximately 34,000 Lexus SC430 vehicles (certain 2002-2010 MY) covered by Lexus recall #DSC in the U.S.

**Q9: What if I previously paid for repairs to my vehicle for this condition?**

A9: Reimbursement consideration instruction will be provided in the remedy owner letter.

**Q10: What if I have additional questions or concerns?**

A10: If you have additional questions or concerns, please contact the Toyota Customer Experience Center at 1-888-270-9371 Monday through Friday, 5:00 am to 6:00 pm, or Saturday 7:00 am to 4:00 pm Pacific Time.