



David J. Johnson
Director
Service Engineering Operations
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

December 17, 2018

TO: All U.S. Ford and Lincoln Dealers

SUBJECT: Safety Recall 16S26 – Supplement #11
Certain 2005-2006 Ford GT, 2005-2011 Mustang, 2006-2011 Fusion and Milan,
2006 Zephyr, 2007-2011 MKZ, 2007-2010 Edge and MKX, and 2007-2011 Ranger
Vehicles
Passenger Airbag Inflator Replacement

New! REASON FOR THIS SUPPLEMENT

- *The deadline for the long-term rental program has been extended to **December 24, 2018** to allow dealers to finalize and submit claims, and to repair the few remaining vehicles. Dealers should prioritize these customers' vehicles to ensure they are repaired by this date. Refer to the Rental Vehicles section and the Takata Airbag Recall Rental Vehicle Policy attachment for details.*
- *To allow dealers to be creative in their approach to completing Takata airbag recall repairs, technician time recording requirements, as specified in the Warranty & Policy Manual, **are not required for this recall**. Some examples of creative approaches to repairs include:*
 - o *Mobile repairs*
 - o *Sublet repairs to outside repair facilities (including body shops)*
 - o *Utilizing other areas of the dealership such as new vehicle delivery, wash bays, parking lot, etc.*
 - o *Utilizing multiple technicians in an assembly-line form of repair*

REMINDER: Previous passenger airbag modules with part numbers AE5Z-54044A74-C and AH6Z-54044A74-C, for 2010-11 Fusion, Milan, and MKZ are subject to a stop sale and must be returned. **Do not perform any repairs using these parts.**

- If an affected part was installed in a vehicle, submit a web contact to the Special Service Support Center (SSSC) under FSA 18S34 using contact type 'Non-Involved'. Include repair order documentation showing use of the part on the vehicle.

REASON FOR THIS SAFETY RECALL

NHTSA and Takata have determined that the propellant in certain Takata airbag inflators can experience an alteration over time with exposure to certain climate conditions. A combination of time, high temperature fluctuations, and humidity contribute to the degradation of the propellant in the inflators. This degradation can cause the propellant to burn too quickly, creating high pressure inside the inflator, and in extreme cases causing the inflator to rupture in the event of a crash necessitating airbag deployment. A ruptured inflator can send inflator parts toward vehicle occupants resulting in serious injury or death. Additional information regarding Takata recalls can be found at www.nhtsa.gov and www.safercar.gov.

SERVICE ACTION

Dealers are to replace the passenger airbag inflator or passenger airbag module as directed in the Technical Information attachments. This service must be performed on all affected vehicles at no charge to the vehicle owner.

For Mustang and Ford GT vehicles, dealers should check OASIS to determine if safety recall 15S21 is open for the driver side airbag. If safety recall 15S21 is open, then it must be completed in addition to safety recall 16S26. Parts are readily available to complete safety recall 15S21.

NOTE: This is a final / permanent repair. All 2005-2006 Ford GT vehicles that were previously serviced under Safety Recall 14S28 must have this repair performed.

AFFECTED VEHICLES

Affected vehicles are identified in OASIS and FSA VIN Lists.

Vehicle	Model Year	Assembly Plant	Parts Availability
Mustang	2005-2006	Flat Rock	✓ Available
Ford GT	2005-2006	Wixom	✓ Available
Ranger	2007-2011	Twin Cities	✓ Available
Fusion/Milan	2006-2011	Hermosillo	✓ Available
MKZ/Zephyr	2006-2011	Hermosillo	✓ Available
Edge	2007-2010	Oakville	✓ Available
MKX	2007-2010	Oakville	✓ Available

OWNER NOTIFICATION MAILING SCHEDULE

Owner letters for Ranger, Mustang, Ford GT, and 2006-2009 MKZ/Zephyr vehicles have been mailed. Edge and 2006-2009 Fusion and Milan customers will be notified in 4 separate mailings starting the week of September 24, 2018. MKX and 2010-2011 Fusion, Milan, and MKZ customers will be notified in 4 separate mailings starting the week of October 29, 2018. Dealers must repair any affected vehicles that repairs are available for, whether or not the customer has received a letter.

PLEASE NOTE:

Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$21,000 per vehicle. Correct all vehicles in your new vehicle inventory before delivery.

New! ATTACHMENTS

<i>Attachment I:</i>	<i>Administrative Information</i>
Attachment II:	Labor Allowances and Parts Ordering Information
Attachment III:	Technical Information – 2010-2011 Mustang and 2005-2006 Ford GT
Attachment IV:	Technical Information – 2005-2009 Mustang
Attachment V:	Technical Information – 2007-2011 Ranger
Attachment VI:	Technical Information – 2006-2009 MKZ/Zephyr
Attachment VII:	Technical Information – 2006-2009 Fusion and Milan
Attachment VIII:	Technical Information – 2007-2010 Edge
Attachment IX:	Technical Information – 2010-2011 Fusion and Milan
Attachment X:	Technical Information – 2010-2011 MKZ
Attachment XI:	Technical Information – 2007-2010 MKX
Attachment XII:	Airbag Inflator Return Process – Parts with Core Charges
Attachment XIII:	Dealer Q & A

Attachment XIV: Takata Airbag Recall Rental Vehicle Policy

Owner Notification Letters

QUESTIONS & ASSISTANCE

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician Society (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Sincerely,



David J. Johnson

Safety Recall 16S26 – Supplement #11

Certain 2005-2006 Ford GT, 2005-2011 Mustang, 2006-2011 Fusion and Milan, 2006 Zephyr, 2007-2011 MKZ, 2007-2010 Edge and MKX, and 2007-2011 Ranger Vehicles
Passenger Airbag Inflator Replacement

OASIS ACTIVATION

OASIS was activated on June 30, 2016.

FSA VIN LISTS ACTIVATION

FSA VIN Lists were made available through <https://web.fsavinlists.dealerconnection.com> on September 24, 2018, for vehicles that can be repaired at this time.

NOTE: Your FSA VIN Lists may contain owner names and addresses obtained from motor vehicle registration records. The use of such motor vehicle registration data for any purpose other than in connection with this recall is a violation of law in several states, provinces, and countries. Accordingly, you must limit the use of this listing to the follow-up necessary to complete this recall.

SOLD VEHICLES

- Owners of affected vehicles will be directed to dealers for repairs.
- Immediately contact any of your affected customers whose vehicles are not on your VIN list but are identified in OASIS. Give the customer a copy of the Owner Notification Letter (when available) and schedule a service date.
- Correct other affected vehicles identified in OASIS which are brought to your dealership.
- Dealers are to prioritize repairs of customer vehicles over repairs of used vehicle inventory.

STOCK VEHICLES

- Dealers should use OASIS to identify any affected vehicles in your used vehicle inventory and perform the repair.

USED CAR LOTS/OTHER FRANCHISES

Dealers are encouraged to establish ongoing contacts with local used car lots, non-Ford or Lincoln branded dealerships, independent repair facilities and vehicle auctions. Dealers should request that these businesses notify them if they have vehicles affected by a Takata airbag recall. If a dealer is notified of vehicles that have an open Takata airbag recall, repairs must promptly be made to these vehicles.

DEALER-OPERATED RENTAL VEHICLES

The Fixing America's Surface Transportation (FAST) Act law effective June 2016 prohibits a rental company from selling, renting or leasing vehicles subject to a safety or compliance recall. Please consult your legal counsel for legal advice.

TITLE BRANDED / SALVAGED VEHICLES

Affected title branded and salvaged vehicles are eligible for this recall.

QUICK LANE REPAIRS

- At the dealer's discretion, dealers with Quick Lanes may now use Quick Lane service bays and Quick Lane technicians to perform **Takata Airbag Recalls**.
- Claim processing, hazardous material handling and parts returns **MUST** be processed through the main dealership's warranty submission process and parts department.
- No other warranty or recall repairs are allowed at Quick Lanes at this time.

OWNER REFUNDS

Refunds are not approved for this program.

Safety Recall 16S26 – Supplement #11

Certain 2005-2006 Ford GT, 2005-2011 Mustang, 2006-2011 Fusion and Milan, 2006 Zephyr, 2007-2011 MKZ, 2007-2010 Edge and MKX, and 2007-2011 Ranger Vehicles
Passenger Airbag Inflator Replacement

New! RENTAL VEHICLES

Parts are now available to order for all vehicles. With proper dealer parts ordering and service appointment scheduling, rental vehicles should not be required to complete this recall repair. Due to increased parts availability, *effective **December 24, 2018**, no additional long-term rentals will be approved. Back-dated rental approvals will not be approved effective **December 17, 2018**.*

NOTE: For customers that have been in a long-term rental vehicle as of, or before, the dates listed in the table below, the recall repair on their recalled vehicle must be completed by **December 24, 2018**. Parts for these customers' recalled vehicles were shipped to dealers in November 2018.

Customer's Recalled Vehicle:	Customer in Rental As Of, or Before:
2006-2009 Fusion/Milan/MKZ/Zephyr	September 24, 2018
2007-2010 Edge/MKX	October 19, 2018
2010-2012 Fusion/Milan/MKZ	November 16, 2018

These customers' recalled vehicles must be dropped off at their servicing dealership by **December 10, 2018** for repairs. If their recalled vehicle is not dropped off by **December 10, 2018**, the customer will be responsible for rental expenses incurred from December 10, 2018 until the date the vehicle is dropped off at the dealership.

If unique circumstances require additional rental days beyond **December 24, 2018**, include details outlining why the additional days are required in the SSSC web contact.

NOTE: Dealers must notify the customer the same day that the repair is completed on their vehicle and request that they promptly return the rental vehicle. Once a customer is notified that their vehicle is repaired, they have up to 7 days to return their rental vehicle and pick up their repaired vehicle. Any rental expenses incurred beyond these 7 days will not be reimbursed.

EXAMPLE: Repair is completed on December 12, and customer is notified the same day. The rental reimbursement will not extend past December 19.

Short-term rentals will remain available if a customer requests a rental vehicle while their vehicle is being repaired. The short-term rental vehicle program is an effort to make it easier for customers to have this recall repair completed and should only be offered when a customer requests a rental vehicle. Rental vehicles must not be used to help manage service department scheduling.

If a customer requests a rental vehicle while their vehicle is being repaired, refer to the flow chart in the Takata Airbag Recall Rental Policy attachment for the process for requesting rental vehicle reimbursement. Dealers must:

- order required parts prior to a customer's appointment.
- retain customers' vehicles until the recall repair is completed and the rental vehicle is returned.
- notify the customer the same day that the repair is completed on their vehicle and request that they promptly return the rental vehicle. Rentals exceeding 7 days from the date the customer is notified that their vehicle is repaired, will not be reimbursed.

If the customer has paid for a rental vehicle or alternative transportation for the purpose of this recall, they are eligible for reimbursement within the guidelines outlined in the Takata Airbag Recall Rental Vehicle Policy. Dealers must follow the same process for claiming rental vehicle reimbursement and then refund the customer.

REMINDER: Short-term rentals exceeding 4 days and all long-term rentals **must be submitted to the SSSC at the start of each rental approval period**. Refer to the flow chart in the Takata Airbag Recall Rental Policy attachment for details. If a customer is currently in a rental vehicle and an approval code has not been received for the current timeframe, or any required future timeframe, approval must be submitted to the SSSC by **December 17, 2018**. No back-dated, long-term rentals will be approved on, or after, **December 17, 2018**.

Safety Recall 16S26 – Supplement #11

Certain 2005-2006 Ford GT, 2005-2011 Mustang, 2006-2011 Fusion and Milan, 2006 Zephyr, 2007-2011 MKZ, 2007-2010 Edge and MKX, and 2007-2011 Ranger Vehicles
Passenger Airbag Inflator Replacement

FORD GT SPECIAL HANDLING

Ford and Lincoln dealers are authorized to claim up to a maximum combined value of \$200 to provide unique services to Ford GT owners under this recall. Examples of potential services include:

- o Technician travel to vehicle's location for remote repair
- o Vehicle transportation (towing/flatbed) to and from the dealership

In some cases, \$200 may not be sufficient to tow the vehicle to the dealership and redeliver to the customer. Dealers are encouraged to consider remote repairs at the vehicles location in these cases.

ADDITIONAL REPAIR (LABOR TIME AND/OR PARTS)

Additional repairs identified as necessary to complete the FSA should be managed as follows:

- Vehicles that have deployed, missing, or modified airbags need to be reviewed by the Special Service Support Center (SSSC) to ensure the potential risk for airbag inflator rupture is no longer present. Dealers should submit a VIN-specific web contact request to the SSSC with pictures showing the airbag's state and vehicle's VIN plate so a determination can be made.
- For related damage and access time requirements, refer to the Warranty and Policy Manual – Section 6 – Ford/Lincoln Program Policies – Field Service Actions (FSA) – Related Damage.
- Submit an Approval Request to the SSSC Web Contact Site prior to completing the repair.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using Dealer Management System (DMS) or One Warranty Solution (OWS) online.
 - o When entering claims, select claim type 31: Field Service Action. The FSA number (16S26) is the sub code.
 - o For additional claims preparation and submission information, refer to the Recall and Customer Satisfaction Program (CSP) Repairs in the OWS User Guide.
- Additional labor and/or parts must be claimed as related damage on a separate repair line from the FSA. **IMPORTANT:** Click the radio button on the Related Damage Indicator.

NOTE: The serial number of the new passenger airbag inflator or module must be provided to Ford for the claim to be processed. The Technical Information in this bulletin advises technicians to document the serial number from the new airbag inflator on the repair order. The passenger airbag inflator serial number is 11 characters for Ranger, Mustang, and GT and 13 characters for Edge, MKZ/Zephyr, Fusion, Milan, and MKX. If the serial number is not readable, a new inflator/module must be installed. Enter the serial number of the new airbag inflator or module in the claim as follows:

- For claims submitted using DMS or OWS on-line, enter the serial numbers in the Test Results Section.
 - Select DTC REQUIRED MEASUREMENT OR RESULTS from the drop down list.
 - Enter the serial number in the CODE field.
 - The serial number must be entered without spaces or dashes.
- For Ford GT Special Handling claim up to a maximum of \$200. All Special Handling must be on the same repair line the FSA is claimed. Claim Special Handling under Misc. Expense Code "OTHER."

Sublet Repairs - Refer to the Warranty & Policy Manual for details on sublet invoice requirements.

NOTE: Claim processing, hazardous material handling, and parts returns for sublet repairs must be processed through the dealership's warranty submission process and parts department. Labor operations published in this bulletin should be claimed, not an OSL labor operation.

Safety Recall 16S26 – Supplement #11

Certain 2005-2006 Ford GT, 2005-2011 Mustang, 2006-2011 Fusion and Milan, 2006 Zephyr, 2007-2011 MKZ, 2007-2010 Edge and MKX, and 2007-2011 Ranger Vehicles
Passenger Airbag Inflator Replacement

New! RENTAL VEHICLE REIMBURSEMENT – CLAIMING INSTRUCTIONS

Refer to the Takata Airbag Recall Rental Vehicle Policy attachment for dollar amounts and further reimbursement details.

NOTE: Due to increased parts availability, effective **December 24, 2018**, no additional long-term rentals will be approved, Back-dated rental approvals will not be approved effective **December 17, 2018**. Refer to the Rental Vehicles section of this Dealer Bulletin for details.

Rental Claiming Reference Table*

Rental Term	FSA	Miscellaneous Expense Codes	Claiming Notes
Short-Term	16S26	“RENTAL” for rental expense	Claim all eligible rental expenses and admin fee on the same RO line as the repair. Rental periods greater than 4 days require SSSC approval code.
		“FSAEXP” for \$25 admin fee	
Long-Term	18A01	“RENTAL” for rental expense	Claim all eligible rental expenses and \$25 admin fee on separate 18A01 RO lines. Requires SSSC approval code.
		“FSAEXP” for \$25 admin fee	

* Refer to the information below (continued on the following page) for full rental vehicle claiming instructions.

Short-Term Rental Vehicle Reimbursement

Applicable if parts are listed as ‘**Available**’ in the Dealer Bulletin and a customer requests a rental while the repair is being performed.

- Rental expenses must be claimed under FSA 16S26 on the same claim, and same RO line, as the repair.
- ATTENTION: Rental claims must not be submitted against 16S26 on a separate claim or RO line from the repair. If this occurs the FSA on that VIN can close erroneously and cause further warranty claiming concerns.**
- Dealers are pre-approved for up to 4 days of rental reimbursement.
 - If the rental period does not exceed 4 days**, submit the rental expense on the same claim and RO line as the repair. Use Misc. Expense Code “RENTAL”. No approval code is needed.
 - If the rental period exceeds 4 days**, a web contact must be submitted to the Special Service Support Center (SSSC) for approval. Include details outlining why additional rental days are required.
 - The SSSC web contact must include all rental expenses, admin fee (if applicable), parts costs, and labor costs. All of these amounts are required so the approval code will cover the entire RO line amount.
 - Enter the total amount of the rental expenses on the same claim, and same RO line, as the repair. Use Misc. Expense Code “RENTAL”.
 - A \$25 administrative fee can be claimed on any short-term rental claims that exceed 4 days of rental and have an RO date after September 23, 2018. Claim the administrative fee on the same RO line under Misc. Expense Code “FSAEXP”. The \$25 must be included in the SSSC approval amount.

Only actual rental expenses incurred should be claimed, regardless of approval. OWS will accept claims up to the approved RO line amount; SSSC contacts do not need to be updated to decrease approval amounts.

Safety Recall 16S26 – Supplement #11

Certain 2005-2006 Ford GT, 2005-2011 Mustang, 2006-2011 Fusion and Milan, 2006 Zephyr, 2007-2011 MKZ, 2007-2010 Edge and MKX, and 2007-2011 Ranger Vehicles
Passenger Airbag Inflator Replacement

New! RENTAL VEHICLE REIMBURSEMENT – CLAIMING INSTRUCTIONS (continued)**Long-Term Rental Vehicle Reimbursement**

NOTE: Due to increased parts availability, effective **December 24, 2018**, no additional long-term rentals will be approved, Back-dated rental approvals will not be approved effective **December 17, 2018**. Refer to the Rental Vehicles section of this Dealer Bulletin for details.

Applicable only if parts are listed as '**Limited**' or '**Not Available**' in the Dealer Bulletin and a customer requests a rental while waiting on parts.

- Rental expenses must be claimed under long-term rental program number 18A01. Enter the total amount of the rental expense under Misc. Expense Code "RENTAL".
NOTE: If a rental approval code has already been provided under FSA 16S26, that approval code can be submitted under 18A01 in OWS without updating the SSSC contact. If a 16S26 approval code being submitted under 18A01 also included parts, labor, etc., only claim the rental expense under 18A01.
- **Because long-term rentals end December 24, 2018, when submitting SSSC web contacts dealers should only request the actual rental days required.**
- For easier warranty claiming and rental invoicing, SSSC contacts can be updated to add additional days to a current approval code.
 - o EXAMPLE: If approved for 14 days and 10 more are required, update the SSSC contact to request the 10 additional days on the same approval code/RO line. The approval code will now include a total of 28 days. If further days are required, the request can be updated again.
- Rental agency invoices do not need to match the individual rental warranty claims submitted.
 - o EXAMPLE: Dealer has two rental approval codes for 14 days for the same VIN. A rental claim will need to be submitted for each prior approval code but a single rental invoice of 28 days will suffice.
 - o The total number of rental days paid, across all the rental claims submitted for this program on a VIN, will be compared against the total number of days included on the invoice(s).
- Dealers are eligible to claim a \$25 administrative fee for any long-term rental claims that are submitted after June 13, 2018. This includes claims that were originally approved by the SSSC after May 12, 2018 but processed for warranty payment after June 13, 2018. Claim the administrative fee on a separate RO line under Misc. Expense Code "FSAEXP".

Only actual rental expenses incurred should be claimed even if approved for additional rental days. OWS will accept claims up to the approved RO line amount, SSSC contacts do not need to be updated to decrease approval amounts.

Safety Recall 16S26 – *Supplement #11*

Certain 2005-2006 Ford GT, 2005-2011 Mustang, 2006-2011 Fusion and Milan, 2006 Zephyr, 2007-2011 MKZ, 2007-2010 Edge and MKX, and 2007-2011 Ranger Vehicles
Passenger Airbag Inflator Replacement

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Replace Passenger Airbag Inflator – 2005-2011 Mustang	16S26B	0.5 Hours
Replace Passenger Airbag Inflator – 2005-2006 Ford GT	16S26C	0.6 Hours
Replace Passenger Airbag Inflator – 2007-2011 Ranger	16S26D	0.5 Hours
Replace Passenger Airbag Module – 2006-2009 MKZ/Zephyr	16S26E	0.5 Hours
Replace Passenger Airbag Module – 2006-2009 Fusion/Milan	16S26F	0.4 Hours
Replace Passenger Airbag Module – 2007-2010 Edge	16S26G	0.4 Hours
Replace Passenger Airbag Module – 2010-2011 Fusion/Milan	16S26H	2.8 Hours
Replace Passenger Airbag Module – 2010-2011 MKZ	16S26L	2.9 Hours*
Replace Passenger Airbag Module – 2007-2010 MKX	16S26K	0.7 Hours

* Previous 2010-2011 MKZ technical instructions included steps for an airbag cushion sheet installation. 2010-2011 MKZ vehicles do not require an airbag cushion sheet.

PARTS AVAILABILITY MATRIX

NOTE: The airbag inflators for Mustang, Ford GT, and Ranger vehicles are shipped directly from the supplier rather than from a Ford parts warehouse. **PARTS ARE AVAILABLE FOR ORDERING even though parts warehouses will not show any inventory.**

Vehicle	Model Years	Parts Availability	Seed Stock
Mustang	2005-2011	Available on open order	2 nd seed stock in Nov. 2018
Ford GT	2005-2006	Available on open order	Seed stock completed
Ranger	2007-2011	Available on open order	Seed stock completed
Fusion/Milan	2006-2011	Available through the SSSC	TBD
MKZ/Zephyr	2006-2011	Available through the SSSC	TBD
Edge	2007-2010	Available through the SSSC	TBD
MKX	2007-2010	Available through the SSSC	TBD

Refer to the Parts Requirements and Parts Ordering Information sections on the following pages for specific part numbers and ordering information by vehicle and model year.

Safety Recall 16S26 – Supplement #11

Certain 2005-2006 Ford GT, 2005-2011 Mustang, 2006-2011 Fusion and Milan, 2006 Zephyr, 2007-2011 MKZ, 2007-2010 Edge and MKX, and 2007-2011 Ranger Vehicles
Passenger Airbag Inflator Replacement

PARTS REQUIREMENTS

Instructions on how to order each specific part number are listed on page 4 of this attachment.

NOTE: The parts used in this safety recall may physically appear to be identical, but they have differing operating characteristics. **It is crucial that parts are NOT interchanged or substituted.**

The DOR/COR number for this recall is 51115.

2005-2009 Mustang

Part Number	Description	Interior Color(s)	Component Color	Order Quantity	Claim Quantity
5R3Z-63044A74-B	Passenger Airbag Inflator	-	-	1	1

2010-2011 Mustang and 2005-2006 Ford GT

Part Number	Description	Interior Color(s)	Component Color	Order Quantity	Claim Quantity
6G7Z-63044A74-A	Passenger Airbag Inflator	-	-	1	1

2007-2011 Ranger

Part Number	Description	Interior Color(s)	Component Color	Order Quantity	Claim Quantity
8L5Z-10044A74-E	Passenger Airbag Inflator	-	-	1	1

2006-2009 MKZ/Zephyr

Part Number	Description	Interior Color(s)	Component Color	Order Quantity	Claim Quantity
7H6Z-54044A74-AD	Passenger Airbag Module	Light Stone	Light Stone	1	1
7H6Z-54044A74-AE	Passenger Airbag Module	Charcoal Black	Charcoal Black	1	1
7H6Z-54044A74-AF	Passenger Airbag Module	Sand	Sand	1	1

2006-2009 Fusion/Milan

Part Number	Description	Interior Color(s)	Component Color	Order Quantity	Claim Quantity
8E5Z-54044A74-AC	Passenger Airbag Module	Camel	Dark Stone	1	1
8E5Z-54044A74-AD	Passenger Airbag Module	Charcoal Black or Light Stone	Charcoal Black	1	1

Parts Requirements are continued on the following page.

Safety Recall 16S26 – Supplement #11

Certain 2005-2006 Ford GT, 2005-2011 Mustang, 2006-2011 Fusion and Milan, 2006 Zephyr, 2007-2011 MKZ, 2007-2010 Edge and MKX, and 2007-2011 Ranger Vehicles
Passenger Airbag Inflator Replacement

PARTS REQUIREMENTS (continued)

Instructions on how to order each specific part number are listed on page 4 of this attachment.

NOTE: The parts used in this safety recall may physically appear to be identical, but they have differing operating characteristics. **It is crucial that parts are NOT interchanged or substituted.**

The DOR/COR number for this recall is 51115.

2007-2010 Edge

Part Number	Description	Interior Color(s)	Component Color	Order Quantity	Claim Quantity
9T4Z-78044A74-AA	Passenger Airbag Module – 2007-2010 Edge Only	Charcoal Black or Camel	Charcoal Black	1	1
9T4Z-78044A74-AB	Passenger Airbag Module – 2008-2010 Edge Only	Medium Light Stone	Greystone	1	1
9T4Z-78044A74-AC	Passenger Airbag Module – 2007 Edge Only	Medium Light Stone	Medium Light Stone	1	1
9T4Z-78044A74-AD	Passenger Airbag Module – 2007 Edge Only	Camel	Medium Camel	1	1

2010-2011 Fusion/Milan

Part Number	Description	Interior Color(s)	Component Color	Order Quantity	Claim Quantity
AE5Z-54044A74-D	Passenger Airbag Module	-	-	1	1
W711044-S403 or W711044-S439	A-Pillar Trim Clip	-	-	1	2
W712961-S439	Steering Column Shaft-to-Steering Gear Bolt	-	-	1	1
AE5Z-7804500-A	Airbag Cushion Sheet	-	-	Only if required	

2010-2011 MKZ

Part Number	Description	Interior Color(s)	Component Color	Order Quantity	Claim Quantity
AH6Z-54044A74-D	Passenger Airbag Module	-	-	1	1
W711044-S403 or W711044-S439	A-Pillar Trim Clip	-	-	1	2
W712961-S439	Steering Column Shaft-to-Steering Gear Bolt	-	-	1	1

2007-2010 MKX

Part Number	Description	Interior Color(s)	Component Color	Order Quantity	Claim Quantity
9A1Z-78044A74-A	Passenger Airbag Module	-	-	1	1

Safety Recall 16S26 – Supplement #11

Certain 2005-2006 Ford GT, 2005-2011 Mustang, 2006-2011 Fusion and Milan, 2006 Zephyr, 2007-2011 MKZ, 2007-2010 Edge and MKX, and 2007-2011 Ranger Vehicles
Passenger Airbag Inflator Replacement

PARTS ORDERING INFORMATION

Due to the varying levels of part inventories, the parts ordering procedure and the distribution strategy for this recall will vary by vehicle line. Refer to the vehicle lines listed below for the part ordering procedure and distribution strategy. Once sufficient parts inventory is available, parts will be available for open ordering. Dealers will be notified via a DOES II communication if circumstances warrant a change in part supply strategy and when open ordering begins.

Fusion, Milan, MKZ/Zephyr, Edge, and MKX

To place an order, submit a VIN-specific Part Order contact via the SSSC Web Contact Site.

Mustang, Ford GT, and Ranger

Due to the large volume of affected Mustang vehicles that still have an open recall, dealers will receive a second seed stock of Mustang parts starting in the month of November 2018 to ensure parts are readily available to complete repairs. If additional parts are required, order your parts through normal order processing channels.

To guarantee the shortest delivery time, an emergency order for parts must be placed. The emergency order surcharge can be waived on Ford Motor Company-paid repairs; see section 2500 of the Dealer Parts Policy & Procedure Manual on FMCDealer for details on order submission requirements.

Due to the significant number of vehicles requiring repair dealers are encouraged to maintain stock of FSA parts to be prepared to repair vehicles as they arrive for repairs. To ensure that parts are readily available at dealers to repair the millions of Ford and Lincoln vehicles affected by the Takata airbag recalls, dealers may receive seed stocks of additional parts.

EXCESS STOCK RETURN

To support NHTSA-assigned completion mandates for the Takata airbag recalls, and the millions of Ford and Lincoln vehicles that require repairs under the Takata airbag recalls, excess stock returns will not be accepted for unused new recall remedy parts until 85% of all affected vehicles have been repaired. Dealers should utilize their FSA VIN list and DMS information to contact their affected customers and repair all vehicles that are brought to your dealership with an open Takata airbag recall.

DEALER PRICE

For latest prices, refer to DOES II.

PARTS RETENTION AND RETURN

It is critical that all original passenger airbag inflators removed from vehicles are not allowed back into the market. Therefore, all passenger airbag inflators under this safety recall have been assigned a \$100 core charge to ensure they will be properly returned.

The Regional Core Recover Center (RCRC), **including dealers in Alaska and Hawaii**, will pick up these airbag inflators along with all other core returns during your normal core retrieval visit.

For details, refer to attachment: Regional Core Recovery Center - Airbag Inflator Return Process

IMPORTANT:

- Old part number 5G7Z-63044A74-A for 2005-2006 Ford GT vehicles used under 14S28 must no longer be installed in vehicles, and can be returned via the FSA parts return process. Please use "CG" as the claim code and note in the shipper field the FSA bulletin number (16S26).
- Any new, unused stock of part numbers AE5Z-54044A74-C or AH6Z-54044A74-C (previously utilized under FSAs 16S26, 17S01, and 18S01) must no longer be installed in vehicles, and must be returned following the instructions in EFC07026, published November 1, 2018 on FMCDealer.

CERTAIN 2005-2006 FORD GT AND 2010-2011 MUSTANG VEHICLES — PASSENGER AIRBAG INFLATOR REPLACEMENT

OVERVIEW

Takata has determined that the propellant wafers in some airbag inflators may experience an alteration over time, which could potentially lead to an over-aggressive combustion in the event of a crash that requires airbag deployment. This potential condition could create excessive internal pressure when the airbag is deployed, which could result in the body of the inflator rupturing upon deployment increasing the risk of injury to occupants.

Dealers are to replace the passenger airbag inflator. The serial number from the new airbag inflator must be recorded on the repair order. Place the replaced inflator into the packaging from the new part and provide to the appropriate dealership personnel for part returns.

NOTE: For vehicles that the airbags have deployed or that have other modifications preventing the recall repair from being completed, submit a VIN specific request to the SSSC Web Contact Site prior to attempting a repair. Attach pictures of the vehicles airbag modules to the request.

SERVICE PROCEDURE

Recommended Tools:

1/4" Drive Deep Socket - 7mm
1/4" Drive Ratchet
1/4" Drive Extension - 6" (152mm)
1/4" Drive Shallow Socket - 8mm
1/4" Drive Impact Driver
1/4" Drive Torque Wrench
Side Cutters
Utility Knife
Needle Nose Pliers
Pocket Screwdriver



AIRBAG INFLATOR REPLACEMENT

NOTE: The following repair instructions only apply to 2010-2011 Mustang and 2005-2006 Ford GT vehicles. Repair instructions will be published in separate attachments for the other vehicle lines included in this recall as parts become available for those vehicles.

NOTE: The parts used in this safety recall may physically appear to be identical, but they have differing operating characteristics. It is crucial that parts are not interchanged or substituted.

 **WARNING:** Failure to follow the instructions and warnings in the Workshop Manual (WSM) may result in injury.

NOTE: If the Airbag Readiness light indicates no Supplemental Restraint System (SRS) faults are present, it is not necessary to follow the WSM SRS Depowering and Repowering steps. Turn the ignition to OFF and wait 1 minute, then it is safe to proceed with airbag inflator replacement.

NOTE: The ignition must remain OFF until this service procedure is completed.

NOTE: Mustang airbag shown in this procedure, Ford GT similar.

NOTE: To view a video demonstration of this repair procedure, click the video icon. 



NOTE: For Mustang vehicles equipped with SYNC, it is not necessary to remove the Accessory Protocol Interface Module (APIM) retainers to access the passenger airbag module. Unclip the APIM mounting bracket and position the APIM aside.

1. Remove the passenger airbag from the vehicle. Please follow the WSM procedures in Section 501-20B.
2. Set the airbag face down onto a surface that will not scratch or damage the airbag face.
3. Remove the wiring harness connector retainer from the passenger airbag assembly. See Figure 1.




FIGURE 1

NOTE: Carry out this step on the longer wire on the end opposite of the airbag inflator retaining bracket. See Figure 2.

4. Remove approximately 100 mm (3.93 in) of the conduit from the passenger airbag assembly wire harness. See Figure 2.




FIGURE 2



5. Position the shorting clip onto the harness wires, and crimp the shorting clip together one side at a time using pliers. See Figure 3.




FIGURE 3

6. Cut the harness wires between the shorting clip and the harness connector. See Figure 4.




FIGURE 4



7. Remove and discard the four passenger airbag inflator retaining bracket nuts and the retaining bracket. See Figure 5.




FIGURE 5

WARNING: Do not allow any debris on or around the airbag once the inflator is removed.

8. With an assistant holding the passenger airbag assembly, remove the inflator from the assembly by pushing outward on the inflator. Set the airbag inflator aside for return shipping. See Figure 6.

- If required, use of a brass punch is permitted (only at the location shown) to free the inflator from its mounted position.




FIGURE 6



NOTE: The serial number of the new airbag inflator must be provided to Ford for the warranty claim to be processed.

9. Record the 11 character serial number of the *new* airbag inflator on the repair order. See Figure 7.



FIGURE 7



10. **NOTE:** Both *new* inflator end caps are specific to their respective end of the inflator and must be fully seated.

NOTE: The tail end cap does not have an alignment tab and may be installed in any orientation.

Install both *new* inflator end caps making sure the alignment feature on the cap nearest the inflator retaining bracket is properly oriented. See Figure 8.




FIGURE 8

11. Install the inflator into the passenger airbag assembly with the orange connector end facing out. Align the three tabs on the cap nearest the inflator retaining bracket with the airbag module lower channel (facing down). See Figure 9.




FIGURE 9



NOTE: If the inflator retaining bracket is unable to be installed, ensure the inflator tail end cap is fully seated.

12. Install the *new* passenger airbag inflator retaining bracket and *new* nuts. See Figure 10.

- Torque the new retaining nuts in the sequence shown below to 4 Nm (35 lb.in).




FIGURE 10

13. Align the T-shape index on both the wiring harness electrical connector and the airbag inflator. Install the *new* wiring harness onto the passenger airbag module and connect to both sides of the inflator. See Figure 11.




FIGURE 11



14. Insert the inflator wiring harness connector tabs. See Figure 12.

NOTE: Pull gently on the wiring harness to ensure it is properly seated.




FIGURE 12

15. Re-install the passenger airbag. Please follow WSM procedures in Section 501-20B.

16. Package the replaced inflator in the *new* part box and provide to the appropriate dealership personnel for part returns.



CERTAIN 2005-2009 MUSTANG VEHICLES — PASSENGER AIRBAG INFLATOR REPLACEMENT

OVERVIEW

Takata has determined that the propellant wafers in some airbag inflators may experience an alteration over time, which could potentially lead to an over-aggressive combustion in the event of a crash that requires airbag deployment. This potential condition could create excessive internal pressure when the airbag is deployed, which could result in the body of the inflator rupturing upon deployment increasing the risk of injury to occupants.

Dealers are to replace the passenger airbag inflator. The serial number from the new airbag inflator must be recorded on the repair order. Place the replaced inflator into the packaging from the new part and provide to the appropriate dealership personnel for part returns.

NOTE: For vehicles that the airbags have deployed or that have other modifications preventing the recall repair from being completed, submit a VIN specific request to the SSSC Web Contact Site prior to attempting a repair. Attach pictures of the vehicles airbag modules to the request.

SERVICE PROCEDURE

Recommended Tools:

1/4" Drive Deep Socket - 7mm
1/4" Drive Ratchet
1/4" Drive Extension - 6" (152mm)
1/4" Drive Shallow Socket - 8mm
1/4" Drive Impact Driver
1/4" Drive Torque Wrench
Side Cutters
Utility Knife
Needle Nose Pliers
Pocket Screwdriver



AIRBAG INFLATOR REPLACEMENT

NOTE: The following repair instructions only apply to 2005-2009 Mustang vehicles. Repair instructions will be published in separate attachments for the other vehicle lines included in this recall as parts become available for those vehicles.

NOTE: The parts used in this safety recall may physically appear to be identical, but they have differing operating characteristics. It is crucial that parts are not interchanged or substituted.

 **WARNING:** Failure to follow the instructions and warnings in the Workshop Manual (WSM) may result in injury.

NOTE: If the Airbag Readiness light indicates no Supplemental Restraint System (SRS) faults are present, it is not necessary to follow the WSM SRS Depowering and Repowering steps. Turn the ignition to OFF and wait 1 minute, then it is safe to proceed with airbag inflator replacement.

NOTE: The ignition must remain OFF until this service procedure is completed.

NOTE: To view a video demonstration of this repair procedure, click the video icon. 



1. Remove the passenger airbag from the vehicle. Please follow the WSM procedures in Section 501-20B.
2. Set the airbag face down onto a surface that will not scratch or damage the airbag face.
3. Remove the wiring harness connector retainer from the passenger airbag assembly. See Figure 1.




FIGURE 1

NOTE: Carry out this step on the longer wire on the end opposite of the airbag inflator retaining bracket. See Figure 2.

4. Remove approximately 100 mm (3.93 in) of the conduit from the passenger airbag assembly wire harness. See Figure 2.




FIGURE 2



5. Position the shorting clip onto the harness wires, and crimp the shorting clip together one side at a time using pliers. See Figure 3.




FIGURE 3

6. Cut the harness wires between the shorting clip and the harness connector. See Figure 4.




FIGURE 4



7. Remove and discard the four passenger airbag inflator retaining bracket nuts and the retaining bracket. See Figure 5.




FIGURE 5

⚠ WARNING: Do not allow any debris on or around the airbag once the inflator is removed.

8. With an assistant holding the passenger airbag assembly, remove the inflator from the assembly by pushing outward on the inflator. Set the airbag inflator aside for return shipping. See Figure 6.
- If required, use of a brass punch is permitted (only at the location shown) to free the inflator from its mounted position.



FIGURE 6



NOTE: The serial number of the new airbag inflator must be provided to Ford for the warranty claim to be processed.

9. Record the 11 character serial number of the *new* airbag inflator on the repair order. See Figure 7.



FIGURE 7



10. **NOTE:** Both *new* inflator end caps are specific to their respective end of the inflator and must be fully seated.

NOTE: The tail end cap does not have an alignment tab and may be installed in any orientation. Make sure the tail end cap is fully seated or you will not be able to install the inflator retaining bracket.

Install both *new* inflator end caps making sure the alignment feature on the cap nearest the inflator retaining bracket is properly oriented. See Figure 8.




FIGURE 8

11. Install the inflator into the passenger airbag assembly with the orange connector end facing out. Align the three tabs on the cap nearest the inflator retaining bracket with the airbag module lower channel (facing down). See Figure 9.




FIGURE 9



NOTE: If the inflator retaining bracket is unable to be installed, ensure the inflator tail end cap is fully seated.

12. Install the *new* passenger airbag inflator retaining bracket and *new* nuts. See Figure 10.

- Torque the new retaining nuts in the sequence shown below to 4 Nm (35lb.in).




FIGURE 10

13. Align the T-shape index on both the wiring harness electrical connector and the airbag inflator. Install the *new* wiring harness onto the passenger airbag module and connect to both sides of the inflator. See Figure 11.




FIGURE 11



14. Insert the inflator wiring harness connector tabs. See Figure 12.

NOTE: Pull gently on the wiring harness to ensure it is properly seated.




FIGURE 12

15. Re-install the passenger airbag. Please follow WSM procedures in Section 501-20B.

16. Package the replaced inflator in the *new* part box and provide to the appropriate dealership personnel for part returns.



CERTAIN 2007-2011 RANGER VEHICLES — PASSENGER AIRBAG INFLATOR REPLACEMENT

OVERVIEW

Takata has determined that the propellant wafers in some airbag inflators may experience an alteration over time, which could potentially lead to an over-aggressive combustion in the event of a crash that requires airbag deployment. This potential condition could create excessive internal pressure when the airbag is deployed, which could result in the body of the inflator rupturing upon deployment increasing the risk of injury to occupants.

Dealers are to replace the passenger airbag inflator. The serial number from the new airbag inflator must be recorded on the repair order. Place the replaced inflator into the packaging from the new part and provide to the appropriate dealership personnel for part returns.

NOTE: For vehicles that the airbags have deployed or that have other modifications preventing the recall repair from being completed, submit a VIN specific request to the SSSC Web Contact Site prior to attempting a repair. Attach pictures of the vehicles airbag modules to the request.

SERVICE PROCEDURE

Recommended Tools:

1/4" Drive Deep Socket - 7mm
1/4" Drive Ratchet
1/4" Drive Extension - 6" (152mm)
1/4" Drive Shallow Socket - 8mm
1/4" Drive Impact Driver
1/4" Drive Torque Wrench
Side Cutters
Utility Knife
Needle Nose Pliers
Pocket Screwdriver



AIRBAG INFLATOR REPLACEMENT

NOTE: The following repair instructions only apply to 2007-2011 Ranger vehicles. Repair instructions will be published in separate attachments for the other vehicle lines included in this recall as parts become available for those vehicles.

NOTE: The parts used in this safety recall may physically appear to be identical, but they have differing operating characteristics. It is crucial that parts are not interchanged or substituted.



WARNING: Failure to follow the instructions and warnings in the Workshop Manual (WSM) may result in injury.

NOTE: If the Airbag Readiness light indicates no Supplemental Restraint System (SRS) faults are present, it is not necessary to follow the WSM SRS Depowering and Repowering steps. Turn the ignition to OFF and wait 1 minute, then it is safe to proceed with airbag inflator replacement.

NOTE: The ignition must remain OFF until this service procedure is completed.



1. Remove the passenger airbag from the vehicle. Please follow the WSM procedures in Section 501-20B.
2. Set the airbag face down onto a surface that will not scratch or damage the airbag face.
3. Remove the wiring harness connector retainer from the passenger airbag assembly. See Figure 1.




FIGURE 1

NOTE: Carry out this step on the shorter wire on the end opposite of the airbag inflator retaining bracket. See Figure 2.

4. Remove the conduit from the passenger airbag assembly wire harness in the area shown. See Figure 2.




FIGURE 2



5. Position the shorting clip onto the harness wires, and crimp the shorting clip together one side at a time using pliers. See Figure 3.
6. Cut the harness wires between the shorting clip and the harness connector. See Figure 3.




FIGURE 3

7. Remove and discard the four passenger airbag inflator retaining bracket nuts and the retaining bracket. See Figure 4.




FIGURE 4



⚠ WARNING: Do not allow any debris on or around the airbag once the inflator is removed.

8. With an assistant holding the passenger airbag assembly, remove the inflator from the assembly by pushing outward on the inflator. Set the airbag inflator aside for return shipping. See Figure 5.
 - If required, use of a brass punch is permitted (only at the location shown) to free the inflator from its mounted position.




FIGURE 5

NOTE: The serial number of the new airbag inflator must be provided to Ford for the warranty claim to be processed.

9. Record the 11 character serial number of the *new* airbag inflator on the repair order. See Figure 6.



FIGURE 6



10. **NOTE:** Both *new* inflator end caps are specific to their respective end of the inflator and must be fully seated.

NOTE: The tail end cap does not have an alignment tab and may be installed in any orientation. Make sure the tail end cap is fully seated or you will not be able to install the inflator retaining bracket.

Install both *new* inflator end caps making sure the alignment feature on the cap nearest the inflator retaining bracket is properly oriented. See Figure 7.




FIGURE 7



11. Install the inflator into the passenger airbag assembly with the orange connector end facing out. Align the three tabs on the cap nearest the inflator retaining bracket with the airbag module lower channel (facing down). See Figure 8.




FIGURE 8

NOTE: If the inflator retaining bracket is unable to be installed, ensure the inflator tail end cap is fully seated.

12. Install the *new* passenger airbag inflator retaining bracket and *new* nuts. See Figure 9.

- Torque the new retaining nuts in the sequence shown below. Tighten to 4 Nm (35 lb in).




FIGURE 9



13. Align the T-shape index on both the wiring harness electrical connector and the airbag inflator. Install the *new* wiring harness onto the passenger airbag module and connect to both sides of the inflator and fully seat the black tabs. See Figure 10.

NOTE: Pull gently on the wiring harness to ensure it is properly seated.




FIGURE 10

14. Install the *new* tape to the wiring harness and airbag assembly, do not cover the airbag warning label with the new tape. For correct placement See Figure 11.




FIGURE 11

15. Re-install the passenger airbag. Please follow WSM procedures in Section 501-20B.
16. Package the replaced inflator in the *new* part box and provide to the appropriate dealership personnel for part returns.



CERTAIN 2006-2009 MKZ/ZEPHYR VEHICLES – PASSENGER AIRBAG MODULE REPLACEMENT

OVERVIEW

Takata has determined that the propellant wafers in some airbag inflators may experience an alteration over time, which could potentially lead to an over-aggressive combustion in the event of a crash that requires airbag deployment. This potential condition could create excessive internal pressure when the airbag is deployed, which could result in the body of the inflator rupturing upon deployment increasing the risk of injury to occupants.

Dealers are to replace the passenger airbag module. The serial number from the new airbag module must be recorded on the repair order. Place the replaced airbag module into the packaging from the new part and provide to the appropriate dealership personnel for part returns.

NOTE: For vehicles that the airbags have deployed or that have other modifications preventing the recall repair from being completed, submit a VIN specific request to the SSSC Web Contact Site prior to attempting a repair. Attach pictures of the vehicles airbag modules to the request.

SERVICE PROCEDURE

NOTE: The following repair instructions only apply to 2006-2009 MKZ/Zephyr vehicles. Repair instructions will be published in separate attachments for other vehicle lines included in this recall as parts become available for those vehicles.

NOTE: The parts used in this safety recall may physically appear to be identical, but they have differing operating characteristics. It is crucial that parts are not interchanged or substituted.

 **WARNING:** Failure to follow the instructions and warnings in the Workshop Manual (WSM) may result in injury.

NOTE: If the Airbag Readiness light indicates no Supplemental Restraint System (SRS) faults are present, it is not necessary to follow the WSM SRS Depowering and Repowering steps. Turn the ignition to OFF and wait 1 minute, then it is safe to proceed with airbag inflator replacement.

NOTE: The ignition must remain OFF until this service procedure is completed.



1. Record the 13 character serial number of the new airbag module on the repair order. See Figure 1.
2. Replace the passenger airbag module. Refer to section 501-20B of the Workshop Manual.

NOTE: Use caution when removing the 5 instrument panel trim panel fasteners or the studs may strip out. Submit a contact to the SSSC if damage to the trim panel does occur.

3. Package the replaced airbag module in the new part box and provide to the appropriate dealership personnel for part returns.



FIGURE 1



CERTAIN 2006-2009 FUSION AND MILAN VEHICLES – PASSENGER AIRBAG MODULE REPLACEMENT

OVERVIEW

Takata has determined that the propellant wafers in some airbag inflators may experience an alteration over time, which could potentially lead to an over-aggressive combustion in the event of a crash that requires airbag deployment. This potential condition could create excessive internal pressure when the airbag is deployed, which could result in the body of the inflator rupturing upon deployment increasing the risk of injury to occupants.

Dealers are to replace the passenger airbag module. The serial number from the new airbag module must be recorded on the repair order. Place the replaced airbag module into the packaging from the new part and provide to the appropriate dealership personnel for part returns.

NOTE: For vehicles that the airbags have deployed or that have other modifications preventing the recall repair from being completed, submit a VIN specific request to the SSSC Web Contact Site prior to attempting a repair. Attach pictures of the vehicles airbag modules to the request.

SERVICE PROCEDURE

NOTE: The following repair instructions only apply to 2006-2009 Fusion and Milan vehicles. Repair instructions will be published in separate attachments for other vehicle lines included in this recall as parts become available for those vehicles.

NOTE: The parts used in this safety recall may physically appear to be identical, but they have differing operating characteristics. It is crucial that parts are not interchanged or substituted.



WARNING: Failure to follow the instructions and warnings in the Workshop Manual (WSM) may result in injury.

NOTE: If the Airbag Readiness light indicates no Supplemental Restraint System (SRS) faults are present, it is not necessary to follow the WSM SRS Depowering and Repowering steps. Turn the ignition to OFF and wait 1 minute, then it is safe to proceed with airbag inflator replacement.

NOTE: The ignition must remain OFF until this service procedure is completed.



1. Record the 13 character serial number of the new airbag module on the repair order. See Figure 1.
2. Replace the passenger airbag module. Refer to section 501-20B of the workshop manual.
3. Package the replaced airbag module in the new part box and provide to the appropriate dealership personnel for part returns.




FIGURE 1



CERTAIN 2007 - 2010 EDGE VEHICLES – PASSENGER AIRBAG MODULE REPLACEMENT

OVERVIEW

Takata has determined that the propellant wafers in some airbag inflators may experience an alteration over time, which could potentially lead to an over-aggressive combustion in the event of a crash that requires airbag deployment. This potential condition could create excessive internal pressure when the airbag is deployed, which could result in the body of the inflator rupturing upon deployment increasing the risk of injury to occupants.

Dealers are to replace the passenger airbag module. The serial number from the new airbag module must be recorded on the repair order. Place the replaced airbag module into the packaging from the new part and provide to the appropriate dealership personnel for part returns.

NOTE: For vehicles that the airbags have deployed or that have other modifications preventing the recall repair from being completed, submit a VIN specific request to the SSSC Web Contact Site prior to attempting a repair. Attach pictures of the vehicles airbag modules to the request.

SERVICE PROCEDURE

NOTE: The following repair instructions only apply to 2007 through 2010 Edge vehicles. Repair instructions will be published in separate attachments for other vehicle lines included in this recall as parts become available for those vehicles.

NOTE: The parts used in this safety recall may physically appear to be identical, but they have differing operating characteristics. It is crucial that parts are not interchanged or substituted.

 **WARNING:** Failure to follow the instructions and warnings in the Workshop Manual (WSM) may result in injury.

NOTE: If the Airbag Readiness light indicates no Supplemental Restraint System (SRS) faults are present, it is not necessary to follow the WSM SRS Depowering and Repowering steps. Turn the ignition to OFF and wait 1 minute, then it is safe to proceed with airbag inflator replacement.

NOTE: The ignition must remain OFF until this service procedure is completed.



1. Record the 13 character serial number of the new airbag module on the repair order. See Figure 1.
2. Replace the passenger airbag module. Refer to section 501-20B of the Workshop Manual.

NOTE: Releasing the side tabs of the airbag trim cover first will aid in the removal process.

3. Package the replaced airbag module in the new part box and provide to the appropriate dealership personnel for part returns.




FIGURE 1



CERTAIN 2010 – 2011 FUSION AND MILAN VEHICLES – PASSENGER AIRBAG MODULE REPLACEMENT

OVERVIEW

Takata has determined that the propellant wafers in some airbag inflators may experience an alteration over time, which could potentially lead to an over-aggressive combustion in the event of a crash that requires airbag deployment. This potential condition could create excessive internal pressure when the airbag is deployed, which could result in the body of the inflator rupturing upon deployment increasing the risk of injury to occupants.

Dealers are to replace the passenger airbag module. The serial number from the new airbag module must be recorded on the repair order. Place the replaced airbag module into the packaging from the new part and provide to the appropriate dealership personnel for part returns.

NOTE: For vehicles that the airbags have deployed or that have other modifications preventing the recall repair from being completed, submit a VIN-specific request to the SSSC Web Contact Site prior to attempting a repair. Attach pictures of the vehicle's airbag modules to the request.

SERVICE PROCEDURE

NOTE: The following repair instructions only apply to 2010 – 2011 Fusion and Milan vehicles. Repair instructions are published in separate attachments for other vehicle lines included in this recall as parts become available for those vehicles.

NOTE: The parts used in this safety recall may physically appear to be identical, but they have differing operating characteristics. It is crucial that parts are not interchanged or substituted.



WARNING: Failure to follow the instructions and warnings in the Workshop Manual (WSM) may result in injury.

NOTE: If the Airbag Readiness light indicates no Supplemental Restraint System (SRS) faults are present, it is not necessary to follow the WSM SRS Depowering and Repowering steps. Turn the ignition to OFF and wait 1 minute, then it is safe to proceed with airbag inflator replacement.

NOTE: The ignition must remain OFF until this service procedure is completed.



1. Record the 13 character serial number of the new airbag module on the repair order. See Figure 1.




FIGURE 1

2. Remove the left hand and right hand A-Pillar trim panels. Reuse the LH and RH trim panels for this repair. See Figure 2.

- Grasp the trim panel approximately 5 inches from the top and pull downward toward the door, then rotate the panel inward toward the windshield to slide it off of the a-pillar clip.

NOTE: Do not bend or flex the trim panels during removal to avoid stress marks from occurring.

NOTE: To view a video demonstration of this repair procedure, click the video icon. 



FIGURE 2



3. Remove and discard the top A-Pillar clip from the body. See Figure 3.




FIGURE 3

4. Remove the passenger airbag module. Please refer to Workshop Manual (WSM) procedures in section 501-20B.

- Remove the instrument panel crossmember-to-airbag module bracket. See Figure 4.
- Torque to 80 lb. in (9 Nm).




FIGURE 4



5. Remove the six nuts retaining the airbag module bracket to the instrument panel. Remove the bracket from the instrument panel. See Figure 5.

- Torque to 80 lb.in (9 Nm).




FIGURE 5



6. Inspect the white airbag cushion sheet installed on the instrument panel and the new airbag cushion sheet included with the new airbag module. See Figure 6.

NOTE: If any damage is present on the existing or new airbag cushion sheet it must be replaced. Type of damage includes, but is not limited to, cuts, creases, folds, or the perforations being broken.

NOTE: Sheets can be installed in any direction or orientation.




FIGURE 6



7. If no damage is found, clear both sheets of any dirt or debris and **install both sheets** on the airbag mounting bracket studs. See Figure 7.

NOTE: The sheets will not lay perfectly flat when installed on the instrument panel.




FIGURE 7

8. Reinstall the airbag module bracket onto the instrument panel. See Figure 5.
9. Install the new airbag module and instrument panel. Please follow WSM procedures in section 501-20B.
- Install the instrument panel crossmember-to-airbag module bracket. See Figure 4.



10. Install the new A-Pillar trim panel clip onto the trim panel. See Figure 7.

NOTE: If the new A-Pillar trim panel clips are not equipped with a screw installed, re-use the screw from the original clip from step 3. Install the screw into the new clip by hand.

- Torque to 9 lb.in (1 Nm).




FIGURE 7

11. Install the LH and RH A-Pillar trim panels by aligning the attachment clips to the holes and snapping the new trim panel in place.
12. Package the replaced airbag module in the new part box and provide to the appropriate dealership personnel for part returns.



CERTAIN 2010 – 2011 MKZ VEHICLES – PASSENGER AIRBAG MODULE REPLACEMENT

OVERVIEW

Takata has determined that the propellant wafers in some airbag inflators may experience an alteration over time, which could potentially lead to an over-aggressive combustion in the event of a crash that requires airbag deployment. This potential condition could create excessive internal pressure when the airbag is deployed, which could result in the body of the inflator rupturing upon deployment increasing the risk of injury to occupants.

Dealers are to replace the passenger airbag module. The serial number from the new airbag module must be recorded on the repair order. Place the replaced airbag module into the packaging from the new part and provide to the appropriate dealership personnel for part returns.

NOTE: For vehicles that the airbags have deployed or that have other modifications preventing the recall repair from being completed, submit a VIN-specific request to the SSSC Web Contact Site prior to attempting a repair. Attach pictures of the vehicle's airbag modules to the request.

SERVICE PROCEDURE

NOTE: The following repair instructions only apply to 2010 – 2011 MKZ vehicles. Repair instructions are published in separate attachments for other vehicle lines included in this recall as parts become available for those vehicles.

NOTE: The parts used in this safety recall may physically appear to be identical, but they have differing operating characteristics. It is crucial that parts are not interchanged or substituted.



WARNING: Failure to follow the instructions and warnings in the Workshop Manual (WSM) may result in injury.

NOTE: If the Airbag Readiness light indicates no Supplemental Restraint System (SRS) faults are present, it is not necessary to follow the WSM SRS Depowering and Repowering steps. Turn the ignition to OFF and wait 1 minute, then it is safe to proceed with airbag inflator replacement.

NOTE: The ignition must remain OFF until this service procedure is completed.



1. Record the 13 character serial number of the new airbag module on the repair order. See Figure 1.




FIGURE 1

2. Remove the left hand and right hand A-Pillar trim panels. Reuse the LH and RH trim panels for this repair. See Figure 2.

- Grasp the trim panel approximately 5 inches from the top and pull downward toward the door, then rotate the panel inward toward the windshield to slide it off of the a-pillar clip.

NOTE: Do not bend or flex the trim panels during removal to avoid stress marks from occurring.

NOTE: MKZ A-Pillar trim is wrapped in fabric, be sure to protect the fabric from stains when removing.

NOTE: To view a video demonstration of this repair procedure, click the video icon. 



FIGURE 2



3. Remove and discard the top A-Pillar clip from the body. See Figure 3.




FIGURE 3

4. Remove the passenger airbag module. Please refer to Workshop Manual (WSM) procedures in section 501-20B.

- Remove the instrument panel crossmember-to-airbag module bracket. See Figure 4.
- Torque to 80 lb. in (9 Nm).




FIGURE 4



5. Install the new airbag module and instrument panel. Please follow WSM procedures in section 501-20B.

- Install the instrument panel crossmember-to-airbag module bracket. See Figure 4.

6. Install the new A-Pillar trim panel clip onto the trim panel. See Figure 5.

NOTE: If the new A-Pillar trim panel clips are not equipped with a screw installed, re-use the screw from the original clip from step 3. Install the screw into the new clip by hand.

- Torque to 9 lb.in (1 Nm).




FIGURE 5

7. Install the LH and RH A-Pillar trim panels by aligning the attachment clips to the holes and snapping the new trim panel in place.
8. Package the replaced airbag module in the new part box and provide to the appropriate dealership personnel for part returns.



TAKATA AIRBAG RECALL RENTAL VEHICLE POLICY

This rental vehicle policy only applies to the Takata airbag recalls 15S21, 16S26, 17S01, 17S42, 18S01, and 18S02.

New! Short-Term Rental: When Parts Are Available, Limited, or Temporarily Delayed

A majority of the Takata airbag recall repairs take less than one hour to complete. With proper dealer parts ordering and service appointment scheduling, rental vehicles should not be required to complete this recall repair. However, if a customer requests a rental vehicle while their vehicle is being repaired, dealers are pre-approved for up to 4 days of rental vehicle reimbursement. Prior approval for more than 4 rental days is required from the Special Service Support Center (SSSC) via the SSSC Web Contact Site and is not to exceed 7 days from the time the customer is notified that their vehicle is repaired. Refer to the short-term rental process on page 5.

NOTE: *This rental vehicle provision is an effort to make it easier for customers to have this recall repair completed on their vehicle and should only be offered when a customer requests a rental vehicle. Rental vehicles must not be used to help manage service department scheduling. To minimize the time that a customer is in a rental vehicle, dealers must order the required parts prior to the customer's appointment.*

New! Long-Term Rental: When Parts Are Not Available For Ordering

Rental vehicle reimbursement is available for customers that request a rental vehicle while waiting for parts to become available to complete the recall repair on their vehicle. If parts are not available for ordering, and the customer requests a rental vehicle, dealers must follow the long-term rental process starting on page 6.

NOTE: *Takata airbag recalls 16S26, 17S01, and 18S01 only affect the passenger side airbag in affected vehicles. If the customer does not use their vehicle's front passenger seat, the passenger side airbag will not deploy in a crash.*

As parts become available they will be shipped to dealers with customers in long term rental vehicles starting with vehicles in the highest risk zones first. Dealers must notify the customer the same day the repair is completed on their vehicle and request that they promptly return the rental vehicle. Rental days in excess of 7 days from the time the customer is notified that their vehicle is repaired will not be reimbursed.

Rental Vehicles

Rental vehicles may be supplied through dealership owned rental units, the Ford Courtesy Transportation Program, Ford Rent-A-Car, Lincoln Rent-A-Car, or third party rental agencies. When requesting a rate quote from a rental vehicle agency, ensure to ask for a monthly rate for long-term rentals, as this can be significantly lower than daily rates. If a customer has reserved a rental vehicle on their own or with the assistance of the Customer Relationship Center, the same rental guidelines and processes for requesting reimbursement apply.

Vehicle Make and Model Year Requirements

While it is a preference to put Ford customers in Ford rental vehicles and Lincoln customers in Lincoln rental vehicles, this is not always possible and is not a requirement for rental reimbursement under the Takata airbag recalls. Due to varying rental vehicle agency make and model inventory, Ford and Lincoln vehicles may not always be available so it is acceptable to use other make rental vehicles. There are no model year requirements for rental vehicle reimbursement.

New! Rental Vehicle Reimbursement Guidelines/National Takata Airbag Recall Rental Agreement

The following table lists the maximum per day and per month dollar amounts that will be reimbursed under this policy. In some cases, the cost per day limit may not be sufficient to cover all of the costs associated with a rental vehicle. It is the customer's responsibility to cover any additional costs above the cost per day and per month limits. If there is a unique customer circumstance that requires a rental vehicle with a higher per day/month allowance, dealers should submit a VIN specific request to the Special Service Support Center (SSSC) for special consideration.

Make of Recalled Vehicle	Rental Vehicle Reimbursement Cost Per Day Limit	Rental Vehicle Reimbursement Cost Per Month Limit
Ford	\$44 (including tax)	\$1,320 (including tax)
Mercury	\$44 (including tax)	\$1,320 (including tax)
Lincoln	\$55 (including tax)	\$1,650 (including tax)

To make it easier for dealers to locate vehicles within the rental vehicle reimbursement limits, Ford has established an agreement with Enterprise Rent-A-Car, Avis Budget Group, and Hertz to provide rental vehicles for customers affected by the Takata airbag recalls within the reimbursement limits listed above including tax. The only exclusion being the \$55 per day rate for Lincoln customers, which has only been agreed upon by Enterprise Rent-A-Car and Hertz.

- For Enterprise Rent-A-Car, Avis Budget Group, and Hertz, rental rates charged will be based on the make of the vehicle covered under the recall, rather than the type of vehicle rented to the customer (i.e. \$44 per day for Ford and Mercury owners and \$55 per day for Lincoln owners).*
- If a customer decides to rent a specialty vehicle such as a large SUV that is in excess of the cost per day/month reimbursement limits, the additional cost beyond the approved rate for the vehicle rented will be the customer's responsibility to pay.*
- Enterprise Rent-A-Car, Avis Budget Group, and Hertz do not guarantee that a Ford or Lincoln vehicle will be rented to all customers that own or request such vehicles.*
- Regardless of a dealer's tax status Enterprise Rent-A-Car, Avis Budget Group, and Hertz will bill dealers at the rates listed above.*
- The rates listed above may not be available at airport locations.*
- Ford does not endorse any particular rental vehicle provider.*

Enterprise Automated Rental Management System

If renting from Enterprise Rent-A-Car dealers are encouraged to schedule reservations through Enterprise's free Automated Rental Management System (ARMS®).

The ARMS® benefits to dealers are as follows:

- The ability to create and submit "real time" rental reservations online or through your CDK® or Reynolds & Reynolds® Dealership Management System to the local Enterprise branch.
- Reservations can be made same day or submitted in advance with anticipation of rental needs.
- Specific rental needs can be communicated in the reservation (e.g. full-size SUV desired, etc.).
- Authorize additional rental days when necessary.
- View and print rental invoices (after each rental event is completed).

Expenses Not Covered Under Rental Vehicle Reimbursement

Rental Vehicle Reimbursement does not cover the following expenses:

- Mileage charges
- Fuel charges
- Underage driver surcharge
- Insurance
- One way fees

NOTE: Some car insurance policies include rental vehicle insurance coverage so the purchase of additional insurance may not be required.

Rental Vehicle Documentation

Rental vehicle documentation must include the following:

- A rental invoice from a dealership or commercial rental agency
- Contract holder's name on the rental invoice
- Daily rental rate
- Proof of payment (for customer refund of rental)
- Completed Restricted Vehicle Use Agreement (for long term rentals)

Increased Ford Courtesy Transportation Program (FCTP) Guides

In order to support these customers, FCTP Program Headquarters will review increased guides requests above the existing maximum on a case by case basis to ensure coverage is sufficient. Dealers must submit their request to their sales operations manager in order to be considered.

New! Customer Waitlist

Dealers with customers on a waitlist for a rental vehicle are encouraged to work with their rental vehicle provider of choice. In most cases if a rental vehicle is not immediately available, rental vehicle providers are able to provide one to customers within 24 hours.

If using Ford Courtesy Transportation Program (FCTP) for rentals, dealers should contact their sales operations manager for consideration for additional FCTP units.

New! Rental Vehicles Paid By Customers

If a customer has obtained a rental vehicle on their own that is within the guidelines of this policy, they are eligible for a refund. The customer must provide the dealer with the rental documentation necessary to request rental reimbursement. Dealers must then follow the rental vehicle reimbursement process, including completion of the Restricted Vehicle Use Agreement by the customer, and provide a refund to the customer. Amounts above the cost per day/month limits will not be reimbursed.

New! Youthful Renter Surcharge

Drivers under the age of 25 may be subject to a youthful renter surcharge and additional insurance requirements. These additional fees are not eligible for rental vehicle reimbursement unless they fall within the cost per day/month limits. Youthful renter policies vary by rental vehicle provider and location. Contact the rental vehicle provider that the vehicle is being rented from for further details.

New! Storage of Customers Vehicles

A vehicle storage/upkeep allowance will not be provided to dealers under this program.

- For long-term rentals where parts will not be available for ordering, it is recommended that customers retain and store their vehicles. If a dealer would like to store a customer's vehicle as a service for their customers, this would be at the dealer's discretion, but a storage and upkeep allowance will not be provided.*
- For short-term rentals where parts are readily available or "limited" availability, dealers must retain the customer's vehicle so a repair can be completed as soon as the part arrives.*

New! Alternative Transportation

If a customer is unable or does not wish to rent a vehicle but still requires transportation, the rental reimbursement allowance can be used for alternative transportation. The same cost per day limits apply of \$44 per day for Ford and Mercury customers and \$55 per day for Lincoln customers. The dollar per day allowance can be cumulative across multiple rides per day (e.g. ride to work \$20 and ride home \$24).

- Alternative transportation reimbursement can be claimed for both short-term and long-term scenarios.*
- Any amount in excess of the cost per day limits will be the customer's responsibility.*
- The customer will need to pay up front and provide proof of payment to the dealer.*
- Dealers will then need to submit for reimbursement following the Rental Vehicle Reimbursement Process and then refund the customer.*

Examples of alternative transportation:

- Taxi*
- Public Transportation - Subway, Train, or Bus*
- Rideshare alternatives (Chariot, Uber, Lyft, etc.)*

New! Restricted Vehicle Use Agreement

Customers that are being placed into a long-term rental when parts are not currently available will need to complete a restricted vehicle use agreement. The purpose of this agreement is to signify that the customer will not continue to drive their recalled vehicle while waiting on parts since they have been provided alternate transportation. The customer can drive the recalled vehicle to a storage location and to the dealer for the recall repair to be completed. This form was recently updated but previous completed versions of this form are sufficient to fulfill this requirement. Completion of this document is not required if the dealer decides to store the customer's vehicle or for short-term rental scenarios since the vehicle will not be leaving the dealership until the recall repair has been completed.

New! Administrative Allowance

Dealers are authorized to claim an administrative allowance of \$25 for every *long-term* rental vehicle warranty claim submitted. This administrative allowance can be claimed every 30 days, at which time a new approval code needs to be requested. Reference the dealer bulletin claims preparation and submission section for further details.

Because short-term rentals are pre-approved for up to 4 days, short-term rental claims are not eligible for the \$25 administrative allowance.

New! Rental Vehicle Reimbursement Process:

1. *Customer contacts the dealer and requests a rental vehicle*
2. Check OASIS to confirm the vehicle is involved in one of the Takata airbag recalls: 15S21, 16S26, 17S01, 17S42, 18S01, or 18S02.
3. *Refer to the dealer bulletin to determine the parts availability status.*

Is the parts status “Available” or “Limited” for the recalled vehicle?

Yes: *Proceed to the Short-Term rental process*

No: *Proceed to the Long-Term rental process*

New! Short-Term Rental Process

1. *In the FSA dealer bulletin is the parts status “Available” for the recalled vehicle?*
Yes – Proceed to step 2.
No – For a “Limited” parts status submit a contact to the SSSC under the FSA program number (i.e.15S21,16S26,17S01,17S42,18S01,18S02). The SSSC will place a part order for the vehicle and provide an approval code for the number of expected rental days required to receive the part and complete the repair. Proceed to step 3.
2. *Dealers are pre-approved for up to 4 rental days to complete the repair when the parts status is “Available”.*
3. *Arrange for a rental vehicle for the customer through either the dealership's rental vehicle fleet or an outside rental vehicle agency. If using Enterprise, it is recommended that the reservation be made through ARMS®.*
4. *Customer completes all required rental vehicle paperwork and leaves with the rental vehicle.*
 - *Rental vehicle agencies may offer pick-up and delivery.*
5. *Dealer retains the customer's vehicle so the repair can be completed as soon as parts arrive.*
6. *If additional rental days are required, submit a VIN specific approval contact to the SSSC under the FSA program number (i.e.15S21,16S26,17S01,17S42,18S01,18S02).*
7. *Dealer completes the repair the same day the part arrives.*
8. *Dealers must notify the customer the same day the repair is completed.*
9. *Customer promptly returns the rental vehicle. Rental days in excess of 7 days from the time the customer is notified that their vehicle is repaired will not be reimbursed.*

New! Long-Term Rental Process

1. Arrange for a rental vehicle for the customer through either the dealership's rental vehicle fleet or an outside rental vehicle agency. If using Enterprise, it is recommended that the reservation be made through ARMS®.
2. Customer completes the Restricted Vehicle Use Agreement.
3. *Customer drives their vehicle to their home or another storage location of their choice.*
4. Customer completes all required rental vehicle paperwork.
5. *Customer picks up the rental vehicle from the rental vehicle provider.*
 - *Rental vehicle agencies may offer pick-up and delivery.*
6. Submit a VIN specific web contact to the Special Service Support Center (SSSC) under the appropriate rental program as listed below:
 - 18A01 for 16S26
 - 18A02 for 17S01
 - 18A03 for 18S01
 - 18A04 for 17S42

(long-term rentals do not apply to 18S02 and 15S21 because parts are readily available)


The SSSC Web Contact Site can be accessed through the Professional Technician Society (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

7. Attach the completed Restricted Vehicle Use Agreement to the SSSC contact.
8. If the vehicle is involved in the recall and does not have parts available, the SSSC will provide an approval code to use on the warranty claim for the long-term rental.
9. For warranty payment purposes and to continue long-term rental vehicle reimbursement dealers will need to re-contact the SSSC under a new contact every 30 days to receive a new approval code. This can be managed two different ways depending on dealership preference:
 - **Option 1:** Close out the R.O. every 30 days and open a new R.O. prior to contacting the SSSC under a new contact.
 - **Option 2:** Leave the current R.O. open and add another line to the R.O. for the next month's rental prior to contacting the SSSC under a new contact.


NOTE: A new function to the SSSC web tracker has been added so contacts approaching a long-term rental renewal date (30 days old) will turn red.

10. *As parts become available they will automatically be shipped to dealers with customers in long-term rental vehicles starting with vehicles in the highest risk zones first. The vehicle's VIN will be printed on the part to identify which vehicle the part should be used to repair.*
11. *Dealers should contact customers currently in a long-term rental vehicle if the parts status for their affected vehicle is listed as "Limited" or "Available" in the Parts Availability Matrix. Request the vehicle owner drop off their recalled vehicle at the dealership as soon as possible. This will enable dealers to complete the repair as soon as the parts arrive.*
12. *Dealers must complete the recall repair as soon as parts are available and the customer has brought their vehicle to the dealership.*
13. *Dealers must notify the customer that their vehicle is ready for pick-up the same-day that the recall repair is completed. Customers should pick up their repaired vehicle and return the rental vehicle promptly. Rental days in excess of 7 days from the time the customer is notified that their vehicle is repaired will not be reimbursed.*

TAKATA AIRBAG RECALL SHORT-TERM RENTAL PROCESS



TAKATA AIRBAG RECALL LONG-TERM RENTAL PROCESS



Safety Recall 16S26

Certain 2005-2006 Ford GT, 2005-2011 Mustang, 2006-2011 Fusion and Milan, 2006 Zephyr, 2007-2011 MKZ, 2007-2010 Edge and MKX, and 2007-2011 Ranger Vehicles
Passenger Airbag Inflator Replacement

DEALER Q & A**Q1. How will I know when parts are available to order for vehicles affected by this recall?**

A. Dealers are encouraged to refer to the [Takata Airbag Inflator Recall Information for Dealers](#) document on the FMC dealer homepage for the latest parts status for all Takata airbag recalls.

Q2. Why is it taking so long to get parts for this recall?

A. To support this recall new parts had to be designed and rigorously tested. In addition, multiple vehicle manufacturers are affected by the Takata airbag inflator recalls and use the same suppliers for replacement recall parts. This has caused a high demand for airbag inflator parts industry wide.

Q3. 14S28 has previously been performed on a 2005-2006 Ford GT. Why is the same vehicle also affected by 16S26?

A. Safety Recall 16S26 utilizes a redesigned part for a final repair. 14S28 was an interim repair using a “like for like” part that must be replaced under safety recall 16S26.

Q4. Can the airbag inflator part number provided in 14S28 be used to complete repairs on 2005-2006 Ford GT vehicles under 16S26?

A. No, the part used in 14S28 are not equivalent. Use only the part number listed in 16S26 (or latest level replacements) for this final repair.

Q5. Are rental vehicles available for customers?

A. Yes, if a customer requests a rental vehicle. Refer to the Takata Airbag Recall Rental Vehicle Policy attachment for full details.

Q6. Why is a core charge applied to the parts for this program when that has not been the case on previous Takata recalls?

A. This is an effort to make it easier to do business with Ford and reduce the amount of paperwork required for dealers.

NOTE: All previously published Takata safety recalls will continue to use the FCS-700 tag process (15S21, 17S42 and 18S02).

Q7. A vehicle on my dealer’s FSA VIN list has deployed, modified, or missing airbags. Can the vehicle be removed from my dealer’s FSA VIN list?

A. Vehicles that have deployed, missing, or modified airbags need to be reviewed by the Special Service Support Center (SSSC) to ensure the potential risk for airbag inflator rupture is no longer present. Dealers should submit a VIN-specific web contact request to the SSSC with pictures showing the airbag’s state and vehicle’s VIN plate so a determination can be made.

Safety Recall 16S26

Certain 2005-2006 Ford GT, 2005-2011 Mustang, 2006-2011 Fusion and Milan, 2006 Zephyr, 2007-2011 MKZ, 2007-2010 Edge and MKX, and 2007-2011 Ranger Vehicles
Passenger Airbag Inflator Replacement

Q8. Can my Dealership use Quick Lane bays and Technicians to complete this recall?

- A. At the dealer's discretion, dealers with Quick Lanes may now use Quick Lane service bays and Quick Lane technicians to perform **Takata Airbag Recalls**.
- Claim processing, hazardous material handling and parts returns **MUST** be processed through the main dealership's warranty submission process and parts department.
 - No other warranty or recall repairs are allowed at Quick Lanes at this time.

Q9. A Ford GT customer is hesitant to bring their vehicle to the dealer, what should I do?

- A. Dealers are authorized to claim up to a maximum combined value of \$200 to provide unique services to Ford GT owners under this recall. Examples of potential services include:
- Technician travel to vehicle location for remote repair
 - Vehicle transportation (towing/flatbed) to dealership
 - Vehicle re-delivery to the owner's location after repairs have been completed
 - Ford and Lincoln Dealerships are authorized to claim the special handling allowance.

In some cases, \$200 may not be sufficient to tow the vehicle to the dealership and redeliver to the customer. Dealers are encouraged to consider remote repairs at the vehicles location in these scenarios.

Q10. Will completed surveys count towards my Customer Viewpoint (CVP) score? Are the scores included in my Ford Commitment Plan (FCP) calculations?

- A. All vehicles affected by this recall are over the 5 years/75,000 scoring criteria, which makes them ineligible for CVP Score and FCP calculations. Completed surveys will be reported as "Recall Over 5/75" and that means they are NOT included in their CVP/FCP scores.

QUESTIONS & ASSISTANCE

For additional questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician Society (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

TAKATA AIRBAG RECALL RENTAL VEHICLE POLICY

This rental vehicle policy only applies to the Takata airbag recalls 15S21, 16S26, 17S01, 17S42, 18S01, and 18S02.

New! RENTAL POLICY OVERVIEW

NOTE: Due to increased parts availability, effective December 24, 2018, no additional long-term rentals will be approved. Back-dated rental approvals will not be approved effective December 17, 2018. Refer to the Dealer Bulletin for details.

Short-term rentals will remain available if a customer requests a rental vehicle while their vehicle is being repaired. The short-term rental vehicle program is an effort to make it easier for customers to have this recall repair completed and should only be offered when a customer requests a rental vehicle. Rental vehicles must not be used to help manage service department scheduling.

If a customer requests a rental vehicle while their vehicle is being repaired, refer to the flow chart on the last page of this attachment for the process for requesting rental vehicle reimbursement. Dealers must:

- order required parts prior to a customer's appointment.
- retain customers' vehicles until the recall repair is completed and the rental vehicle is returned.
- notify the customer the same day that the repair is completed on their vehicle and request that they promptly return the rental vehicle. Rentals exceeding 7 days from the date the customer is notified that their vehicle is repaired, will not be reimbursed.

If the customer has paid for a rental vehicle or alternative transportation for the purpose of this recall, they are eligible for reimbursement within the guidelines outlined in the Takata Airbag Recall Rental Vehicle Policy. Dealers must follow the same process for claiming rental vehicle reimbursement and then refund the customer.

RENTAL VEHICLE SOURCE

Rental vehicles may be supplied through dealership owned rental units, the Ford Courtesy Transportation Program, Ford Rent-A-Car, Lincoln Rent-A-Car, or third party rental agencies. If a customer has reserved a rental vehicle on their own or with the assistance of the Customer Relationship Center, the same rental guidelines and processes for requesting reimbursement apply.

VEHICLE MAKE AND MODEL YEAR REQUIREMENTS

While it is a preference to put Ford customers in Ford rental vehicles and Lincoln customers in Lincoln rental vehicles, this is not always possible and is not a requirement for rental reimbursement under the Takata airbag recalls. Due to varying rental vehicle agency make and model inventory, Ford and Lincoln vehicles may not always be available so it is acceptable to use other make rental vehicles. There are no model year requirements for rental vehicle reimbursement.

RENTAL REIMBURSEMENT GUIDELINES / NATIONAL TAKATA RECALL RENTAL AGREEMENT

The following table lists the maximum per day and per month dollar amounts that will be reimbursed under this policy. In some cases, the cost per day limit may not be sufficient to cover all of the costs associated with a rental vehicle. It is the customer's responsibility to cover any additional costs above the cost per day and per month limits. If there is a unique customer circumstance that requires a rental vehicle with a higher per day/month allowance, dealers should submit a VIN specific request to the Special Service Support Center (SSSC) for special consideration.

Make of Recalled Vehicle	Rental Vehicle Reimbursement Cost Per Day Limit	Rental Vehicle Reimbursement Cost Per Month Limit
Ford	\$44 (including tax)	\$1,320 (including tax)
Mercury	\$44 (including tax)	\$1,320 (including tax)
Lincoln	\$55 (including tax)	\$1,650 (including tax)

To make it easier for dealers to locate vehicles within the rental vehicle reimbursement limits, Ford has established an agreement with Enterprise Rent-A-Car, Avis Budget Group, and Hertz to provide rental vehicles for customers affected by the Takata airbag recalls within the reimbursement limits listed above including tax. The only exclusion being the \$55 per day rate for Lincoln customers, which has only been agreed upon by Enterprise Rent-A-Car and Hertz.

- For Enterprise Rent-A-Car, Avis Budget Group, and Hertz, rental rates charged will be based on the make of the vehicle covered under the recall, rather than the type of vehicle rented to the customer (i.e. \$44 per day for Ford and Mercury owners and \$55 per day for Lincoln owners).
- If a customer decides to rent a specialty vehicle such as a large SUV that is in excess of the cost per day/month reimbursement limits, the additional cost beyond the approved rate for the vehicle rented will be the customer's responsibility to pay.
- Enterprise Rent-A-Car, Avis Budget Group, and Hertz do not guarantee that a Ford or Lincoln vehicle will be rented to all customers that own or request such vehicles.
- Regardless of a dealer's tax status Enterprise Rent-A-Car, Avis Budget Group, and Hertz will bill dealers at the rates listed above.
- The rates listed above may not be available at airport locations.
- Ford does not endorse any particular rental vehicle provider.

ENTERPRISE AUTOMATED RENTAL MANAGEMENT SYSTEM

If renting from Enterprise Rent-A-Car dealers are encouraged to schedule reservations through Enterprise's free Automated Rental Management System (ARMS®).

The ARMS® benefits to dealers are as follows:

- The ability to create and submit "real time" rental reservations online or through your CDK® or Reynolds & Reynolds® Dealership Management System to the local Enterprise branch.
- Reservations can be made same day or submitted in advance with anticipation of rental needs.
- Specific rental needs can be communicated in the reservation (e.g. full-size SUV desired, etc.).
- Authorize additional rental days when necessary.
- View and print rental invoices online, immediately after each rental event is completed.

EXPENSES NOT COVERED UNDER RENTAL VEHICLE REIMBURSEMENT

Rental Vehicle Reimbursement does not cover the following expenses:

- Mileage charges
- Fuel charges
- Underage driver surcharge
- Insurance
- One way fees

NOTE: Some car insurance policies include rental vehicle insurance coverage so the purchase of additional insurance may not be required.

RENTAL VEHICLE DOCUMENTATION

Rental vehicle documentation must include the following:

- A rental invoice from a dealership or commercial rental agency
- Contract holder's name on the rental invoice
- Daily rental rate
- Proof of payment (for customer refund of rental)

ADMINISTRATIVE ALLOWANCE

Dealers are only eligible to claim a \$25 administrative fee for:

- Any rental claims under long-term rental program 18A01, 18A02, 18A03, or 18A04 that were submitted after June 13, 2018. This includes long-term rental claims that were originally approved by the SSSC after May 12, 2018 but processed for warranty payment after June 13, 2018.
- Any rental claims with an RO open date after September 23, 2018 that require more than 4 rental days.

CUSTOMER WAITLIST

Dealers with customers on a waitlist for a rental vehicle are encouraged to work with their rental vehicle provider of choice. In most cases if a rental vehicle is not immediately available, rental vehicle providers are able to provide one to customers within 24 hours.

If using Ford Courtesy Transportation Program (FCTP) for rentals, dealers should contact their sales operations manager for consideration for additional FCTP units.

YOUTHFUL RENTER SURCHARGE

Drivers under the age of 25 may be subject to a youthful renter surcharge and additional insurance requirements. These additional fees are not eligible for rental vehicle reimbursement unless they fall within the cost per day/month limits. Youthful renter policies vary by rental vehicle provider and location. Contact the rental vehicle provider that the vehicle is being rented from for further details.

INCREASED FORD COURTESY TRANSPORTATION PROGRAM (FCTP) GUIDES

In order to support these customers, FCTP Program Headquarters will review increased guides requests above the existing maximum on a case by case basis to ensure coverage is sufficient. Dealers must submit their request to their sales operations manager in order to be considered.

RENTAL VEHICLES PAID BY CUSTOMERS

If a customer has obtained a rental vehicle on their own that is within the guidelines of this policy, they are eligible for a refund. The customer must provide the dealer with the rental documentation necessary to request rental reimbursement. Dealers must then follow the rental vehicle reimbursement process and provide a refund to the customer. Amounts above the cost per day/month limits will not be reimbursed.

ALTERNATIVE TRANSPORTATION

If a customer is unable or does not wish to rent a vehicle but still requires transportation, the rental reimbursement allowance can be used for alternative transportation. The same cost per day limits apply of \$44 per day for Ford and Mercury customers and \$55 per day for Lincoln customers. The dollar per day allowance can be cumulative across multiple rides per day (e.g. ride to work \$20 and ride home \$24).

- Any amount in excess of the cost per day limits will be the customer's responsibility.
- The customer will need to pay up front and provide proof of payment to the dealer.
- Dealers will then need to submit for reimbursement following the Rental Vehicle Reimbursement Process and then refund the customer.

Examples of alternative transportation:

- Taxi
- Public Transportation - Subway, Train, or Bus
- Rideshare alternatives (Chariot, Uber, Lyft, etc.)

STORAGE OF CUSTOMERS VEHICLES

For all new rental requests, dealers should retain customers' vehicles until the recall repair is completed and the rental vehicle is returned. This will allow for the vehicle to be repaired as soon as the part arrives and for the rental vehicle to be promptly returned. Due to the vehicle storage duration only anticipated to be short term, a vehicle storage/upkeep allowance will not be provided to dealers under this program.

Customers that were previously advised to retain and store their vehicles should drop their vehicles off at their dealer so the vehicle can be repaired as soon as the part arrives. The Customer Relationship Center will be contacting customers currently in long-term rental vehicles to advise them to drop off their recalled vehicle at the dealer so the repair can be made as soon as the part arrives. Customers will be responsible for all vehicle upkeep during the time the vehicle is being stored.

RESTRICTED VEHICLE USE AGREEMENT

The Restricted Vehicle Use Agreement is no longer required for new rental requests due to the recalled vehicle remaining at the dealership until repaired.

TAKATA AIRBAG RECALL RENTAL VEHICLE PROCESS

