

## View Message

|                |   |    |      |                   |    |    |      |
|----------------|---|----|------|-------------------|----|----|------|
| <b>Sent on</b> | 07  | 09 | 2016 | <b>Expires on</b> | 10 | 06 | 2016 |
| <b>From</b>    | Campaign Administration   |    |      |                   |    |    |      |
| <b>Subject</b> | Stop Sale/Safety Recall: 2016 Civic 2-Door Rear Marker Light Is Not Working |    |      |                   |    |    |      |

DATE: July 9, 2016

TO: All Honda Sales, Service & Parts Managers and Personnel

FROM: Campaign Administration

RE: Stop Sale/Safety Recall: 2016 Civic 2-Door Rear Marker Light Is Not Working

Yesterday, July 8, 2016, American Honda Motor Co., Inc. notified NHTSA of a **Safety Recall** affecting a small number of units of model year 2016 Civic 2-Door to inspect and, if needed, replace any of the two rear marker light taillight assemblies that does not illuminate. **Any new or used units in dealer stock must be inspected and if needed repaired per service bulletin, 16-058 Safety Recall: Rear Side Marker Light Is Not Working, prior to sale. Refer to your eResponsibility report or VIN inquiry to determine which units in your inventory are affected.** American Honda expects to begin client notification in early August, 2016.

Note: Some vehicles affected by this campaign may be in your new or used vehicle inventory. Failure to inspect and, if needed repair, a vehicle subject to a recall or campaign may subject your dealership to claims or lawsuits from the customer or anyone else harmed as a result of such failure. In addition, state law may provide American Honda with the right to seek indemnification in any such claim or lawsuit.

#### Basic Problem

Certain taillight assemblies may have a LED side marker light that does not illuminate due to damage during manufacturing transit making it inoperable and therefore not compliant with FMVSS No. 108; Lamps, reflective devices, and associated equipment. Affected vehicles with an inoperative rear side marker light have decreased visibility in certain traffic conditions, which may increase the risk of a crash.

#### Campaign Information

Service bulletin 16-058, has been posted to the Service Information System as of July 9, 2016, and includes, inspection and repair, parts, and warranty information related to the recall campaign.

#### Parts Information

American Honda expects very few vehicles will have damaged LED Marker Lights and therefore few will require taillight assembly replacement. Replacement parts for 16-058 should be ordered after the LED Marker Lights are inspected and are confirmed to not illuminate. Replaced parts will be on warranty call in to validate damage to LED.

#### Tools, Warranty, and Inspection/Repair Information

No special tools are needed to perform the inspection. Warranty and inspection/repair information is detailed in service bulletin 16-058.

#### Client Notification

American Honda expects to complete initial client notification by early August, 2016.

As always, please be sure to check VIN status inquiry to determine if a particular VIN is affected by this recall.

Click [here](#) for a copy of bulletin 16-058.