



MERCEDES-BENZ USA, LLC 303 Perimeter Center North, Suite 202 Atlanta, GA, 30346 Phone: (770) 705-0600 Fax: (770) 705-0117

newschannel update

то: Mercedes-Benz Dealer Principals, General	FROM: Thomas Brunner, Department Manager,	
Managers, Sales Managers, Service Managers, Parts	Vehicle Compliance and Analysis, Engineering	
Managers	Services	
RE: Recall Campaign 2016120004		
MY 2016-2017 Model 166, 292 (GLE, GLE-Coupe,	DATE: December 22, 2016	
GLS) OCS SCN Coding		

IMPORTANT RECALL LAUNCH INFORMATION

Please see the attached document for the subject new recall campaign and launch information.





December 22, 2016



Campaign No.: Occupant Classification System (OCS) SCN Coding 2016120004 This is to notify you of the launch of a Recall Campaign to update the SCN coding on 47,797 MY16-17 GLE-Class/GLS-Class SUVs (166), and GLE-Coupe (292) vehicles. Please review the recall information below. The recall will be launched on December 22, 2016 and all affected VINs will be flagged in VMI. **Background** Daimler AG ('DAG') the manufacturer of Mercedes-Benz passenger vehicles, has determined that on certain GLE/GL/GLS (166 platform) and GLE Coupe (292 platform) vehicles, the calibration of the front passenger seat Occupant Classification System (OCS) may not detect Issue a very light occupant if the occupant is sitting on the edge of the seat and remains stationary for a long period of time. Consequently, there is a possibility that the occupant may be reclassified as a child seat and the passenger-side frontal airbag may be deactivated. MBUSA will conduct a voluntary recall. An authorized Mercedes-Benz dealer, will adapt the What We're Doing proper coding of the control unit on the affected vehicles. **Parts** No parts are needed - recoding the control unit is required **Vehicles Affected** Vehicle Model Year 2016-2017 GLE-Class, GL & GLS-Class SUVs, GLE-Coupe Vehicle Models **Vehicle Populations** 47,797 **Total Recall Population** Total Vehicles in Dealer Inventory | 1123 (AOMs will forward the VIN list of vehicles in dealer inventory) Given this notice, it is a violation of Federal law for a dealer to sell or lease any new Model Year 2016-2017 GLE-Class, GL-Class, GLS-Class, and GLE-Coupe Class covered by this notification in dealer inventory until the vehicle has been repaired. Dealers are advised to check new vehicle inventory for recall campaign applicability in VMI, and repair immediately. Once the repair is complete, the vehicle may be sold or leased. **Dealer Notification (NCU)** Documentation pertaining to this recall will be received by dealers in December 22, 2016 NetStar and Star TekInfo on the following date: Next Steps/Notes Owner notification letter timeline Customer notification letters will be mailed in early January 2017. AOMs - Please check the VIN list, you may have a dealer that has a vehicle affected by this AOMS/SOMS recall in inventory.

While we regret any inconvenience this may cause, MBUSA is determined to maintain a high level of vehicle quality and customer satisfaction. Please refer all customer inquiries to the Customer Assistance Center at 1-800-FOR-MERCEDES. Please contact Allen Ambulo (x2579) or me with any questions.

Recall Campaign Bulletin

Recall Campaign Bulletin



Campaign No. 2016120004, December 2016

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: Models 166, 292; Model Year 2016-2017

Recode Occupant Classification System (OCS) Control Module

On certain ML/GL/GLE/GLS (166 platform) and GLE Coupe (292 platform) vehicles, the calibration of the front passenger seat Occupant Classification System (OCS) may not detect a very light occupant if the occupant is sitting on the edge of the seat and remains stationary for a long period of time. Consequently, there is a possibility that the occupant may be classified as a child seat and the passenger side frontal airbag may be deactivated. An authorized Mercedes-Benz dealer will recode the Occupant Classification System (OCS) control module.

Prior to performing this Recall Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Recall Campaign bulletin and follow the repair procedure exactly as described.

Please note that Recall Campaigns **do not expire** and may also be performed on a vehicle with a vehicle status indicator.

Approximately 47,797 vehicles are involved.

Order No. T-RC-2016120004

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Procedure

i Note

- Use following versions of XENTRY Diagnostics/XENTRY DAS: Use BD/DVD (09/2016) + add-on 6820 and 6849 or BD/DVD (12/2016) + add-on 6819 and 6848 or higher.
- Follow the steps exactly as described in DAS/Xentry.
- Connect battery charger (battery voltage >12.5V).
- Ensure all electrical consumers are switched-off.
- In the event of software/SCN update issues, contact Star Diagnosis User Help Desk. Please refer to the "pre-call" check list before contacting UHD
- Refer to Star Diagnosis System (SDS) Best Practices Guide.
- Perform SCN coding in Weight Sensing System (WSS) control module: Quick test view Control unit N110 Weight Sensing System (WSS) Adaptations Control unit update SCN coding.
- 2. Follow on-screen instructions.
- 3. Disconnect XENTRY/DAS.

i Note:

The following allowable labor operation should be used when submitting a warranty claim for this repair:

Warranty Information

Operation: Connect/disconnect battery charger (02-5058)

Star Diagnosis System (SDS), Connect/disconnect (02-4762) Perform SCN coding in Weight Sensing System (WSS) (02-9446)

Damage Code	Operation Number	Labor Time (hrs.)
91 902 48 8	02-5058	0.1
	02-4762	0.1
	02-9446	0.1

iNote

Operation Number labor times are subject to change