

[Next Unread Message](#)

View Message

Sent on	10	06	2017	Expires on	11	06	2017
From	Parts and Service Division						
Subject	2011-2016 Odyssey SB# 16-108 Repair Procedure NEW Information						

PRIORITY NOTIFICATION

To: All Honda Service and Parts Managers
From: Service Engineering
RE: 2011-2016 Odyssey Service Bulletin 16-108 Repair Procedure NEW Information

This message is solely directed to Honda dealership personnel; please handle accordingly.

Dealer,

American Honda (AHM) issued Service Bulletin #16-108 in support of the Odyssey “Second Row (Both Outer) Seats” Campaign. In the REPAIR PROCEDURE section, two steps have been added.

When working on a vehicle remove any child or booster seats that are installed in the second row seats and place them in the cargo area for the customer to reinstall.

When reinstalling the second row seats, make sure they are installed and latched (in either the inner position (standard mode) or outer position (wide mode)).

Please review the [bulletin](#) for detail of the added information.

Thank you