

## **RECALL CAMPAIGN BULLETIN**

Reference:

NTB16-053b

Date: July 15, 2016

## VOLUNTARY SAFETY RECALL CAMPAIGN 2013-2016 SENTRA OCCUPANT CLASSIFICATION SYSTEM REPROGRAMMING SEATBELT BUCKLE BRACKET INSTALLATION

This bulletin has been amended. An alternate method of performing the reprogramming procedures in this bulletin has been added. No other changes have been made. Please discard all previous versions of this bulletin.

CAMPAIGN ID #: R1608

**NHTSA #:** 16V-242

APPLIED VEHICLE: 2013-2016 Sentra (B17)

#### Check Service COMM to confirm campaign eligibility.

#### INTRODUCTION

Nissan is conducting a Voluntary Safety Recall Campaign on certain specific Nissan Vehicles, listed in APPLIED VEHICLES above, to install a seatbelt buckle bracket and reprogram the Airbag Diagnostic Sensor Unit and Occupant Classification System (OCS) control unit. This service will be performed at no cost to the customer for parts or labor.

#### **IDENTIFICATION NUMBER**

Nissan has assigned identification number R1608 to this campaign. This number must appear on all communications and documentation of any nature dealing with this campaign.

#### DEALER RESPONSIBILITY

It is the dealer's responsibility to check Service Comm for the campaign status on each vehicle falling within the range of this voluntary recall which for any reason enters the service department. This includes vehicles purchased from private parties or presented by transient (tourist) owners and vehicles in a dealer's inventory. Federal law requires that new vehicles in dealer inventory which are the subject of a safety recall must be corrected prior to sale. Failure to do so can result in civil penalties by the National Highway Traffic Safety Administration. While federal law applies only to new vehicles, Nissan strongly encourages dealers to correct any used vehicles in their inventory before they are retailed.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

#### **CAMPAIGN INFORMATION**

#### Front Passenger Air Bag Status Light


Performing the procedures in the bulletin (campaign R1608) changes the operation of the passenger air bag status light.

• After performing this campaign, the passenger air bag status light will be ON (illuminated) when the front passenger seat is empty.

#### Air Bag Warning Light

This campaign does not change the operation of the air bag warning light.






• One J-51594 OCS reprogramming cable has been supplied to each dealer. Additional cables can be obtained from Tech-Mate at 1-800-662-2001.







#### NOTE:

- The Service Procedure in this bulletin uses <u>CONSULT-III plus</u> to reprogram the Airbag Diagnostic Sensor Unit and the Occupant Classification System (OCS) control unit.
- For an alternate reprogramming method, refer to **ALTERNATIVE METHOD TO PERFORM REPROGRAMMING** starting on page 22 of this bulletin. This alternate procedure allows the reprograming in this bulletin using BOSCH MTS 6513 Special Tool.

#### SERVICE PROCEDURE

#### Seatbelt Buckle Bracket Installation

1. Tilt both the driver's and passenger seats all the way forward, and then move both seats as far forward as possible.



Figure 1

- 2. Unbolt the passenger seat from the floorboard.
  - Remove the rear bolts first and then the front.
  - Four T50 Torx bolts; two front and two rear.
  - Rear bolts shown in Figure 2. Front bolts not shown.




Figure 2

- 3. Tilt the passenger seat rearward so that the harnesses underneath can be accessed.
- 4. Unclip the harness from the seat bottom at the two locations shown in Figure 3.

# IMPORTANT: Do not disconnect any of the harness connectors under the seat.




Figure 3

- 5. Return the seat to an upright position (seat rails flat on floor).
- 6. Gently slide the seat all the way to the rear so that the seatbelt buckle bolt can be reached.
- 7. Remove the seatbelt buckle bolt.




Figure 4



Figure 5




Figure 6

 Remove the seat cushion outer finisher (LH) with an appropriate tool.

9. Remove the seatback bolt shown in Figure 6.

NOTE: This bolt will not be reused.

- 10. Remove the seatbelt buckle bolt retaining clip and bolt spacer from the seatbelt buckle.
  - Discard the bolt retaining clip and bolt spacer.




Figure 7

- 11. Install the seatbelt buckle bracket onto the backside of the seatbelt buckle as shown in Figure 8.
  - Confirm that wave washer is between seatbelt buckle and bolt where shown in Figure 8.
  - Position bracket notch as shown in Figure 9.
- 12. Attach the seatbelt buckle to the seat, but <u>do not</u> tighten.

**IMPORTANT:** Start the seat belt buckle bolt by hand.


13. Place the spacer between the seatbelt bracket and the seatback and then install the new seatback bolt.

**IMPORTANT:** Start the seatback bolt by hand.

- 14. Torque the seatback bolt; seat belt buckle bolt will be tightened later in the procedure.
  - Seat back bolt torque: 46.5 N•m (4.74 Kg-m, 34 ft-lb.)



Figure 8




6

15. Slide the seat cushion outer finisher (LH) past the loose seatbelt buckle and then snap it into place.

**NOTE:** Align and attach the forward metal clip of the seat cushion outer finisher (LH) first (Figure 11), and then the remaining plastic clips.

- 16. Torque the seatbelt buckle bolt (Figure 10).
  - Bolt torque: 49 N•m (5.0 Kg-m, 36 ftlb.)







Figure 11





17. Reattach harnesses unclipped in step 4.

- 18. Gently move the passenger seat into its original position.
  - Align the guide pin on the left rear corner of the seat track (Figure 13) and insert into guide pin hole.


19. Install all four Torx seat track bolts and torque them in the pattern shown in

Bolt torque: 40 N•m (4.1 Kg-m, 30 ft-

Figure 14.

lb.)

•








Figure 14

- 20. Slide the front passenger seat completely forward and completely rearward a few times to confirm it is operating correctly.
- 21. Return both front seats to their original positions.

#### **CAUTION:**

- Connect the GR8 to the 12V battery and select ECM Power Supply Mode. If the vehicle battery voltage goes below <u>12.0V or above 15.5V</u> during reprogramming, <u>the Airbag Diagnostic Sensor Unit (ADSU) may be</u> <u>damaged</u>.
- Be sure to turn OFF all vehicle electrical loads.
  If a vehicle electrical load remains ON, <u>the ADSU may be damaged</u>.
- Be sure to connect the AC Adapter.
  If the CONSULT PC battery voltage drops during reprogramming, the process will be interrupted and <u>the ADSU may be damaged</u>.
- 1. Make sure ASIST has been synchronized to the <u>current date</u> and all updates have been installed.


**NOTE:** The PC automatically gets applicable reprogramming software during ASIST synchronization.

- 2. Open the vehicle hood, connect GR8 and set to ECM Power Supply Mode.
- 3. Turn the ignition ON (engine OFF / not Ready).
- 4. Turn hazards ON.
- 5. Connect the CONSULT-III plus VI (C-III plus VI) to the vehicle.
- 6. Connect the VI to the CONSULT PC with a USB cable.
- 7. Start the CONSULT PC, open ASIST and then select "**R1608 & R1609 ACU Reprogram**" on ASIST under Specialty Tools (Figure 15).




#### Figure 15

- 8. Read the on screen CAUTION statement before proceeding.
- 9. Select Accept.













10. Select VI-2 from the drop down list and then Next.

11. Select Reprogramming.





12. Select AIRBAG.

13. Is the screen in Figure 20 displayed?

NO: Proceed to step 14.

YES:

- a. Select **End** and discontinue airbag reprogramming.
- b. Proceed to OCS Control Unit Reprogram.

NISSAN			SHIFT_the way you move
ERROR			
This ECU part is not su	pporte	ed for this application.	
VIN		1N4AA6AP9GC375268	
Software Version		R7_2050H.P14	
ECU Serial Number		AE4RB163245875	
ECU Part Number		988204RB0A	
		End	



- 14. Confirm that the Battery Voltage is between 12.0V and 15.5V.
  - If the Battery Voltage is not between12.0V and 15.5V, resolve before proceeding.
- 15. Select Start.




Figure 21

- **REPROGRAMMING PROGRESS** screen will be displayed (Figure 22).
- Reprogram will take approximately 3 • minutes.
- Once the reprogramming has finished • the screen in Figure 23 will be displayed.
- **WARNING:** Airbag control unit • damage may occur if reprogramming is interrupted.




Figure 22

- 16. Confirm that the "Software Version(Before)" and "Software Version(After)" are different.
- 17. Select End.

NISSAN		SHIFT_the way you move
REPRO/PROGRAMMING CO	OMPLETE	
Battery Voltage	: 12.553	
VIN	: 3N1AB7AP7GY208589	
Software Version(Before)	RCN7L42L3306	
Software Version(After)	: RCN7L42L3307	
ECU Serial Number(Before)	: AE3YU15Y10576F	
ECU Serial Number(After)	: AE3YU15Y10576F	
ECU Part Number(Before)	: 98820-3YU0A	
ECU Part Number(After)	98820-3YU0A	
End	Step 17	

Figure 23

18. Save the confirmation page, print and attach it to the repair order.

Leave the ignition ON and proceed to **OCS** 

Control Unit Reprogram on the next page.




Figure 24

#### OCS Control Unit Reprogram

**IMPORTANT:** Seatbelt buckle bracket MUST be installed <u>before</u> OCS Control Unit Reprogramming is performed.

**NOTE:** In this Service Procedure, OCS is sometimes referred to as ODS.

- 1. Install the driver for the J-51594 OCS reprogramming cable as follows:
  - a. Keep the PC connected to the internet.
  - b. Connect the J-51594 OCS reprogramming cable to the PC USB port.
  - c. Wait 1 minute, the drivers will install automatically.

**NOTE**: Step 1 above is only required the first time this procedure is performed. It is recommended that it be performed at the beginning of each day to confirm you have the latest software installed in your PC.

- 2. Turn the ignition ON, engine OFF / not Ready (if not still ON) and turn ON the hazard warning flasher lights (if not still ON).
- 3. Connect the J-51594 OCS reprogramming cable:
  - Connect to the vehicle's DLC connector and the PC USB port.
  - Make sure the cable is securely connected at both ends.
- 4. Prepare the vehicle for OCS Reprogramming as follows:
  - Level the vehicle
  - No objects on the passenger seat.
  - No occupants in the vehicle including the servicing technician.
  - PC is outside of the vehicle on a suitable support.
    - > Do not set the PC on the vehicle.
  - Do not touch the vehicle during the OCS Reprogramming.
  - Minimize vibrations of the vehicle.


- 5. Open ASIST (if not already open).
- 6. Select "R1608 & R1609 OCS Reprogram" under Specialty Tools (Figure 25).

ASIST Terminal				
Dealer Code 2150 Se	ec Key No. c343 Last Sync.	5/17/2016 8:43:14 AM		
	IST	AUTOMOTIVE	SERVICE INFORMATION	Version 13.7.8
	VIN:	Retrieve VIN Clear Model:	✓ Year:	•
	What's New Service Manual	CONSULT Codes Symptom Diag.	Service History Campaigns	Quick Reference
TECH LINE DB Search				Featured NEWS
Latest TSBs	Keyword Search:			Service Manual
TSB Search		paigns issued/updated within last 30	days	Destination Hyperlinks now
CONSULT-II 😵				work with the latest
NATS & Keycode 🛛 😵				Adobe Reader 11
Specialty Tools 🔹				and DC versions
HD Navi. Tools R1608 & R1609 OCS Reprogram	0100			go to www.adobe.com
Check OCS ECU Module R1608 & R1609 ACU Reprogram	Step 6			to upgrade your
Midtronics Software Update				Reader version
Midtronics Update Help				now!
TECH LINE Support 😵				Adobe Reader 10,
Tech Support Info 😵				version 10.1.14 and
Tech-Mate 😵				higher is not ASIST certified.
Virtual Acadamy				

Figure 25

**NOTE**: If you get a black message screen as shown in Figure 26, this indicates that the reprogramming cable is not connected, or the cable driver did not install correctly.

- a. Close ODS Repro.
- b. Close ASIST.
- c. Start over from step 1 on page 13.





7. Select Start Repro.

**NOTE:** If the error message "an error occurred on connection" displays:

- a. Disconnect the J-51594 OCS reprogramming cable, both ends.
- b. Reconnect the cable; make sure it is securely connected at both ends.






Figure 27

- 8. Turn the ignition ON (engine OFF).
- 9. Select OK.
  - After selecting OK in Figure 28, the OCS reprogramming will start.



 If the OCS reprogramming stops (displays NG) at item 1, 2, 3 or 4, refer to Figures 34 through 37 on pages 18 and 19.






Figure 29

- 10. Cycle the ignition OFF > ON.
- 11. Select OK.

- After selecting OK in Figure 30, the OCS reprogramming will likely complete items 5 through 7 quickly (see "Complete" screen, Figure 32 below).
- If the OCS reprogramming stops (displays NG) at item 5, 6 or 7, refer to Figures 38 through 40 on pages 20 and 21.









Figure 31

- 12 When this screen displays (Figure 32), OCS reprogramming is complete.
- 13. Select OK.



Step 14	x
COM Port:	•
Start Repro	
1. Connect	ок
2. Read EEPDATA	D207
3. Write EEPDATA	ок
4. Check EEPDATA	ок
5. Reconnect	ок
6. Zero Reset	ок
7. Read EEPDATA	D207

- 14. Close the program (click on the red X in the upper right corner).
- 15. Turn the ignition OFF.

Figure 33

- 16. Disconnect the J-51594 OCS reprogramming cable.
- 17. Turn the ignition ON and observe the air bag warning light and the front passenger air bag status light:

X

• The air bag warning light

should illuminate for 7 seconds and then go out.

• The front passenger airbag status light should illuminate for 7 seconds and then either stay illuminated or go out, depending on the occupation of the front passenger seat.

**NOTE:** If the air bag warning light or the front passenger airbag status light does not operate as described above, there may be an issue not covered by this campaign. Refer to ASIST and the appropriate ESM for additional diagnostic and repair information.

## **OCS Reprogramming is Complete**

#### NOTE:

- Zero Point Reset was included in the reprogramming it is not necessary to perform as a separate step.
- Figures 34 through 40 on pages 18 through 21 are provided as reference if the OCS reprogramming stops (displays NG) at one of the items (1-7).

#### **APPENDIX**

- #1 If Connect indicates NG:
  - a. Click OK on the accompanying error message.
  - b. Turn the ignition OFF.
  - c. Close ODS Repro (click on the red X in the upper right corner).
  - d. Restart from step 1 on page 13.



Figure 34

- #2 If Read EEPDATA indicates NG:
  - a. Click OK on the accompanying error message.
  - b. Turn the ignition OFF.
  - c. Close ODS Repro (click on the red X in the upper right corner).
  - d. Restart from step 1 on page 13.




Figure 35

- #3 If Write EEPDATA indicates NG:
  - a. Click OK on the accompanying error message.
  - b. Turn the ignition OFF.
  - c. Close ODS Repro (click on the red X in the upper right corner).
  - d. Restart from step 1 on page 13.




Figure 36

- #4 If Check EEPDATA indicates NG:
  - a. Click OK on the accompanying error message.
  - b. Turn the ignition OFF.
  - c. Close ODS Repro (click on the red X in the upper right corner).
  - d. Restart from step 1 on page 13.




Figure 37

- #5 If Reconnect indicates NG:
  - a. Click OK on the accompanying error message.
  - b. Turn the ignition OFF.
  - c. Close ODS Repro (click on the red X in the upper right corner).
  - d. Restart from step 1 on page 13.




Figure 38

- #6 If Zero Reset indicates NG:
  - a. Click OK on the accompanying error message.
  - b. Cycle the ignition OFF > ON.
    - If needed, retry ignition OFF > ON 5 times.
  - c. If Zero Reset still indicates NG, close ODS Repro (click on the red X in the upper right corner), and restart from step 1 on page 13.




Figure 39

- #7 If Read EEPDATA indicates NG:
  - a. Click OK on the accompanying error message.
  - b. Turn the ignition OFF.
  - c. Close ODS Repro (click on the red X in the upper right corner).
  - d. Restart from step 1 on page 13.

🔰 ODS Repro	X
COM Port:	
Start Repro	
1. Connect	ок
2. Read EEPDATA	D207
3. Write EEPDATA	OK
4. Check EEPDATA	OK
5. Reconnect	OK
6. Zero Reset	OK
7. Read EEPDATA	NG

Figure 40

#### ALTERNATIVE METHOD TO PERFORM REPROGRAMMING FOR CAMPAIGN R1608.

#### NOTE:

- This procedure is an alternative method to perform reprogramming for campaign R1608.
- The primary reprograming method is using CONSULT-III plus.
- DO NOT perform the steps in the following pages if the procedures using CONSULT-III plus have already been performed.
- This method uses BOSCH MTS 6513.



#### **REQUIRED SPECIAL TOOL – BOSCH MTS 6513**

Figure A1

• One BOSCH MTS 6513 was shipped to each dealer. Additional tools can be obtained from Tech-Mate at 1-800-662-2001.

#### BOSCH MTS 6513 Airbag Diagnostic Sensor Unit Reprogram and OCS Control Unit Reprogram

**NOTE:** Screens on the BOSCH MTS 6513 indicate ACU. This stands for Airbag Control Unit, which is the same as Airbag Diagnostic Sensor Unit.

1. Open the engine hood and connect the GR8 to the 12V battery and set it to ECM power supply mode.

#### CAUTION:

- Connect the GR8 to the 12V battery and select ECM Power Supply Mode. If the vehicle battery voltage goes below <u>12.0V or above 15.5V</u> during reprogramming, <u>the control unit may be damaged</u>.
- Be sure to turn OFF all vehicle electrical loads.
  If a vehicle electrical load remains ON, <u>the control unit may be damaged</u>.
- 2. Connect the BOSCH MTS 6513 to the vehicle Data Link Connector (DLC).
- 3. Wait for the BOSCH MTS 6513 to boot.
  - A beep will be heard.
  - A green light on the BOSCH MTS 6513 will indicate it is powered ON.
  - When boot-up is complete and the Start Screen (see Figure A2) is displayed, the BOSCH MTS 6513 is ready for reprogramming.




Figure A2

#### NOTE:

- If the screen in Figure A2 does not display, the correct software has not been loaded into the BOSCH MTS 6513.
- On screen instructions will help guide you through the reprogramming process.

- 4. Turn the hazards (4 way flashers) ON.
- 5. Select enter on the key pad.

**NOTE:** During this procedure you will be asked several times to "select enter on the key pad". Each time, use the key pad enter button shown in Figure A3.




Figure A3

- 6. Turn the ignition ON (engine OFF / not Ready).
- 7. Select enter on the key pad.




Figure A4

NOTE: The VIN is read automatically.

8. Select enter on the key pad.

Vehic	le Ide	entifi	leation
VIN Model	JINE AL		16 176 97
Year			2015
CE	NTERIto	contin	ue
( dette)		$\Diamond$	10

Figure A5

#### NOTE:

- System call will be perfromed.
- Progress bar will be displayed during system call.
- The screen in Figure A6 (next page) will dispay when system call is complete.
- If system call does not complete and the screen in Figrue A6 does not display, the vehicle may not apply to this campaign.

9. Select enter on the key pad.



Figure A6

**NOTE:** (Airbag Diagnostic Sensor Unit Reprogram)

- The current version of the Airbag Diagnostic Sensor Unit software is read automatically to determine if it needs to be reprogrammed.
- If the Airbag Diagnostic Sensor Unit <u>does not</u> require reprogramming, the process will skip to OCS reprogramming (Figure A8 on the next page).
- If reprogramming is required, reprogramming will begin automatically. A progress bar will be displayed showing the percent complete, and the car icon will flash during the reprogramming process (see Figure A7).
- Approximate reporgram time is 3 to 5 minutes.




Figure A7

10. When reprogramming is complete, the screen in Figure A8 (next page) will display.




Figure A8

**NOTE:** (OCS Reprogram)

11. Select enter on the key pad.

- The current version of the OCS software is read automatically.
- Reprogramming will begin automatically. A progress bar will be displayed showing the percent complete, and the car icon will flash during the reprogramming process (see Figure A9).

oc	S rep	rogram	sing
IGN S		mID :	
03		103 h	1009
6		0	10

Figure A9

**NOTE:** During the OCS reprogramming you will be prompted to turn the ignition OFF, then back ON (see steps 12 through 15).

- 12. Turn the ignition OFF.
- 13. Select enter on the key pad.

	ocs	repi	-oğrı	mai	ng	]
	Turn	the	IGN-S	SW OF	F	
_	CEN	TERIte	o cont	inue		-
1		-	1 4		0	

Figure A10

- 14. Turn the ignition ON (engine OFF / not Ready).
- 15. Select enter on the key pad.



Figure A11

16. When reprogramming is complete, the screen in Figure A12 will display.




Figure A12

17. Prepare the vehicle for zero point reset as follows:

- Level the vehicle.
- No objects on the passenger seat.
- No occupants in the vehicle including the servicing technician.
- Do not touch the vehicle during the zero point reset.
- Minimize vibrations of the vehicle.

18. Select enter on the key pad.

18. Turn the ignition OFF.

19. Select enter on the key pad.




Figure A13




Figure A14



Figure A15



Figure A16

- 20. Turn the ignition ON (engine OFF / not Ready).
- 21. Select enter on the key pad.

• The screen in Figure A15 will display while zero point reset is being performed.

• The screen in Figure A16 will display when zero point reset is complete.

- 22. The reprogramming process is complete. Select the enter button on the key pad to display the result screens.
- 23. Turn the hazards (4-way flashers) OFF.
- 24. Turn the Ignition OFF.
- 25. Disconnect the BOSCH MTS 6513 from the vehicle DLC.

**IMPORTANT**: Make sure the BOSCH MTS 6513 powers down (wait about 30 seconds) before connecting to another vehicle. This will confirm any saved vehicle information is erased.

- 26. Disconnect the GR8 from the vehicle 12V battery.
- 27. Turn the ignition ON and observe the air bag warning light and the front passenger air bag status light:

×

• The air bag warning light

should illuminate for 7 seconds and then go out.


• The front passenger airbag status light should illuminate for 7 seconds and then either stay illuminated or go out, depending on the occupation of the front passenger seat.

**NOTE:** If the air bag warning light or the front passenger airbag status light does not operate as described above, there may be an issue not covered by this campaign. Refer to ASIST and the appropriate ESM for additional diagnostic and repair information.

### **Reprogramming is Complete**

#### PARTS INFORMATION

DESCRIPTION	PART #	QUANTITY
Leg Assy-Front LH (Seatbelt Buckle Bracket Kit)	87110-9AN0A	1



#### **CLAIMS INFORMATION**

#### Submit a Campaign (CM) line claim using the following claims coding:

CAMPAIGN ("CM") ID DESCRIPTION		OP CODE	FRT
R1608	Install Seatbelt Buckle Bracket and Reprogram	R16080	0.6 hrs.

#### FRONT PASSENGER AIR BAG STATUS LIGHT OPERATION

**NOTE:** Please print this page and place a copy in the vehicle.

Recall Campaign R1608 changes the operation of the passenger air bag status light.

• The passenger air bag status light will now be ON (illuminated) when the front passenger seat is empty.

Below is additional information regarding the operation of the passenger air bag status light.

The front passenger seat is equipped with an occupant classification sensor (weight sensor) that turns the front passenger air bag on or off depending on the weight applied to the front passenger seat. The status of the front passenger air bag (ON or OFF) is indicated by the front passenger air bag status light shift which is located on the instrument panel. After the ignition switch is placed in the "ON" position, the front passenger air bag status light on the instrument panel illuminates for about 7 seconds and then turns off or remains illuminated depending on the front passenger seat occupied status. The light operates as follows:



CONDITION	DESCRIPTION	PASSENGER AIR BAG INDICATOR LIGHT	FRONT PASSENGER AIR BAG STATUS
Empty	Empty front passenger seat	ON (illuminated)	INHIBITED
Nobody/Somebody	Bag or Child or Child Restraint or Small Adult in the front passenger seat	ON (illuminated)	INHIBITED
Adult	Adult in front passenger seat	OFF (dark)	ACTIVATED