# **TECHNICAL INSTRUCTIONS**

## FOR

# SAFETY RECALL G0P/G0R

## FRONT PASSENGER AIRBAG MODULE

## **CERTAIN 2006 – 2011 MY YARIS HATCHBACK**


The repair quality of covered vehicles is extremely important to Toyota. All dealership technicians performing this repair are required to successfully complete the most current version of the E-Learning course "Safety Recall and Service Campaign Essentials". To ensure that all vehicles have the repair performed correctly; technicians performing this repair are required to currently hold at least one of the following certification levels:

- Toyota Expert (Electrical)
- Master
- Master Diagnostic Technicians

Always check which technicians can perform the recall remedy by logging on to <u>https://www.uotdealerreports.com</u>. It is the dealership's responsibility to select technicians with the above certification level or greater to perform this repair. Carefully review your resources, the technician skill level, and ability before assigning technicians to this repair. It is important to consider technician days off and vacation schedules to ensure there are properly trained technicians available to perform this repair at all times.


## I. OPERATION FLOW CHART

The flow chart is for reference only. *DO NOT* use it in place of the full technical instructions. Follow *ALL* steps as outlined in the full technical instructions to confirm the campaign is completed correctly.



## **II. BACKGROUND**

The subject vehicles are equipped with front passenger airbag inflators produced by Takata. According to Takata, the propellant in these inflators may degrade after prolonged exposure to high absolute humidity and fluctuating high temperatures. Degraded propellant can cause inflator rupture during airbag deployment. In the event of an inflator rupture, metal fragments could pass through the airbag cushion material, striking the vehicle occupants, and result in serious injury or death.



## **III. IDENTIFICATION OF AFFECTED VEHICLES**

- Check the TIS Vehicle Inquiry System to confirm the VIN is involved in this Safety Recall, and that the campaign has not already been completed prior to dealer shipment or by another dealer.
- TMS warranty will not reimburse dealers for repairs conducted on vehicles that are not affected or were completed by another dealer.

## **IV. PREPARATION**

A. PARTS

Model	Part Number	Part Description	Quantity
	04005-23752	Instrument Panel Airbag Module	1
Yaris Hatchback	04005-28352	Wire Harness	1
	Local source	Tie-wrap	2


#### A. TOOLS & EQUIPMENT

Standard hand tools
 Torque wrench
 Techstream
 Molding remover set

**OPTIONAL SST** – This is an essential special service tool that the dealership should have. This tool is not mandatory when performing this repair.


Part Number	Part Name	Quantity
09890-47010-01	Anti-Static Mat Set	1

**GOP CAMPAIGN TOOLS** – This tool was previously provided to the dealership for campaign DOF and will be used for campaign GOP.



NOTE: This tool *CANNOT* be ordered through the parts or tool system. If additional scanners are needed, contact your regional representative.

## **V. SAFETY PRECAUTIONS**



## VI. SRS SYSTEM HEALTH CHECK



#### 1. PERFORM A HEALTH CHECK


- a) Confirm the Techstream is connected to the dealership's internet.
- b) When launching the Techstream software the VIN may need to be entered manually.

NOTE: All letters of the VIN *MUST* be entered in ALL CAPS, or the VIN will need to be reentered when running the diagnostic report.

- c) Perform a health check.
  - Note: The VIN may auto populate on the later model year vehicles, if this happens DO NOT change the VIN.


#### 2. RUN A DIAGNOSTIC REPORT


a) After the health check has completed, run a diagnostic report by clicking on the link on the health check screen.



# **VII. PASSENGER AIRBAG MODULE REPLACEMENT**

#### **COMPONENTS**





## 1. REMOVE THE AIRBAG MODULE

a) Refer to TIS for instructions on airbag removal:

 Hatchback
 2006MY
 2007MY
 2008MY
 2009MY
 2010MY
 2011MY

Wait at least 90 seconds after disconnecting the cable from the negative battery terminal to prevent airbag and seat belt pre-tensioner deployment.
Follow all precautions as outlined on TIS before servicing the SRS system.

## 2. LAUNCH THE SERIAL NUMBER RECORDING APPLICATION


- The AIRBAG MODULE serial number MUST be recorded using the barcode scanner (provided at the launch of SSC D0F).
   The barcode scanner application MUST be completed on every vehicle. These numbers MUST be included on every warranty claim that is submitted for module replacement or the claim may be subject to debit.
   The technician performing the work MUST have valid TIS login credentials and an intermediate of the statement of the statement of the technician performing the work MUST have valid TIS login credentials and an intermediate of the statement of the technician performing the work MUST have valid TIS login credentials and an intermediate of the statement of the technician performing the work MUST have valid TIS login credentials and an intermediate of the statement of the technician performing the work MUST have valid TIS login credentials and an intermediate of the statement of the technician performing the work MUST have valid TIS login credentials and an intermediate of the statement of the statement of the technician performing the work MUST have valid TIS login credentials and an intermediate of the statement of the statement of the technician performing the work MUST have valid TIS login credentials and an intermediate of the statement of the sta
  - The technician performing the work MUST have valid TIS login credentials and an internet connection to perform the inspection and scanning process.
  - a) Log in to TIS and input the VIN of the vehicle in the Vehicle Inquiry tab.
  - b) Confirm the VIN is applicable and that the campaign has not been completed.
  - c) Click on the link to launch the serial number recording application.

Note: The Serial Number Recording Application is the same as the DSF/E04 application, so the screens will still indicate campaign DSF or E04.

Vehicle Identification Number	Search		
Enter a 17 Digit V/IN below to sear			
V 4 1NX BR32E 000000000			
a)			
Vehicle Information			
Division: TOYOTA	Model: Corolla	Grade: CE	Model Year: 2003
Drive Type: 2WD	Body Type: 4Dr. Sedan	Engine Family: 4-cylinder - 1ZZ	Transmission:
Date of First Use:	Production Date: 01/18/2002	Plant Code: Z - FREMONT PLANT - NUMMI	
VIN: 1NX -8R32E-00000000	Standard Equipment: Click her	e to display	
Exterior Color: 03MS, SANDRIF	T METALLIC	Interior Color: FA41, FA41	
		Interior Trim Color: FA, *	Interior Fabric: F, *
Vehicle accessories are not curre	ntly available. Try your query again later.		
Campaign Service History	Warranty DTC History D	agnostic Report	
Service Campaign	Hereich ereicht e	a prosess compare	
Service campaign			
Campaign Description: Safety	y Recall DOF Remedy Notice - 2003-2004 M	odel Year Corolla, Corolla Matrix, Sequoia, an	d Tundra Vehicles, 2002-2003 Model Year
	completers check applicability for VIN		
Completion Status: Not C	Erect Passences I bog minister Medule	boli fear Corona, Corona Matrix, Sequola, an	a runara vencies, 2002-2003 Hodel fea

d) Reenter TIS password in the serial number recorder application.

NOTE: The person logged-in to TIS <u>MUST</u> be the person performing the repair.



e) Record the vehicle mileage into the serial number recording application.

NOTE:

٠

If this screen indicates that the module has already been replaced on this VIN, there is no need to perform the campaign again.

#### 3. CONNECT THE BARCODE SCANNER

- a) Connect the barcode scanner to the USB port on the Techstream.
- b) The scanner will automatically connect and a beep will be heard when the scanner is ready.

NOTE:

- The scanner was provided for SSC D0F.
- The scanner works best in low light conditions.
- Always hold the scanner directly in front of and parallel to the barcode label.

# **ATTENTION:** This information is **CRITICAL**

- a) Scan the **AIRBAG ASSEMBLY** serial number 2 times.
  - 1) Confirm the cursor is in the first serial number box then scan the serial.
  - 2) Position the cursor in the second serial number box then scan the serial.
- b) Click next.

#### NOTE:

- If both serial numbers that are entered do not match, confirm and reenter.
- If the serial number barcode will not scan, it can be entered manually.


#### AIRBAG SERIAL NUMBER IDENTIFICATION

- The airbag serial number is *ALWAYS* the 12 *DIGITS* located between the asterisks.
- The 3 digits before the asterisk ARE NOT part of the serial number, and SHOULD NOT be entered or an inaccurate response may be returned.


Airbag Serial Number Label Example




## The AIRBAG serial number MUST be recorded prior to replacement.



- c) Check the box as shown below this will allow the scanning system to move to the next screen.
- d) Click submit.






g) Click next.

t3qa.tms.toyota.com/t3Portal/portlets/tis/a	airBag/AirBagController.portlet?_nfpb=true&_windowLabel=Standa
Front Passenger Airba	ag Inflator Module - Safety Recall 🥂 🚔
	SSC - DSF
	(1)(2)(3)(4)(5)
User ID: SuzukiR	Technician Name: Russell Suzuki
Dealer Code:	Dealer Name:
Time: 06/10/2014 05:13 PM PDT	Airbag Serial #: *********96
Original Inflator Serial #: AAEL5110212	Replacement Inflator Serial #: AAEL5110213
I agree to complete the safety recall's remaining	llowing terms and conditions on 06/10/2014 05:13 PM PDT ng technical instructions. n Techstream upon completion of the safety recall's technical instructions.
Russell Suzuki has successfully o	confirmed completion of Airbag Inflator Module Safety Recall for
VIN - 5TD BT44	A 335157291 [2003 Sequoia BEIGE M. M.]
Warra	nty Authorization #: b5511e9f
Airbag inflator m	nodule was replaced under this safety recall.
Print this page for you	ir records and then click 'Close' to resume working.

- h) Confirm agreement by checking the two boxes.
- i) Record the Warranty Authorization # to be included in the warranty claim.
- j) Place the old module in the parts box and take it immediately to the parts department. **NOTE:**
- Confirm the cursor is in the correct serial number input box before scanning.
- If the serial number barcode will not scan, it can be entered manually.
- If there are any difficulties or concerns with this process, email
- quality\_compliance@toyota.com with details.

## AIRBAG SERIAL NUMBER IS MISSING OR IS UNREADABLE




## VIII. FRONT PASSENGER AIRBAG REINSTALLATION

## 1. INSTALL THE NEW AIRBAG







c) Refer to TIS for instructions on airbag installation:

a) Install the new harness onto the new airbag by plugging in the two connectors.

NOTE: Match the color of the harness connector to that of the airbag. Ensure that the connectors are fully seated.

b) Engage the secondary locks.

NOTE: Ensure the secondary locks are fully engaged.

 Hatchback
 2006MY
 2007MY
 2008MY
 2009MY
 2010MY
 2011MY

After the upper instrument panel has been installed secure the new airbag adaptor harness as shown.



2. RECONNECT THE NEGATIVE BATTERY CABLE

- a) Reconnect the negative battery cable.
- b) Perform any needed system intialzations.
- 3. PERFORM A HEALTH CHECK AND DIAGNOSTIC REPORT

# ◄ VERIFY REPAIR QUALITY ►

- Confirm all precautions are follow to ensure safety during the repair
- Confirm the entire serial number checker application is completed and the warranty authorization # is recorded on EVERY vehicle
- Confirm the old module is handled safely and given to the appropriate parts professional for shipment
- Confirm the airbag harness connector is fully engaged.

If you have any questions regarding this repair, please contact your regional representative.

Secure the adaptor harness to the dash harness.


Also secure the adaptor harness to the dash bracket.

NOTE: The upper instrument panel has been removed for clarity. Both areas can be accessed through the opening for the glove box door and/or the opening for the combination meter.

Check that the adaptor harness has the proper clearances and is not strained.

## **IX APPENDIX**

#### A. CAMPAIGN DESIGNATION DECODER



#### **B. CAMPAIGN PARTS DISPOSAL**

**ALL** airbags that are removed from vehicles under this campaign **MUST** be packaged and shipped back to the manufacturer following the manufacturer's instructions. The instructions can be found in the following locations:

- Attached to the dealer letter
- Included in the parts box
- On the laminated aid that was provided at the launch of the campaign