

P081NAS1

# TECHNICAL BULLETIN

16 MAR 2017



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

---

SECTION:

501-20B

---

## SUBJECT/CONCERN:

SAFETY RECALL: Takata Passenger Airbag

## AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:
Range Rover (LM)	2007-2011	233807-360036	Solihull

## MARKETS:

## CONDITION SUMMARY:

### SITUATION:

Vehicles listed within the Affected Vehicle Range are equipped with certain Takata airbag inflators (Ammonium Nitrate without desiccant propellant) assembled as part of the front passenger airbag modules and used as original equipment or replacement equipment.

In the event of a crash necessitating deployment of the front passenger airbag, these Takata inflators may rupture due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

An inflator rupture may result in metal fragments striking the vehicle occupants and could result in serious **INJURY or DEATH** .

### NOTE:

**This Safety Recall affects 2007-2011 model year vehicles originally sold, or ever registered, in Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, American Samoa, Guam, the Northern Mariana Islands (Saipan), and the U.S. Virgin**

Islands. It also affects 2007-2008 model year vehicles originally sold, or ever registered in, Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and West Virginia.

#### **ACTION:**

Retailers are required to **HOLD** affected new vehicles that are within your control and refrain from releasing the vehicles for **new vehicle sale** pending completion of the Service Instruction detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but **must** have it completed prior to vehicle handover to the customer.

Affected vehicles already in the hands of customers should be updated at the next available opportunity.

#### **PARTS:**

#### **NOTES:**

- **Order only the expected percentage demand of parts identified.**
- **The serial number of the new airbag module (example highlighted in blue) MUST be recorded on the claim verbatim.**



E206204

DESCRIPTION	PART NO. /SUNDRY CODE	QTY. /VALUE	EXPECTED % OF VEHICLES REQUIRING PARTS
Airbag Module	LR095854	1	100
Nut and Washer Kit	YYH500020	8	100
Bolt	RYG500230	2	100

### SPECIAL DISPLACED PARTS HANDLING PROCEDURE

Displaced parts require special handling and shipping procedures. Refer to Service Bulletin SRE17-05 for complete details.

**WARRANTY:**

 **NOTE:**

**Check DDW to ensure that a vehicle is affected by this program prior to undertaking any rework action.**

At the time of confirming a booking for vehicle repair, ensure that **all** outstanding Recalls and Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting the Program Code together with the relevant Option Code. The SRO and parts information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time.

Warranty claims must be submitted or payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PARTS /SUNDRY CODE	QTY. /VALUE
P081	B	Passenger airbag module renew	76.74.02	1.4	LR095854 YYH500020 RYG500230	1 8 2
P081	C	Passenger airbag module renew	76.74.02	1.4	LR095854 YYH500020 RYG500230	1 8 2
		Drive in/drive out	02.02.02	0.2	-	-

Normal Warranty policies and procedures apply.

SERVICE  
INSTRUCTION:

△ NOTE:

The Airbag may be referred to as 'Air Bag' in TOPIX.

1

△ NOTE:

The serial number of the new airbag module (example highlighted in blue) MUST be recorded on the claim verbatim.



E206204

Locate and record the serial number of the new airbag module on the claim verbatim.

2

Install a new passenger airbag module (see TOPIX Workshop Manual section 501-20B: Supplemental Restraint System - Passenger Air Bag Module).

Refer to Service Bulletin SRE17-05 for full details of the Special Displaced Parts Handling Procedure.