

TECHNICAL BULLETIN

P086NAS1

27 JUN 2016



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 501-20

SAFETY RECALL: Driver Airbag Slow Deployment

AFFECTED VEHICLE RANGE:

LR4 (LA)

Model Year: 2016

VIN: 829622-831108

Assembly Plant: Solihull

MARKETS:

NAS

CONDITION SUMMARY:

This bulletin supersedes UPS4116-4bNAS (Q598) with immediate effect.

Situation: An issue has been identified on a limited number of vehicles within the listed Affected Vehicle Range where driver airbag performance is outside of the required specification for time to inflate due to a malformed canister. In this condition, the flow of the gas generated for airbag deployment is not controlled as required. In the event of a crash where the driver airbag is required to deploy, the driver will not be fully protected by the airbag as per design intent. This could lead to an increased risk of injury.

Action: Retailers are required to **HOLD** affected new vehicles that are within your control and refrain from releasing the vehicles for **new vehicle sale** pending completion of the Service Instruction detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but **must** have it completed prior to vehicle handover to the customer.

Affected vehicles already in the hands of customers should be updated at the next available opportunity.

PARTS:



WARNING: All pyrotechnic devices are dangerous. Before performing any procedures -- including disposal -- on any pyrotechnic device, read all information contained within the TOPIx Workshop Manual section 100-00: Description and Operation - Standard Workshop Practices.



NOTE: Retailers must place orders following the Restricted Parts order guidelines. Provide the VIN in the Customer Material Number field for all parts orders.

DESCRIPTION	PART No./SUNDRY CODE	QTY./VALUE	EXPECTED % of VEHICLES REQUIRING PARTS
Driver Airbag Module	LR051756	1	100

SPECIAL TOOLS:

Refer to Workshop Manual/Service Instruction for any required tools.

WARRANTY:



NOTE: Check DDW to ensure that a vehicle is affected by Program Code P086 prior to undertaking any rework action.

At the time of confirming a booking for vehicle repair, ensure that all outstanding Recalls and Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code **P086** together with the relevant Option Code from the table. SRO and parts information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.


Warranty claims must be submitted or payment within 30 calendar days of completion of the repair. For vehicles repaired prior to this publication as part of Q598 but which have not yet been claimed, submit claims under Program Code P086.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PARTS/SUNDRY CODE	QTY./VALUE
P086	B	Replace driver airbag module	76.74.01	0.1	LR051756	1
P086	C	Replace driver airbag module Drive in/drive out	76.74.01 02.02.02	0.1 0.2	LR051756	1

Normal Warranty policies and procedures apply.

SERVICE INSTRUCTION:

-  **WARNING: All pyrotechnic devices are dangerous. Before performing any procedures -- including disposal -- on any pyrotechnic device, read all information contained within TOPIx Workshop Manual section 100-00: Description and Operation - Standard Workshop Practices.**

Replace the driver airbag module (see TOPIx Workshop Manual section 501-20: Supplemental Restraint System).