IMPORTANT UPDATE OCTOBER 7, 2016

TECHNICAL INSTRUCTIONS

FOR

SAFETY RECALL GOU

CURTAIN SHIELD AIRBAG

CERTAIN 2010 –2012 MODEL YEAR PRIUS CERTAIN 2010 AND 2012 MODEL YEAR PRIUS PLUG-IN

UPDATED OCTOBER 7, 2016

Update 10/7/2016

- The parts-table in section IV of the Technical Instructions has been updated.


The repair quality of covered vehicles is extremely important to Toyota. All dealership technicians performing this repair are required to successfully complete the most current version of the E-Learning course "Safety Recall and Service Campaign Essentials". To ensure that all vehicles have the repair performed correctly; technicians performing this repair are required to currently hold <u>at least one</u> of the following certification levels:

- Expert Technician Electrical
- Master Technician
- Master Diagnostic Technician (MDT)

It is the dealership's responsibility to select technicians with the above certification level or greater to perform this repair. Carefully review your resources, the technician skill level, and ability before assigning technicians to this repair. It is important to consider technician days off and vacation schedules to ensure there are properly trained technicians available to perform this repair at all times.

I. OPERATION FLOW CHART


The flow chart is for reference only. *DO NOT* use it in place of the full technical instructions. Follow *ALL* steps as outlined in the full technical instructions to confirm the campaign is completed correctly.



II. BACKGROUND

The involved vehicles are equipped with curtain shield air bags (CSA) in the driver and passenger side roof rails that have air bag inflators composed of two chambers welded together. Some inflators could have a small crack in the weld area joining the chambers, which could grow over time, and lead to the separation of the inflator chambers. This has been observed when the vehicle is parked and unoccupied for a period of time. If an inflator separates, the CSA could partially inflate, and, in limited circumstances, one or both sections of the inflator could enter the interior of the vehicle. If an occupant is present in the vehicle, there is an increased risk of injury.

The remedy will consist of installing retention brackets designed to prevent the inflator chambers from entering the vehicle interior if separation occurs.



III. IDENTIFICATION OF AFFECTED VEHICLES

- Check the TIS Vehicle Inquiry System to confirm the VIN is involved in this Safety Recall, and that the campaign has not already been completed prior to dealer shipment or by another dealer.
- TMS warranty will not reimburse dealers for repairs conducted on vehicles that are not affected or were completed by another dealer.

IV. PREPARATION

A. PARTS

All applicable vehicles will require the parts in the table below

Part Number	Description	Qty
04006-25147	CSA Bracket Kit	1

B. MATERIALS

- Protective tape
 Protective
- Gloves
- Marker Pen

C. TOOLS & EQUIPMENT


- Standard hand tools
- Molding remover set
- Torque wrench
- Techstream
- Clip remover


REDUCE INTERIOR TEMPERATURE AND INFLATOR PRESSURE


ALWAYS PERFORM THIS STEP TO ENSURE THE INFLATOR TEMPERATURE IS LOWERED. THIS IS CRUCIAL FOR YOUR SAFETY; SPECIFICALLY DURING THE STOF HOTTER MONTHS WHEN DIRECT SOLAR LOAD IS PLACED ON VEHICLES. **REDUCE INTERIOR TEMPERATURE VIDEO** 1. RECORD THE CUSTOMER CLIMATE CONTROL SETTINGS םר 🗱 a) Temperature ***** b) Air Inlet Setting (Recirculation or Fresh Air) c) Vent Setting MAIC \° d) Vent Position 2. TURN ON THE A/C TO THE FOLLOWING SETTINGS 7 LO a) A/C On 7. b) Maximum blower/fan speed c) Max cool/LO setting AIC 0 d) Recirculation for air inlet e) Face/dash vent only mode f) Aim the dash vents upward toward the headliner 3. REPOSITION FRONT DOOR WEATHERSTRIP a) Remove the upper portion of the weatherstrip on both front doors to allow the cool A/C air to enter the area between the headliner and roof panel. b) Using a cloth clean off the residual sealant left behind on the door frame from the weatherstrip. c) Place the loose weatherstrip inside the cabin of the vehicle to ensure that it does not get pinched by the door. Ensure you follow this step, it is crucial to in order STOP for the cool A/C air to reach the CSA Inflator Canister. Š27093aS 4. COOL INTERIOR a) Let the vehicle run for 15 minutes to lower the inflator temperature and pressure. ALWAYS PERFORM THIS STEP TO ENSURE THE INFLATOR TEMPERATURE IS LOWERED. THIS IS CRUCIAL FOR YOUR SAFETY; SPECIFICALLY DURING THE STOP HOTTER MONTHS WHEN DIRECT SOLAR LOAD IS PLACED ON VEHICLES.

V. INTERIOR DISASSEMBLY

1. CONFIRM VEHICLES ORIGINAL CONDITION BY PERFORMING VEHICLE HEALTH CHECK 2. RECORD CUSTOMER SEAT POSITION AND RADIO SETTINGS










VI. INSTALL CURTAIN SHIELD AIRBAG BRACKETS


CSA BRACKET INSTALLATION VIDEO





VII. INTERIOR REASSEMBLY





- 4. **RESTORE SEAT POSITION**
- 5. **RESTORE CUSTOMER CLIMATE CONTROL SETTINGS**
- 6. **CONFIRM ALL INTERIOR COMPONENTS OPERATION**
- 7. CHECK AND CLEAR ANY DTCS

◄ VERIFY REPAIR QUALITY ►

- Confirm the interior temperature was reduced prior to disassembly -
- Confirm the brackets are properly installed _
- _ Confirm the interior settings are reset

If you have any questions regarding this update, please contact your area representative.