TECHNICAL BULLETIN P091NAS1 01 DEC 2016



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 307-01

SAFETY RECALL: 9-Speed Transmission Harness Crimp

AFFECTED VEHICLE RANGE:

Range Rover Evoque (LV)

Model Year: 2014-2015

VIN: 795896-996092 Vehicles With: 9HP48 9-Speed Automatic

Assembly Plant: Halewood Transmission - AWD

Discovery Sport (LC)

Model Year: 2015

VIN: 500320-501680 Vehicles With: 9HP48 9-Speed Automatic

Assembly Plant: Halewood Transmission - AWD

Range Rover Evoque (LV)

Model Year: 2015

VIN: 000134-077907 Vehicles With: 9HP48 9-Speed Automatic

Assembly Plant: Halewood Transmission - AWD

MARKETS:

NAS

CONDITION SUMMARY:

Situation: An issue has been identified on a limited number of vehicles within the listed Affected Vehicle Range which may have insufficient crimps in a transmission wiring harness which may cause an unexpected shift to neutral resulting in a sudden loss of motive power.

Action: Retailers are required to **HOLD** affected new vehicles that are within your control and refrain from releasing the vehicles for **new vehicle sale** pending completion of the Service Instruction detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but **must** have it completed prior to vehicle handover to the customer.

Affected vehicles already in the hands of customers should be updated at the next available opportunity.

PARTS:

No parts required.

SPECIAL TOOLS:



E192494

Jaguar Land Rover-approved Midtronics Battery Power Supply



E179225

Jaquar Land Rover-approved diagnostic tool with latest SDD software and Calibration File

WARRANTY:



NOTE: Check DDW to ensure that a vehicle is affected by this program prior to undertaking any rework action.

At the time of confirming a booking for vehicle repair, ensure that **all** outstanding Recalls and Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting the Program Code together with the relevant Option Code from the table. SRO and parts information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time.

Warranty claims must be submitted or payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PARTS/SUNDRY CODE	QTY./VALUE
P091	А	Check Calibration files - No further action	44.90.89.39	0.10	-	_

P091	К	Check Calibration files - No further action Drive in/drive out	44.90.89.39 02.02.02	0.10 0.20	- -	- -
P091	В	Check and configure the transmission control module	44.90.89.40	0.20	_	_
P091	С	Check and configure the transmission control module Drive in/drive out	44.90.89.40 02.02.02	0.20 0.20	-	-

Normal Warranty policies and procedures apply.

SERVICE INSTRUCTION:

CAUTION: A Jaguar Land Rover-approved Midtronics battery power supply must be connected to the vehicle battery during diagnosis / module programming.

CAUTION: Make sure all ignition ON/OFF requests are carried out; failure to perform these steps may cause damage to control modules in the vehicle.



NOTE: The Jaguar Land Rover-approved diagnostic tool must be loaded with SDD147.07 v.255 (or later).

- 1. Connect the Jaguar Land Rover-approved Midtronics battery power supply to the vehicle battery.
- 2. Turn ignition ON (engine not running).
- 3. Connect the Jaguar Land Rover-approved diagnostic tool to the vehicle and begin a new session.
- **4.** Follow the on-screen prompts, allowing the diagnostic tool to read the VIN and identify the vehicle and initiating the data collect sequence.
- 5. When complete, select the part information tab.

9HP48 Transmission Calibration Files: Discovery Sport (L550)

Discovery Sport (L550) Assembly	Discovery Sport (L550) Calibration File		
FK72-12B565-AJ	FK72-14C337-CAJ		

9HP48 Transmission Calibration Files: Range Rover Evoque (L538)

Range Rover Evoque (L538) Assembly	Range Rover Evoque (L538) Calibration Files
With Active Driveline: EJ32-12B565-AV	EJ32-14C337-CAT
With Active Driveline: EJ32-12B565-UE	EJ32-14C337-CUE
Without Active Driveline: EJ32-12B565-CP	EJ32-14C337-CCP
Without Active Driveline: EJ32-12B565-XE	EJ32-14C337-CXE

- 6. Scroll down to TCM and check the part number corresponding to ' vm_ecu_sw_pn'.
 - If the level of TCM calibration installed matches that referenced in the appropriate table above, go to Step

• If the level of TCM calibration installed does not match that referenced in the appropriate table above, go to Configure Existing Transmission Control Module. Configure Existing Transmission Control Module 7. Select Diagnosis from the Session Type screen. 8. Select the **Selected Symptoms** tab, and then select the following: · Powertrain - Automatic transmission and transaxle - Automatic transmission and transaxle symptoms 9. Run and close the Datalogger tool to reveal the 'Extras 'tab. 10. Select the Extras tab. 11. From the Recommendations tab, select Run to perform the 'Configure existing module - Transmission control module ' option. 12. Follow all on-screen instructions to complete this task, ensuring all Diagnostic Trouble Codes (DTC) are cleared. 13. When all tasks are complete, select the Session tab and then select the Close Session option.

14. Disconnect the diagnostic tool and battery power supply from the vehicle.