

P094NAS1

TECHNICAL BULLETIN

13 FEB 2017



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

SECTION:

501-20B

SUBJECT/CONCERN:

SAFETY RECALL: Autoliv Passenger Airbag Operation

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:
Range Rover Evoque (LV)	2017	178234-184779	Halewood
Range Rover Sport (LW)	2016	112966-119436	Solihull
Range Rover Sport (LW)	2016	664703-664714	Solihull
Range Rover (LG)	2016	310620-318022	Solihull

MARKETS:

NAS

CONDITION SUMMARY:

SITUATION:

An issue has been identified on certain vehicles within the listed Affected Vehicle Range where the front passenger airbag may not function properly due to a deviation in generant mix ratio.

ACTION:

Retailers are required to **HOLD** affected new vehicles that are within your control and refrain from releasing the vehicles for new vehicle sale pending completion of the Service Instruction detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but must have it completed prior to vehicle handover to the customer.

Affected vehicles already in the hands of customers should be updated at the next available opportunity.

PARTS:

NOTE:

Order only the expected percentage demand of parts identified.

DESCRIPTION	PART NO. /SUNDRY CODE	QTY. /VALUE	EXPECTED % OF VEHICLES REQUIRING PARTS
Airbag - Instrument Panel - Passenger - Range Rover Evoque (L538)	LR091702	1	100
Airbag - Instrument Panel - Passenger - Range Rover Sport (L494); Range Rover (L405)	LR037934	1	100
Nut and washer kit	RYH500420	8	100

SPECIAL TOOLS:

Refer to Workshop Manual/Service Instruction for any required special tools.

WARRANTY:

NOTE:

Check DDW to ensure that a vehicle is affected by this program prior to undertaking any rework action.

At the time of confirming a booking for vehicle repair, ensure that **all** outstanding Recalls and Service Actions are identified to ensure

the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting the Program Code ' **P094** ', Option Code ' **X** ', and the relevant SRO and parts information. The drive in / drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time.

Warranty claims must be submitted or payment within 30 calendar days of completion of the repair.

 **NOTE:**

The replacement airbag serial number MUST be recorded on the claim verbatim.

DESCRIPTION	SRO	TIME (HOURS)	PARTS /SUNDRY CODE	QTY. /VALUE
Airbag - Instrument Panel - Passenger - Renew - Range Rover Evoque (L538)	76.74.02	3.80	LR091702 RYH500420	1 8
Airbag - Instrument Panel - Passenger - Renew - Range Rover Sport (L494)	76.74.02	4.70	LR037934 RYH500420	1 8
Airbag - Instrument Panel - Passenger - Renew - Range Rover (L405; SWB)	76.74.02	3.60	LR037934 RYH500420	1 8
Airbag - Instrument Panel - Passenger - Renew - Range Rover (L405; LWB)	76.74.02	5.70	LR037934 RYH500420	1 8
Disengage and reengage	86.90.89.47	0.10	-	-

Transit Mode - Range Rover Evoque (L538)				
Disengage and reengage Transit Mode - Range Rover Sport (L494); Range Rover (L405)	86.90.89.47	0.20	-	-
Drive in/drive out	02.02.02	0.20	-	-

Normal Warranty policies and procedures apply.

SERVICE INSTRUCTION:

 NOTE:

The replacement airbag serial number MUST be recorded on the claim verbatim.

- 1 Install a new passenger airbag module (see TOPIx Workshop Manual section 501-20B: Supplemental Restraint System - Passenger Air Bag Module).