



February 2018

IMPORTANT SAFETY RECALL

NHTSA Recall: 16V-088

Transport Canada Recall: 2016067

This notice applies to your vehicle: "VIN"
"Crane Serial #"

Dear IMT Vehicle Owner: "COMPANY NAME"

Ref: IMT Series III Crane Valve Bank Cover

This applies to your crane if it was manufactured between April 4, 2013 and January 22, 2016.

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

IMT has decided that 2013-2016 IMT Dominator-Propane, Dominator I, Dominator II, Dominator III, and Dominator IV vehicles fitted with Series III Crane Models 6000, 7500, 8600, 9500, 10000, 12000 and 14000 that were built with a certain valve bank cover exhibit a defect that relates to motor vehicle safety.

! I M P O R T A N T !

- Your IMT vehicle is being recalled.
- Perform the attached recall repair procedure as soon as possible.
- Contact IMT toll free at 1-800-554-4421 for any questions.
- This recall repair will result in **no cost** to you.

Why is a recall being conducted?

IMT has identified that certain Series III cranes were built with a valve bank cover that can crack. Under certain road conditions the cracks can propagate and eventually cause the cover to break. If not repaired, a broken valve bank cover can detach from the vehicle and create a possibility of a road hazard which could result in a vehicle crash or injury.

What are we doing about the problem?

For each vehicle, IMT will:

- Provide instructions via a Technical Bulletin (TB) that describes how to replace the existing cover with a new different cover. IMT will provide you with a new valve bank cover at no cost.



What should you do?

- Contact your IMT Distributor to arrange delivery of replacement parts for your crane.
- The replacement of the valve bank cover should be performed by your own service technicians or by an IMT distributor at your earliest opportunity. IMT anticipates that owners will continue to place their vehicles in service until the recall actions can be completed.
- As an interim safety precaution, the valve bank cover should be periodically inspected for cracks forming. If cracks are forming, the cover should be removed.
- The repair should take less than 30 minutes. The process for reimbursement is detailed in the TB.
- If you have any questions or require further assistance, contact IMT at 1-800-554-4421.

What if you no longer own this vehicle?

If you no longer own this vehicle, please contact IMT at 1-800-554-4421 to assist us in updating our records.

Who should you contact if you have further questions or concerns?

If you have further questions, please contact IMT at 1-800-554-4421 to allow us to assist you.

If you have leased this vehicle to another person, federal regulations require you to send a copy of this notice to your lessee by first-class mail within ten days of your receipt of this notice.

If you have already replaced the cover due to this issue, you may be entitled to reimbursement if you incurred any out of pocket cost due to this matter. For further information, please contact IMT Technical Support at the number listed above.

If IMT fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to:

The Administrator, National Highway Traffic Safety Administration
1200 New Jersey Avenue, SE.,
Washington, DC 20590;
or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153);
or go to <http://www.safercar.gov>.

We apologize for any inconvenience this safety recall may cause, but your safety is our first concern.

Sincerely,
Iowa Mold Tooling Company, Inc.