

August 2016
FL711A-D
NHTSA #16V-321

Subject: Motorhome Throttle Pedal Return

Models Affected: Specific Freightliner Custom Chassis XCL, XCM, XCP, and XCR chassis manufactured January 23, 2012, through April 10, 2014, and equipped with certain Williams Control throttle pedal assemblies.

General Information

Daimler Trucks North America LLC, on behalf of its wholly owned subsidiary, Freightliner Custom Chassis Corporation, has decided that a defect that relates to motor vehicle safety exists on the vehicles mentioned above.

There are approximately 2, 275 vehicles involved in this campaign.

On certain vehicles, when the throttle pedal is released, the pedal sensor may not return to zero, causing the engine brake not to activate as expected. The sudden loss of an engine brake without warning on a motorhome may lead to reduced brake capacity, increasing the risk of a vehicle crash.

The throttle pedal will be inspected and replaced as required.

Additional Repairs

Dealers must complete all outstanding Recall and Field Service campaigns prior to the sale or delivery of a vehicle. A Dealer will be liable for any progressive damage that results from its failure to complete campaigns before sale or delivery of a vehicle.

Owners may be liable for any progressive damage that results from failure to complete campaigns within a reasonable time after receiving notification.

Work Instructions

Please refer to the attached work instructions. Prior to performing the campaign, check the vehicle for a completion sticker (Form WAR260).

Replacement Parts

Replacement parts are now available and can be obtained by ordering the kit number(s) listed below from your facing Parts Distribution Center.

If our records show your dealership has ordered any vehicles involved in campaign number FL711, a list of the customers and vehicle identification numbers will be available in OWL. Please refer to this list when ordering parts for this recall.

Table 1 - Replacement Parts for FL711A-D

Campaign Number	Kit Number	Part Description	Part Number	Qty. per Kit
FL711AB	25-FL711-000	PEDAL ASSY-SUSP/ADJ,ISL13	A01-33965-000	1 ea
FL711CD	25-FL711-001	PEDAL ASSY-SUSP/ADJ,ISL13,MEM	A01-33965-001	1 ea

Table 1

Removed Parts

U.S. and Canadian Dealers, please follow Warranty Failed Parts Tracking shipping instructions for the disposition of all removed parts. Export distributors, please destroy removed parts unless otherwise advised.

August 2016
FL711A-D
NHTSA #16V-321

Labor Allowance

Table 2 - Labor Allowance

Campaign Number	Procedure	Time Allowed (hours)	SRT Code	Corrective Action
FL711A-D	Inspect Throttle Pedal	0.1	996-0983B	06 - Inspect
FL711A-D	Inspect and Replace Throttle Pedal	0.4	996-0983A	12 - Repair Recall/Campaign

Table 2

IMPORTANT: When the Recall has been completed, locate the base completion label in the appropriate location on the vehicle, and attach the red completion sticker provided in the recall kit (Form WAR260). If the vehicle does not have a base completion label, clean a spot on the appropriate location of the vehicle and first attach the base completion label (Form WAR259). If a recall kit is not required or there is no completion sticker in the kit, write the recall number on a blank sticker and attach it to the base completion label.

Claims for Credit

You will be reimbursed for your parts, labor, and handling (landed cost for Export Distributors) by submitting your claim through the Warranty system within 30 days of completing this campaign. Please reference the following information in OWL:

- Claim type is **Recall Campaign**.
- In the Campaign field, enter the campaign number and appropriate group (e.g. **FL711-A, FL711-B, etc.**).
- In the Primary Failed Part field, enter **25-FL711-000**.
- In the Parts section, enter the appropriate kit number(s) as shown in the Replacement Parts Table.
- In the Labor section, enter the appropriate SRT from the Labor Allowance Table. Administrative time will be included automatically as SRT 939-6010A for 0.4 hours for RVs.
- The VMRS Component Code is **004-007-032** and the Cause Code is **A1 - Campaign**.
- **U.S. and Canada -- Reimbursement for Prior Repairs.** When a customer asks about reimbursement, please do the following:
 - Accept the documentation of the previous repair.
 - Make a brief check of the customer's paperwork to see if the repair may be eligible for reimbursement. (See the "Copy of Owner Letter" section of this bulletin for reimbursement guidelines.)
 - Submit an OWL Recall Pre-Approval Request for a decision.
 - Attach the documentation to the pre-approval request.
 - If approved, submit a based on claim for the pre-approval.
 - Reimburse the customer the appropriate amount.

IMPORTANT: OWL must be viewed prior to performing the recall to ensure the vehicle is involved and the campaign has not been previously completed. Also, check for a completion sticker prior to beginning work.

For questions, U.S. and Canadian dealers, contact the Warranty Campaigns Department from 7:00 a.m. to 4:00 p.m. Pacific Time, Monday through Friday, via Web inquiry at DTNAConnect.com / WSC, or the Customer Assistance Center at (800) 385-4357, after normal business hours, if you have any questions or need additional information. Export distributors, submit a Web inquiry or contact your International Service Manager.

U.S. and Canadian Dealers: To return excess kit inventory related to this campaign, U.S. dealers must submit a Parts Authorization Return (PAR) to the Memphis PDC. Canadian dealers must submit a PAR to their facing PDC. All kits must be in resalable condition. PAR requests must include the original purchase invoice number. Export Distributors: Excess inventory is not returnable.

**August 2016
FL711A-D
NHTSA #16V-321**

The letter notifying U.S. and Canadian vehicle owners is included for your reference.

Please note that the National Traffic and Motor Vehicle Safety Act, as amended (Title 49, United States Code, Chapter 301), requires the owner's vehicle(s) be corrected within a reasonable time after parts are available to you. The Act states that failure to repair a vehicle within 60 days after tender for repair shall be prima facie evidence of an unreasonable time. However, circumstances of a particular situation may reduce the 60 day period. Failure to repair a vehicle within a reasonable time can result in either the obligation to (a) replace the vehicle with an identical or reasonably equivalent vehicle, without charge, or (b) refund the purchase price in full, less a reasonable allowance for depreciation. The Act further prohibits dealers from selling a vehicle unless all outstanding recalls are performed. Any lessor is required to send a copy of the recall notification to the lessee within 10 days. Any subsequent stage manufacturer is required to forward this notice to its distributors and retail outlets within five working days.

August 2016
FL711A-D
NHTSA #16V-321

Copy of Notice to Owners

Subject: Motorhome Throttle Pedal Return

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Daimler Trucks North America LLC (DTNA), on behalf of its wholly owned subsidiary, Freightliner Custom Chassis Corporation, has decided that a defect which relates to motor vehicle safety exists on specific Freightliner Custom Chassis XCL, XCM, XCP, and XCR chassis manufactured January 23, 2012, through April 10, 2014, and equipped with certain Williams Control throttle pedal assemblies.

On certain vehicles, when the throttle pedal is released, the pedal sensor may not return to zero, causing the engine brake not to activate as expected. The sudden loss of an engine brake without warning on a motorhome may lead to reduced brake capacity, increasing the risk of a vehicle crash.

The throttle pedal will be inspected and replaced as required.

Please contact an authorized Daimler Trucks North America dealer to arrange to have the Recall performed and to ensure that parts are available at the dealership. To locate an authorized dealer, search online at www.Daimler-TrucksNorthAmerica.com / Contact Us / Find a Dealer. The Recall will take approximately one half hour and will be performed at no charge to you.

You may be liable for any progressive damage that results from your failure to complete the Recall within a reasonable time after receiving notification.

If you do not own the vehicle that corresponds to the identification number(s) which appears on the Recall Notification, please return the notification to the Warranty Campaigns Department with any information you can furnish that will assist us in locating the present owner. If you have leased this vehicle, Federal law requires that you forward this notice to the lessee within 10 days. If you are a subsequent stage manufacturer, Federal law requires that you forward this notice to your distributors and retail outlets within five working days. If you have paid to have this recall condition corrected prior to this notice, you may be eligible to receive reimbursement. Please see the reverse side of this notice for details.

If you have questions about this Recall, please contact the Warranty Campaigns Department at (800) 547-0712, 7:00 a.m. to 4:00 p.m. Pacific Time, Monday through Friday, e-mail address DTNA.Warranty.Campaigns@Daimler.com, or the Customer Assistance Center at (800) 385-4357 after normal business hours. If you are not able to have the defect remedied without charge and within a reasonable time, you may wish to submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the Vehicle Safety Hotline at (888) 327-4236 (TTY: 800-424-9153); or to <http://www.safercar.gov>.

We regret any inconvenience this action may cause but feel certain you understand our interest in motor vehicle safety.

WARRANTY CAMPAIGNS DEPARTMENT

Enclosure

August 2016
FL711A-D
NHTSA #16V-321

Reimbursement to Customers for Repairs Performed Prior to Recall

If you have already **paid** to have this recall condition corrected you may be eligible to receive reimbursement.

Requests for reimbursement may include parts and labor. Reimbursement may be limited to the amount the repair would have cost if completed by an authorized Daimler Trucks North America LLC dealer. The following documentation must be presented to your dealer for consideration for reimbursement.

Please provide original or clear copies of all receipts, invoices, and repair orders that show

- The name and address of the person who paid for the repair
- The Vehicle Identification Number (VIN) of the vehicle that was repaired
- What problem occurred, what repair was done, when the repair was done
- Who repaired the vehicle
- The total cost of the repair expense that is being claimed
- Proof of payment for the repair (such as the front and back of a cancelled check or a credit card receipt)

Reimbursement will be made by check from your Daimler Trucks North America LLC dealer.

Please speak with your Daimler Trucks North America LLC authorized dealer concerning this matter.

August 2016
FL711A-D
NHTSA #16V-321

Work Instructions

Subject: Motorhome Throttle Pedal Return

Models Affected: Specific Freightliner Custom Chassis XCL, XCM, XCP, and XCR chassis manufactured January 23, 2012, through April 10, 2014, and equipped with certain Williams Control throttle pedal assemblies.

Throttle Pedal Inspection and Replacement

1. Check the base label (Form WAR259) for a completion sticker for FL711 (Form WAR260) indicating this work has been done. The base label is usually located on the front wall under the dash. If a sticker is present, no work is needed. If there is no sticker, proceed with the next step.
2. Park the vehicle on a level surface, shut down the engine, and set the parking brake. Chock the tires.

NOTE: Use a mirror to view the serial number located on the throttle pedal identification label.

3. Inspect the throttle pedal identification label, shown in [Fig. 1](#). Each label has a serial number, shown in [Fig. 2](#), which indicates the manufacture date. In this example, the manufacture date 160725 of the throttle pedal is July 25, 2016.



Fig. 1, Location of the Throttle Pedal Identification Label




Fig. 2, Throttle Pedal Serial Number

If the manufacture date is March 18, 2014, or later, no further work is needed. Go to step 10.

If the manufacture date is before March 18, 2014, continue with the next step to replace the throttle pedal.

NOTE: Not all body builders use the bolt, washer, and nut supplied by Freightliner Custom Chassis; studs may be used instead.

4. Remove the hardware that attaches the throttle pedal assembly to the firewall.
5. Remove the throttle pedal assembly. Continue holding the throttle pedal for the next step.

NOTE: It may be helpful to use a small bladed tool to disconnect the electrical connectors.

**August 2016
FL711A-D
NHTSA #16V-321**

6. Disconnect the electrical connectors and the adjustable pedal cable from the throttle pedal assembly.
7. Discard the throttle pedal assembly.
8. Connect the adjustable pedal cable to the new throttle pedal assembly and connect the electrical connectors.
9. Using new hardware, install the throttle pedal assembly. Tighten 13 lbf-ft (18 N·m).
10. Clean a spot on the base label (Form WAR259). Write the recall number, FL711, on a completion sticker (Form WAR260), and attach it to the base label.