OMB Control No.: 2127-0004

Part 573 Safety Recall Report

17V-001

Manufacturer Name: Volkswagen Group of America, Inc.

Submission Date: AUG 22, 2017 NHTSA Recall No.: 17V-001 Manufacturer Recall No.: 69P1



Manufacturer Information:

Manufacturer Name: Volkswagen Group of America, Inc.

Address: 3800 Hamlin Road

Auburn Hills MI 48326

Company phone: 1-800-893-5298

Population:

Number of potentially involved: 234,057 Estimated percentage with defect: NR

Vehicle Information:

Vehicle 1: 2011-2017 Audi Q5

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: Audi Q5: 234,057

Production Dates: MAY 28, 2010 - AUG 13, 2016

VIN Range 1: Begin: WA1LFBFP2BA000875 End: WA1M2AFP3HA030793 ✓ Not sequential

Description of Defect:

Description of the Defect: If the water drainage system of the panoramic sunroof becomes damaged or

impaired, e.g. during a repair, water could enter the side head curtain airbag canister. Due to a foam that is touching the airbag inflator, moisture could cause corrosion on the airbag inflator over time. If this happens, the airbag canister could fracture without airbag deployment, propelling fragments into the passenger compartment, striking and causing serious injury to vehicle

occupants.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: A corroded airbag inflator could fracture without airbag deployment,

propelling fragments into the passenger compartment, striking and causing

serious injury to vehicle occupants.

Description of the Cause: If the water drainage system of the panoramic sunroof is impaired, water

could enter a side head curtain airbag canister, causing corrosion over time.

The side head airbag curtain canister is helium-filled.

Identification of Any Warning None

that can Occur:

Supplier Identification:

Component Manufacturer

Name: iSi Automotive Austria GmbH

Address: Scheydgasse 32-32

Vienna FOREIGN STATES A-1210

Country: Austria

Chronology:

• June 14, 2016: Incident reported by FAW-VW (joint venture partner)

• June 21, 2016: Inspection of the vehicle in China by FAW-VW and iSi experts

• June 23, 2016: Results presented to the Product Safety Committee

- July 2016 ongoing:
- Affected vehicle produced by FAW-VW: buy-back in China for further investigation took five months; analysis of inflators, surrounding material (foam) and possible outside influences
- General investigation of construction, history, approval process, supplier change, comparison to other vehicles and inflators, root cause (water ingress)
- Identification and testing of preventive measure in production, decision for implementation (Germany production July 25, 2016, China production Aug 8, 2016)
- Elaborate field analysis in China and Germany, buyback of several vehicles for even more detailed analysis
- Evaluation of influencing factors in local production in China (e.g. locally sourced foam)
- Assessment of field analysis, evaluation of potential remedies for vehicles in the market
- November 11, 2016: Incident reported in Israel (vehicle produced by Audi AG)
- November 16, 2016: Inspection of the vehicle in Israel by an AUDI AG expert
- November 20, 2016: China vehicle finally bought back after 5 months due to Chinese vehicle registration processes - ongoing elaborate analysis of the car
- November 2016 ongoing: Determination of repair procedure for dealers
- December 21, 2016: Meeting with NHTSA on this issue
- December 23, 2016: Determination of a defect by the Product Safety Committee

Description of Remedy:

Description of Remedy Program: Inspect vehicle for evidence of water ingress, examination of drainage system, disassembly of headliner and trim. Remove foam and inspect side head curtain airbag canister for relevant corrosion.

- In case of light surface corrosion a wax will be applied to the inflator.
- In case of more than light surface corrosion, the inflator will be replaced after a robustness check.

from Recalled Component:

How Remedy Component Differs Headliner foam piece will be removed. Corroded canister will be replaced.

Part 573 Safety Recall Report

17V-001

Page 3

Identify How/When Recall Condition In July 2016, the production process was modified to include a plastic was Corrected in Production: sleeve over the side head airbag curtain canister.

Recall Schedule:

Description of Recall Schedule: Dealers/customer notification planned for February 2017

Planned Dealer Notification Date : FEB 07, 2017 - NR Planned Owner Notification Date : MAR 03, 2017 - NR

* NR - Not Reported