OMB Control No.: 2127-0004

Part 573 Safety Recall Report

Manufacturer Name : Subaru of America, Inc. Submission Date : AUG 22, 2017 NHTSA Recall No.: 17V-016 Manufacturer Recall No.: TKC-17

Manufacturer Information :

Manufacturer Name : Subaru of America, Inc. Address: P.O. Box 6000 Cherry Hill NJ 08034-6000 Company phone : 856-488-8500

Vehicle Information :

008 Subaru Imprez EHICLES	a			
		LIGHT VEHICLES		
Not all vehicles in the specified production date range are affected by this recall. This recall affects Takata Non-Desiccated Frontal Passenger-side Air Bag Inflators containing Phase Stabilized Ammonium Nitrate for Zone C, for vehicles not already covered under NHTSA Campaign Numbers 14V763, 15V323 and 16V361. Zone C includes states with lower temperature cycling and absolute humidity. It includes: Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, and Wyoming. Impreza includes WRX and STI.				
0005 UU 00 000				
2005 - JUL 03, 200 NR	End: NR	□ Not convertial		
INIK	LIIU. NK	☐ Not sequential		
008 Subaru Tribeca	3			
LIGHT VEHICLES				
SUV				
fects Takata Non-D Passenger-side Air For Zone C, for vehi , 15V323 and 16V3	Desiccated Bag Inflators containin icles not already covere 361.	cling and absolute humidity. It		
3,	3, 15V323 and 16V3	for Zone C, for vehicles not already covere 3, 15V323 and 16V361. includes states with lower temperature cy s: Alaska, Colorado, Connecticut, Idaho, Iov		



17V-016

Population :

Number of potentially involved : 62,764 Estimated percentage with defect : 100 %

Part 573 Safety Recall Report

17V-016

Page 2

			0	ton, Wisconsin	i, and wyonning.
Production Dates :				ND	
VIN Range 1:E	legin :	NR	End :	NR	Not sequential
Vehicle 3:	2006-2008 Sul	oaru Imprez	a		
Vehicle Type :	LIGHT VEHICL	ES			
Body Style :	STATIONWAGON				
Power Train :	GAS				
-	recall affects Ta	akata Non-D	esiccated	C	e are affected by this recall. This
		e C, for vehi	cles not alre		hase Stabilized Ammonium 1der NHTSA Campaign Number
	includes: Alask	a, Colorado,	Connecticut	t, Idaho, Iowa, I	g and absolute humidity. It Maine, Massachusetts, Michigan
			-		th Dakota, Oregon, Rhode Islan , and Wyoming.
	Impreza includ	es WRX and	STI.		
Production Dates :	MAY 31, 2005 ·	JUL 03, 200	8		
VIN Range 1:E	legin :	NR	End :	NR	☐ Not sequentia
Vehicle 4 ·	2005-2006 Sul	aru Baia			
Vehicle Type :		-			
Body Style :					
Power Train :					
Descriptive Information :	Not all vehicles	in the speci	fied product	tion date range	e are affected by this recall. This
	recall affects Ta			0	5
					hase Stabilized Ammonium
				ady covered ur	nder NHTSA Campaign Number
	14V763, 15V32 Zone C include:			erature cyclin	g and absolute humidity. It
			-		Maine, Massachusetts, Michiga
			-		th Dakota, Oregon, Rhode Islan
	South Dakota, I	Utah, Vermo	nt, Washing	ton, Wisconsin	, and Wyoming.
Production Dates :	JAN 05, 2004	APR 12, 200	6		
VIN Range 1: E	legin :	NR	End :	NR	Not sequentia
Vehicle 5	2006-2006 Saa	h 9-2X			
Vehicle Type :					
• •	STATIONWAG				
Power Train :					
-	Not all vehicles recall affects Ta	-	-	tion date range	e are affected by this recall. This

art 573 Safety	y Reca	ll Rep	ort	17V-016	Page 3
	14V763, 15V Zone C includ includes: Ala Minnesota, M South Dakota MAY 31, 200	323 and 16V des states wi ska, Colorado fontana, New a, Utah, Verm	7361. th lower temperature c o, Connecticut, Idaho, Io 7 Hampshire, New York 10nt, Washington, Wisco		lity. It s, Michigan,
viiv kange 1. D	egin .		Enu. NA		sequentiai
Description of Defect :					
- FMVSS 1	specified Order in 1 Subaru is Remedy (: NR	in the May 4 EA15-001. submitting t	, 2016 Amendment to t	in accordance with the ter he November 3, 2015 Cons with section 46 of Coordina	sent
FMVSS 2 Description of the Safety Risl	x : Activation propellar metal frag	nt may result gments to pa	in an inflator rupture. A ss through the air bag a	An inflator rupture may ca and into the vehicle interio	use
Description of the Cause	e: Based up subject in combusti creates es	on Takata's i Iflators may (on in the eve	nvestigation to date, th degrade over time, which nt the air bag is activat rnal pressure when the	th to vehicle occupants. e propellant wafers in som ch could lead to overaggre ed. Overly aggressive com inflator is activated, whicl	ssive bustion
Identification of Any Warnin that can Occur	ng NR		,		
Supplier Identification :					
Component Manufacturer					
Name : Takata Corporat Address : Tokyo Front Ter					
v		inagawa-ku, '	Tokyo FOREIGN STATE	S 140-0002	
Chronology :					
November 3, 2015 - NHTSA	and Takata e	entered into a	a Consent Urder in EA1	5-UU1 to resolve issues rai	ised in
The inf	ormation cont	ained in this re	port was submitted pursua	ant to 10 CED 8572	

The information contained in this report was submitted pursuant to 49 CFR \$573

Part 573 Safety Recall Report

17V-016

Page 4

that investigation, to mitigate and control risks of harm, and to promote public safety. May 4, 2016 - NHTSA and Takata entered into an Amendment to the November 3, 2015 Consent Order. As stated in that Amendment, on the basis of testing and analysis conducted by Takata and by independent research organizations, NHTSA has concluded that, "at some point in the future all non-desiccated frontal Takata PSAN inflators will reach a threshold level of degradation that could result in the inflator becoming unreasonably dangerous." As a result of this conclusion, and pursuant to Paragraph 29 of the November 3, 2015 Consent Order, NHTSA ordered Takata to file certain defect information reports ("DIR"), in accordance with the schedule set forth in Paragraph 14 of the Amendment.

May 16, 2016 - As specified in that schedule, Takata submitted the DIR.

May 20, 2016 - Subaru has determined to launch recall according to Section 46 of Coordinated Remedy Order. January 3, 2017 - As specified in that schedule, Takata submitted the DIR.

January 10, 2017 - Subaru has determined to launch recall according to Section 32 of 3rd amended Coordinated Remedy Order.

Description of Remedy :

Description of Remedy Program :	The remedy plan calls for dealers to replace the passenger airbag inflator.
How Remedy Component Differs from Recalled Component :	
Identify How/When Recall Condition was Corrected in Production :	NR

Recall Schedule :

Description of Recall Schedule :	If parts supply is sufficient, Subaru will send owner notification letters advising the customer to schedule a repair. If parts supply is insufficient, Subaru will send interim notification letters advising the customer they are affected and will be re-notified when parts supply improves.
Planned Dealer Notification Date : Planned Owner Notification Date :	

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR $\S573$