

Part 573 Safety Recall Report

17V-051

Manufacturer Name : Toyota Motor Engineering & Manufacturing**Submission Date :** JAN 24, 2017**NHTSA Recall No. :** 17V-051**Manufacturer Recall No. :** HOC**Manufacturer Information :**

Manufacturer Name : Toyota Motor Engineering & Manufacturing
Address : 19001 South Western Avenue
 Torrance CA 90501
Company phone : 1-800-331-4331

Population :

Number of potentially involved : 72,847
Estimated percentage with defect : NR

Vehicle Information :**Vehicle 1 :** 2016-2017 Toyota Tundra**Vehicle Type :****Body Style :****Power Train :** NR

Descriptive Information : (1) Although the involved vehicles are within the above production period range, not all vehicles in this range were sold in the U.S.
 (2) Only vehicles equipped with resin rear step bumpers and resin reinforcement brackets are affected; Tundra vehicles equipped with a chrome coated steel rear step bumper and steel reinforcement bracket are not affected.
 (3) No other Toyota or Lexus vehicles utilize the same material or structure of the rear bumper reinforcement bracket as the affected vehicles.

Production Dates : JUL 29, 2015 - DEC 22, 2016**VIN Range 1 : Begin :**

NR

End : NR Not sequential**Description of Defect :**

Description of the Defect : The subject vehicles are equipped with resin rear step bumpers and resin reinforcement brackets at the outboard corners. In the event of a longitudinal impact to the bumper, the resin bracket may become damaged. If this were to occur and a person steps on the corner of the bumper, a portion of the bumper may break away, which could cause the person to fall, increasing the risk of injury.

FMVSS 1 : NR**FMVSS 2 :** NR

Description of the Safety Risk : In the event of a longitudinal impact to the bumper, the resin bracket may become damaged. If this were to occur and a person steps on the corner of the bumper, a portion of the bumper may break away, which could cause the person to fall, increasing the risk of injury.

Description of the Cause : NR
Identification of Any Warning NR
that can Occur :

Supplier Identification :

Component Manufacturer

Name : Flex-N-Gate Oklahoma, LLC
Address : One General Street
Ada OKLAHOMA 74820
Country : United States

Chronology :

Please see the attached Part 573 Defect Information Report for full chronology.

Description of Remedy :

Description of Remedy Program : All known owners of the subject vehicles will be notified by first class mail to return their vehicles to a Toyota dealer. The dealer will replace the resin rear bumper reinforcement brackets with steel ones at no cost. In addition, the rear bumper tread covers will be replaced as part of the remedy repair. The owner letter will instruct vehicle owners who have paid to have this condition remedied prior to this campaign to seek reimbursement pursuant to Toyota's General Reimbursement Plan.

How Remedy Component Differs NR
from Recalled Component :

Identify How/When Recall Condition NR
was Corrected in Production :

Recall Schedule :

Description of Recall Schedule : Notifications to owners will occur by March 25, 2017. A copy of the draft owner notification letter will be submitted as soon as available. Notifications to distributors/dealers will be sent on January 24, 2017. Copies of dealer communications will be submitted as they are issued.

Planned Dealer Notification Date : JAN 24, 2017 - JAN 24, 2017
Planned Owner Notification Date : FEB 15, 2017 - MAR 25, 2017

* NR - Not Reported