

Part 573 Safety Recall Report

17V-097

Manufacturer Name : Chrysler (FCA US LLC)**Submission Date :** FEB 14, 2017**NHTSA Recall No. :** 17V-097**Manufacturer Recall No. :** T03**Manufacturer Information :**

Manufacturer Name : Chrysler (FCA US LLC)

Address : 800 Chrysler Drive
CIMS 482-00-91 Auburn Hills MI
48326-2757

Company phone : 1-800-853-1403

Population :

Number of potentially involved : 69,298

Estimated percentage with defect : 3 %

Vehicle Information :

Vehicle 1 : 2014-2017 Dodge Charger

Vehicle Type :

Body Style : 4-DOOR

Power Train : NR

Descriptive Information : 2014-2017 MY Dodge Charger ("LD") with AWD

Production Dates : APR 01, 2014 - JUN 30, 2016

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 2 : 2014-2017 Chrysler 300

Vehicle Type :

Body Style : 4-DOOR

Power Train : NR

Descriptive Information : Some 2014-2017 MY Chrysler 300 ("LX") with AWD

Production Dates : APR 01, 2014 - JUN 30, 2016

VIN Range 1 : Begin : NR End : NR

 Not sequential**Description of Defect :**

Description of the Defect : Some 2014-2017 MY Chrysler 300 ("LX") and Dodge Charger ("LD") all-wheel drive vehicles may experience loose front propshaft bolts which may result in a disconnected front propshaft.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : A disconnected front propshaft may contact the road surface, detach from the vehicle while driving or may result in damage to powertrain and underbody components which may lead to a loss of motive power.

Description of the Cause : NR

Identification of Any Warning that can Occur : A customer may notice excessive noise and vibration in the vehicle prior to a failure.

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

Please see the attached supplemental information titled "FCA US LLC Chronology - T03 2014-2017 MY LX_LD Front Propshaft Bolts - 02142017.pdf"

Description of Remedy :

Description of Remedy Program : FCA US will conduct a Voluntary Safety Recall on all affected vehicles to replace all eight front propshaft bolts on all affected 2014-2017 MY LX and LD AWD vehicles.

FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : *02/14/17 - FCA US will begin notifying dealers and owners on or about 3/31/2017.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported