OMB Control No.: 2127-0004

Not sequential

Part 573 Safety Recall Report

17V-184

Manufacturer Name: Nissan North America, Inc.

Submission Date: AUG 28, 2017 **NHTSA Recall No.:** 17V-184

Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: Nissan North America, Inc.

Address: P. O. BOX 685001

Franklin TN 37068-5009

Company phone: 800-647-7261

Population:

Number of potentially involved: 56,766 Estimated percentage with defect: NR

Vehicle Information:

Vehicle 1: 2013-2014 Nissan Murano

Vehicle Type: LIGHT VEHICLES

Body Style : SUV Power Train : GAS

Descriptive Information: No other Nissan or Infiniti vehicles are affected by this issue because the affected hose

clamps were installed on models that were manufactured during the above dates.

Production Dates: JUL 18, 2013 - AUG 28, 2014

VIN Range 1 : Begin : NR End : NR

Vehicle 2: 2013-2014 Nissan Murano Cross Cabriolet

Vehicle Type: LIGHT VEHICLES

Body Style: SUV Power Train: GAS

Descriptive Information: No other Nissan or Infiniti vehicles are affected by this issue because the affected hose

clamps were installed on models that were manufactured during the above dates.

Production Dates: JUL 18, 2013 - MAR 28, 2014

VIN Range 1 : Begin : NR End : NR Not sequential

Description of Defect:

Description of the Defect: Due to a manufacturing error at the supplier (LS-Mtron), an incorrect clamp

diameter may allow the power steering hose to separate. If hose separation occurs, power steering fluid may leak, and the operator may experience a gradual increase in steering effort. However, in certain rare instances, if the power steering fluid leaks onto a heat source, it may lead to a thermal incident.

FMVSS 1: NR FMVSS 2: NR Description of the Safety Risk: In the even that leaking power steering fluid contacts a heat source, a thermal

incident can occur.

Description of the Cause: NR

Identification of Any Warning NR

that can Occur:

Supplier Identification:

Component Manufacturer

Name: LS-Mtron Ltd.

Address: 11th floor, LS Tower, LS-ro, Dongan-gu,

Anyang, Gyeonggi-do FOREIGN STATES

Country: Korea, Republic of

Chronology:

In 2016, Nissan became aware of a single incident involving the subject vehicle that occurred in a foreign market. Initial investigation into this issue by the supplier indicated that the power steering hose separation was caused by abnormal usage in high temperature conditions. The issue could not be duplicated, and initial parts collection showed no abnormalities. However, Nissan continued field monitoring and parts collection.

In January 2017, after identifying several additional incidents in overseas markets and one unconfirmed incident in the U.S. market that was potentially attributable to the subject condition, Nissan began to study if this issue could potentially affect vehicles sold in the U.S. market.

In early February 2017, Nissan collected parts from U.S. vehicles and sent them for analysis.

In March 2017, an analysis of the subject parts showed that sealing clamp performance had deteriorated on the parts that were collected, which could increase the potential for power steering fluid leakage.

March 9, 2017 – Based on the results of the parts collection activity, Nissan decided to conduct a Safety Recall Campaign and report in accordance with the defect notification requirements specified in 49 CFR Part 573.

Description of Remedy:

Description of Remedy Program: The dealer will install a power steering high pressure hose kit to remedy

the vehicles.

Nissan will include a statement in the Part 577 owner notification concerning reimbursement for the cost of obtaining a pre-notification

remedy.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: Nissan will notify all owners of potentially affected vehicles within 60

days.

Planned Dealer Notification Date : APR 04, 2017 - NR Planned Owner Notification Date : MAY 10, 2017 - NR

^{*} NR - Not Reported