Part 573 Safety Recall Report

Kia Motors America
AUG 23, 2017
17V-224
SC147
4

Manufacturer Information :

Manufacturer Name :	Kia Motors America
---------------------	--------------------

Address : 111 Peters Canyon Road Irvine CA 92606

Company phone : 800-333-4542

Vehicle Information :

Vehicle 1:	2011-2014 Kia (Optima			
Vehicle Type :	LIGHT VEHICLE	S			
Body Style :	ALL				
Power Train :	GAS				
Descriptive Information :	 All 2011-2013 MY Optima vehicles equipped with the 2.4L Gasoline Direct Injection (GDI) and 2.0L Turbocharged GDI (T-GDI) engines produced from August 12, 2010 through September 27, 2013; All 2014 MY Optima vehicles equipped with the 2.4L Gasoline Direct Injection (GDI) and 2.0L Turbocharged GDI (T-GDI) engines produced at KMMG from August 28, 2013 through May 15, 2014, with engines supplied by Hyundai Motor Manufacturing Alabama; (443,825 vehicles) 				
Production Dates :	AUG 12. 2010 - N	MAY 15. 2014			
VIN Range 1:1		NR	End :	NR	Not sequential
	GAS • All 2011 Direct Injection 30, 2013. (8,417)	-2013 MY Sport (T-GDI) engines 7 vehicles)		nicles equipped with the 2 ced from December 30, 20	
VIN Range 1:1		NR	End :	NR	Not sequential
Valida O	9019 9014 VI- 0				
	2012-2014 Kia S LIGHT VEHICLE				
Body Style :		J			
Power Train :					
The ir	nformation containe	d in this report wa	as submi	tted pursuant to 49 CFR §573	



Number of potentially involved : 618,160 Estimated percentage with defect : 2 %

Population :

17V-224

	All 2012-2014 MY Sorente njection (GDI) engines produced 165,918 vehicles)			
Production Dates : A VIN Range 1 : Be	PR 19, 2011 - FEB 10, 2014 gin : NR E	End : NR	Not se	quential
Description of the Defect	: Metal debris may have been ge part of the manufacturing of th completely removed from the process. In addition, the mach uneven surface roughness. As roughness can restrict oil flow temperatures causing prematu will produce a cyclic knocking	he engine crankshaft wh crankshaft's oil passage ining processes of the c a result, the metal debu to the bearings, thereb ure bearing wear. A wo	nich may not have b es during the cleanin rankpins caused an ris and uneven surfa by increasing bearing rn connecting rod b	een ng nce g vearing
	illumination of the engine war instrument panel. If the warn be driven, the bearing may fail	ings are ignored and the	e vehicle is continue	
FMVSS 1 FMVSS 2				
Description of the Safety Risk Description of the Cause	An engine stall at higher speed: N/A	ls can increase the risk	of a crash.	
			ressure warning lan	

Component Manufacturer

Name : N/A Address : NR NR

Country: NR

Chronology :

See attached document titled "Theta Engine Chronology"

The information contained in this report was submitted pursuant to 49 CFR \$573

Description of Remedy :

Description of Remedy Program :	All owners of the subject vehicles will be notified by first class mail with instructions to bring their vehicles to a Kia dealer. Dealers will be instructed to inspect the engine assembly and replace, if necessary. Kia will reimburse owners for repair expenses already incurred pursuant to Kia's General Reimbursement Plan filed March 21, 2016.
How Remedy Component Differs from Recalled Component :	N/A
	The engine plant processes/operations were improved in August 2013 at the Hwasung plant and during the production of the 2014 model year at the Hyundai Motor Manufacturing Alabama plant.
Recall Schedule :	

Description of Recall Schedule : The dealer notification began on 5/22/2017 and the owner notification started 6/20/2017 and will continue through 10/24/2017. Planned Dealer Notification Date : MAY 22, 2017 - MAY 22, 2017 Planned Owner Notification Date : JUN 20, 2017 - OCT 24, 2017

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573