# Part 573 Safety Recall Report

Manufacturer Name :Aston Martin Lagonda of North AmericaSubmission Date :JUN 21, 2017NHTSA Recall No. :17V-390Manufacturer Recall No. :RA-07-0023

### Manufacturer Information :

Manufacturer Name : Aston Martin Lagonda of North Address : Banbury Road Gaydon Warwick, United Kingdom 00 CV35 0DB Company phone : 999

### **Population :**

Number of potentially involved :6Estimated percentage with defect :23 %

### Vehicle Information :

Vehicle 1:	2012-2012 Aston Martin V8 Vantage
Vehicle Type :	LOW VOLUME VEHICLES
Body Style :	2-DOOR
Power Train :	GAS
Descriptive Information :	2 Door Sports Cars SportShift 6 Speed ASM Transmission
Production Dates :	OCT 13, 2011 - NOV 15, 2011
VIN Range 1:	Begin : SCFEFBBK4CGD15995 End : SCFEFBAK4CGC16112  Vot sequential

### **Description of Defect :**

Description of the Defect :	In October 2011, a connector in the hydraulic system for the 6-speed Auto-Shift Manual (ASM) transmission was redesigned. After redesigning the installation for the connector, it was discovered that due to movement in the connector assembly, it is possible in some circumstances for the connector to fail, causing leakage of hydraulic fluid.	
FMVSS 1 :	NR	
FMVSS 2 :	NR	
Description of the Safety Risk :	Vehicle will stop and be unable to proceed.	
Description of the Cause :	<ul> <li>There have not been any reported injuries relating to this issue and no reports had been received from the US. There have been no further reports of this concern during the period of our investigations.</li> <li>If the fluid leaks, the fluid level will drop and the following can occur: <ul> <li>traces of hydraulic fluid may be seen beneath the vehicle;</li> <li>at start-up, an "Unable to select gears" warning will show in the driver's display and the transmission will not change from Neutral or Park into a gear. The driver will be unable to move the vehicle;</li> </ul> </li> </ul>	
The information contained in this report was submitted pursuant to 49 CFR §573		



### 17V-390

## Part 573 Safety Recall Report

Page 2

• while driving, an "Unable to select gears" warning will flash and the driver can continue in the same gear until they choose a place to stop. In this condition, if the driver operates the brakes, the engine can be stalled as the vehicle comes to a stop;

• if, in the case above there is sufficient pressure remaining in the hydraulic system, the transmission will select emergency neutral as the vehicle comes to a stop.

Identification of Any Warning None that can Occur :

### **Supplier Identification :**

#### **Component Manufacturer**

Name : NR Address : NR NR

Country: NR

### **Chronology**:

In April 2017, we were notified about driveability problems on V8 Vantage Sportshift vehicles. The vehicles were 10,11 and 12.5 model years (manufactured from 12/2010 to 08/2012). We immediately launched an investigation into the issue.

From April 2017 to June 2017, an internal investigation was initiated into the possible cause of driveability and gear-shifting problems. A Service Bulletin to repair a leaking clutch feed pipe was issued on 6-Speed Sportshift. We reviewed the Service Bulletin and it was determined that the failure rate had increased with vehicle age and mileage.

A recommendation was made by the Critical Concerns Review Group (CCRG) to progress the matter to the Recall Committee on 5 June, 2017.

A Recall Committee convened on June 15, 2017 and determined to launch a Recall of all vehicles that still have not had the Service Action completed.

### **Description of Remedy :**

Description of Remedy Program :	Remedy
	The clutch pipe, connector assembly, related brackets and parts on the
	affected vehicles will be replaced with parts known to be reliable in
	operation.
	Reimbursement Plan
	Owners of all potentially affected vehicles will be notified to take their
	vehicle to an Aston Martin dealer. The connector for clutch fluid pipe, the
	pipe and related brackets will be replaced at no cost to the owner.
How Remedy Component Differs	Addition of a stability bracket to the fluid line coupling.
from Recalled Component :	
Identify How/When Recall Condition	Final production cars had no bracket fitted, but are included in the scope
was Corrected in Production :	
was corrected in Froduction .	

### **Recall Schedule :**

Description of Recall Schedule :	It is Aston Martin's intention to notify all customers who are listed in the table above. Aston Martin will provide copies of the notification schedule,
	including mail dates for the owner letter.
Planned Dealer Notification Date :	JUN 23, 2017 - JUN 23, 2017
Planned Owner Notification Date :	JUL 07, 2017 - AUG 07, 2017

\* NR - Not Reported