

Part 573 Safety Recall Report

17V-416

Manufacturer Name : Toyota Motor Engineering & Manufacturing**Submission Date :** JUN 29, 2017**NHTSA Recall No. :** 17V-416**Manufacturer Recall No. :** HOK**Manufacturer Information :**

Manufacturer Name : Toyota Motor Engineering & Manufacturing
Address : 19001 South Western Avenue
 Torrance CA 90501
Company phone : 1-800-331-4331

Population :

Number of potentially involved : 5
Estimated percentage with defect : 100 %

Vehicle Information :**Vehicle 1 :** 2016-2016 Toyota Tundra**Vehicle Type :****Body Style :****Power Train :** NR

Descriptive Information : This issue only involves certain 2016MY Toyota Tundra vehicles produced at TMMTX involving a specific assembly location for the passenger knee airbag module. These passenger knee airbags were installed on May 27, 2016. No other Toyota or Lexus vehicles sold in the U.S. are affected.

Production Dates : MAY 27, 2016 - MAY 27, 2016**VIN Range 1 : Begin :** NR **End :** NR Not sequential**Description of Defect :**

Description of the Defect : The involved vehicles are equipped with a passenger knee airbag module that is attached to the instrument panel mounting brackets by three bolts. During vehicle assembly, there is a possibility that incorrect bolts were installed using the torque specifications of the correct bolts. This could potentially affect the clamping performance of the bolts over time, which could in turn affect the performance of the knee airbag, increasing the risk of injury during a crash.

FMVSS 1 : NR**FMVSS 2 :** NR

Description of the Safety Risk : This could potentially affect the clamping performance of the bolts over time, which could in turn affect the performance of the knee airbag, increasing the risk of injury during a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

Please see the attached Part 573 Defect Information Report for the full chronology.

Description of Remedy :

Description of Remedy Program : On June 23, Toyota was made aware that during a service appointment on June 22, the remaining Tundra vehicle suspected of having incorrect bolts was inspected. It was found to have incorrect bolts, and those bolts were replaced with the correct ones. As a result, there are no remaining vehicles in the U.S. that have this condition and this recall is complete. No further quarterly reporting will be provided. A reimbursement plan is not applicable. As the repairs during the aforementioned activities occurred well within the active period of the Toyota New Vehicle Limited Warranty ("Warranty"), the involved vehicle owners for this recall would have been provided a repair at no cost under Toyota's Warranty.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : There are no remaining vehicles in the U.S. that have this condition and this recall is complete. See Section 7 of the attached Part 573 Defect Information Report.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported