

Part 573 Safety Recall Report

17V-450

Manufacturer Name : Daimler Trucks North America LLC

Submission Date : JUL 17, 2017

NHTSA Recall No. : 17V-450

Manufacturer Recall No. : FL744



Manufacturer Information :

Population :

Manufacturer Name : Daimler Trucks North America LLC

Address : 4747 N. Channel Avenue

Portland OR 97217-3849

Company phone : 800-745-8000

Number of potentially involved : 74

Estimated percentage with defect : 2 %

Vehicle Information :

Vehicle 1 : 2017-2018 Freightliner Freightliner 122SD

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Vehicles built with certain Cummins ISX15 engines

Production Dates : OCT 05, 2016 - MAY 10, 2017

VIN Range 1 : Begin : NR End : NR ☐ Not sequential

Vehicle 2 : 2017-2018 Freightliner Custom Chassis Freightliner Custom Chassis XCM & XCP

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Vehicles built with certain Cummins ISX15 engines

Production Dates : OCT 05, 2016 - MAY 10, 2017

VIN Range 1 : Begin : NR End : NR ☐ Not sequential

Vehicle 3 : 2017-2018 Western Star Western Star 4900 & 6900

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Vehicles built with certain Cummins ISX15 engines

Production Dates : OCT 05, 2016 - MAY 10, 2017

VIN Range 1 : Begin : NR End : NR ☐ Not sequential

Description of Defect :

Description of the Defect : See Cummins Defect Information Report. NHTSA Recall 17E-029 which states "The drive gear on the fuel pump may spin loose on the drive shaft, resulting in the loss of pumping function. If this occurs, the engine may stall without warning and cannot be restarted."

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : See Cummins Defect Information Report. NHTSA Recall 17E-029 which states "An unexpected engine stall without the ability to restart may increase the risk of a crash"

Description of the Cause : NR

Identification of Any Warning
that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Cummins Inc

Address : 500 Jackson Street
Columbus INDIANA 47201

Country : United States

Chronology :

June 2017 – Cummins notified DTNA of NHTSA Recall 17E-029 and DTNA began investigation

July 2017 – DTNA decided to conduct a voluntary safety campaign to recall affected vehicles

Description of Remedy :

Description of Remedy Program : Cummins is conducting this recall. Cummins will install a new fuel pump. Repairs will be performed by Cummins authorized service facilities. For further information and reimbursement plan please see Cummins Defect Information Report NHTSA Recall 17E-029.

How Remedy Component Differs
from Recalled Component : NR

Identify How/When Recall Condition
was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : See Cummins Defect Information Report. NHTSA Recall 17E-029 which states "The timing of owner notification will be determined in consultation with the affected OEMs. Owner notification will commence promptly after the receipt of each vehicle OEMs customer contact information."

Planned Dealer Notification Date : SEP 14, 2017 - SEP 14, 2017

Planned Owner Notification Date : SEP 14, 2017 - SEP 14, 2017

* NR - Not Reported