

Part 573 Safety Recall Report

17V-490

Manufacturer Name : Jaguar Land Rover North America, LLC**Submission Date :** AUG 04, 2017**NHTSA Recall No. :** 17V-490**Manufacturer Recall No. :** N074**Manufacturer Information :****Population :**

Manufacturer Name : Jaguar Land Rover North America, LLC

Number of potentially involved : 1

Address : 555 MACARTHUR BOULEVARD

Estimated percentage with defect : 100 %

MAHWAH NJ 07430

Company phone : 8188500

Vehicle Information :

Vehicle 1 : 2017-2017 Land Rover Range Rover

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : 2017 MY Land Rover Range Rover vehicle in select VIN range. It was identified that during the assembly of the high pressure fuel pump a mixed condition of the fixings had been used for the high pressure fuel pump installation process. The correct length bolts for this application should be 25mm, but some 30mm length bolts were used. The 30mm bolts 'bottomed out' in the blind tapped hole and this led to the high pressure fuel pump not being secured properly.

Production Dates : MAY 18, 2017 - MAY 18, 2017

VIN Range 1 : Begin : SALGS2FV2HA354687 End : SALGS2FV2HA354687 Not sequential**Description of Defect :**

Description of the Defect : On one 2017 Model Year (MY) 3.0L Gasoline Land Rover Range Rover vehicle, one or both of the fixing bolts used to attach the high pressure fuel pumps may be too long and not secure the high pressure fuel pump as required. During normal vehicle usage, vibration of the high pressure fuel pump can lead to a fracture of a brazed joint on the low pressure fuel input pipe. This can lead to a liquid fuel leak into the engine bay.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Should leaking fuel come into contact with a sufficiently hot surface there is an increased risk of fire.

Description of the Cause : NR

Identification of Any Warning that can Occur : Fuel odor may be noticed by the driver and they may also observe liquid fuel underneath the vehicle.

Supplier Identification :**Component Manufacturer**

Name : Ford Motor Company
Address : Bridgend
Wales FOREIGN STATES
Country : United Kingdom

Chronology :

Attachment

Description of Remedy :

Description of Remedy Program : The owner will be notified and instructed to take the vehicle to an approved Jaguar dealer who will replace both fuel pumps and associated fuel lines. The fixing bolts will be replaced with the correct specification parts.

There will be no charge to owners for this repair.

How Remedy Component Differs from Recalled Component : Part Numbers: High Pressure Fixing Bolt AJ810551

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Distribution of owner notification letters will occur on or before September 26, 2017. Notifications to dealers will occur on August 9, 2017
Planned Dealer Notification Date : AUG 25, 2017 - AUG 25, 2017
Planned Owner Notification Date : SEP 26, 2017 - SEP 26, 2017

* NR - Not Reported