

Part 573 Safety Recall Report

17V-562

Manufacturer Name : Chrysler (FCA US LLC)**Submission Date :** OCT 10, 2017**NHTSA Recall No. :** 17V-562**Manufacturer Recall No. :** T51**Manufacturer Information :**

Manufacturer Name : Chrysler (FCA US LLC)

Address : 800 Chrysler Drive
CIMS 482-00-91 Auburn Hills MI
48326-2757

Company phone : 1-800-853-1403

Population :

Number of potentially involved : 443,874

Estimated percentage with defect : 1 %

Vehicle Information :

Vehicle 1 : 2013-2017 Ram 3500

Vehicle Type :

Body Style : PICKUP TRUCK

Power Train : NR

Descriptive Information : 2013-2017 MY Ram 3500 ("D2") vehicles equipped with the Cummins 6.7L Turbo Diesel engine (Sales Code ETK) and Concentric water pump without the vent hole. Vehicles in the recall population were built from October 24, 2012, start of production for 2013 MY Ram Trucks to February 28, 2017. Similar vehicles not included in the recall population were built with either a Concentric water pump with a vent hole, or a non-Concentric water pump.

Production Dates : OCT 24, 2012 - FEB 28, 2017

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2013-2017 Ram 3500 Cab Chassis

Vehicle Type :

Body Style : PICKUP TRUCK

Power Train : NR

Descriptive Information : 2013-2017 MY Ram 3500 Cab Chassis ("DD") vehicles equipped with the Cummins 6.7L Turbo Diesel engine (Sales Code ETK) and Concentric water pump without the vent hole. Vehicles in the recall population were built from October 24, 2012, start of production for 2013 MY Ram Trucks to February 28, 2017. Similar vehicles not included in the recall population were built with either a Concentric water pump with a vent hole, or a non-Concentric water pump.

Production Dates : OCT 24, 2012 - FEB 28, 2017

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 3 : 2013-2017 Ram 2500

Vehicle Type :

Body Style : PICKUP TRUCK

Power Train : NR

Descriptive Information : 2013-2017 MY Ram 2500 ("DJ") vehicles equipped with the Cummins 6.7L Turbo Diesel engine (Sales Code ETK) and Concentric water pump without the vent hole. Vehicles in the recall population were built from October 24, 2012, start of production for 2013 MY Ram Trucks to February 28, 2017. Similar vehicles not included in the recall population were built with either a Concentric water pump with a vent hole, or a non-Concentric water pump.

Production Dates : OCT 24, 2012 - FEB 28, 2017

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 4 : 2013-2017 Ram 4500/5500 Cab Chassis

Vehicle Type :

Body Style : PICKUP TRUCK

Power Train : NR

Descriptive Information : 2013-2017 MY Ram 4500/5500 Cab Chassis ("DP") vehicles equipped with the Cummins 6.7L Turbo Diesel engine (Sales Code ETK) and Concentric water pump without the vent hole. Vehicles in the recall population were built from October 24, 2012, start of production for 2013 MY Ram Trucks to February 28, 2017. Similar vehicles not included in the recall population were built with either a Concentric water pump with a vent hole, or a non-Concentric water pump.

Production Dates : OCT 24, 2012 - FEB 28, 2017

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 5 : 2013-2017 Ram 3500 Cab Chassis with a GVWR less than 10,000 lbs

Vehicle Type :

Body Style : PICKUP TRUCK

Power Train : NR

Descriptive Information : 2013-2017 MY Ram 3500 Cab Chassis with a GVWR less than 10,000 lbs ("DF") equipped with the Cummins 6.7L Turbo Diesel engine (Sales Code ETK) and Concentric water pump without the vent hole. Vehicles in the recall population were built from October 24, 2012, start of production for 2013 MY Ram Trucks to February 28, 2017. Similar vehicles not included in the recall population were built with either a Concentric water pump with a vent hole, or a non-Concentric water pump.

Production Dates : OCT 24, 2012 - FEB 28, 2017

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : Some 2013-2017 MY D2, DD, DJ, DP, and DF trucks equipped with the Cummins 6.7L Turbo Diesel engine (Sales Code ETK) may experience a water pump failure which may result in an engine compartment fire, resulting in an increased risk of injury to motor vehicle occupants or persons outside the vehicle.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : A water pump failure may occur which may result in an engine compartment fire and an increased risk of injury to motor vehicle occupants or persons outside the vehicle.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Cummins

Address : 500 Jackson Street
Columbus INDIANA

Country : United States

Chronology :

Please see the attached supplemental information titled "FCA US LLC Chronology – Cummins, Concentric Water Pump – 10102017.pdf".

Description of Remedy :

Description of Remedy Program : FCA US will conduct a voluntary safety recall to replace water pumps with new water pumps with corrective features including a vent hole.

FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.

How Remedy Component Differs from Recalled Component : Part Name: Water Pump
Part Description: Water pump
Part Number: 68210961AA
Comment: Remedy component is distinguished by implementation of water pump vent hole

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : ** 09/12/2017: FCA US will notify dealers and begin notifying owners on or about November 1, 2017.
Planned Dealer Notification Date : NOV 01, 2017 - NOV 01, 2017
Planned Owner Notification Date : NOV 01, 2017 - NOV 01, 2017

* NR - Not Reported