OMB Control No.: 2127-0004

Part 573 Safety Recall Report

17V-577

Manufacturer Name: Hyundai Motor America

Submission Date: SEP 20, 2017 NHTSA Recall No.: 17V-577 Manufacturer Recall No.: 167



Manufacturer Information:

Manufacturer Name: Hyundai Motor America

Address: 10550 Talbert Avenue

Fountain Valley CA 92708

Company phone: 800-633-5151

Population:

Number of potentially involved: 196 Estimated percentage with defect: NR

Vehicle Information:

Vehicle 1: 2018-2018 Hyundai Santa Fe Sport

Vehicle Type: LIGHT VEHICLES

Body Style: SUV Power Train: GAS

Descriptive Information: Certain 2018 model year Hyundai Santa Fe Sport vehicles produced at the Hyundai

Motor Manufacturing Alabama ("HMMA") plant and the Kia Motor Manufacturing

Georgia ("KMMG") plant between 8/25/2017 - 9/6/2017.

Production Dates: AUG 25, 2017 - SEP 06, 2017

Description of Defect:

Description of the Defect: The subject vehicles may contain improperly manufactured front coil springs

which could fracture under certain loads while driving.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: In limited instances, a fractured coil spring can potentially contact and

puncture the tire while driving. Driving with a punctured tire could result in

a loss of vehicle control and increase the risk of a crash.

Description of the Cause: The front coil springs were damaged during production due to a

malfunctioning coil spring forming tool.

Identification of Any Warning Customers may experience any or all of the following:

that can Occur: 1. Change in vehicle ride height.

2. Abnormal noise from the coil spring rubbing the inboard sidewall of the

tire.

Supplier Identification:

Component Manufacturer

Name: Mando Corporation

Address: 4201 Northpark Drive
Opelika ALABAMA 36801

Country: United States

Chronology:

On September 5, 2017 HMMA notified Hyundai Motor America ("HMA") of coil spring fractures occurring on 2 Santa Fe Sport vehicles during routine test drives. HMA checked market information and did not find any customer complaints for this condition. HMMA identified a population of approximately 1,700 potentially affected vehicles shipped from HMMA to vehicle processing centers. Of these vehicles, 196 units were confirmed to have shipped from vehicle processing centers to dealers. On September 13, 2017 HMA's Technical Committee convened to review this investigation and decided to conduct a voluntary safety recall.

Hyundai is not aware of any accidents, injuries or customer complaints related to this condition.

Description of Remedy:

Description of Remedy Program: Hyundai will notify all owners of affected vehicles by first class mail to

return to their Hyundai dealer to replace both front coil springs in their

vehicles.

The coil spring is covered for 5 years or 60,000 miles under Hyundai's new vehicle limited warranty. As owners of these vehicles would not have incurred expenses for the warranted repair as a result of this condition, notification regarding reimbursement under section 577.11 is not

necessary.

How Remedy Component Differs Recalled component(s):

from Recalled Component: FRONT COIL SPRING, 54630-4Z200 (for 2.0L)

FRONT COIL SPRING, 54630-4Z000 (for 2.4L 2WD) FRONT COIL SPRING, 54630-4Z100 (for 2.4L AWD)

The improved coil springs involved in the remedy were produced after the coil spring forming tool was repaired and meet the correct dimensional specifications for use in vehicle production. There is no part name or

number change for the remedy components.

Identify How/When Recall Condition The coil spring forming tool was repaired on 9/4/2017. The improved coil

was Corrected in Production: springs were used in vehicle production beginning 9/6/2017.

Recall Schedule:

Description of Recall Schedule: Dealers will be notified in September 2017. Owner notifications will be

sent out in October 2017.

Planned Dealer Notification Date : SEP 27, 2017 - SEP 27, 2017 Planned Owner Notification Date : OCT 18, 2017 - OCT 18, 2017

* NR - Not Reported