

Part 573 Safety Recall Report

17V-626

Manufacturer Name : Keystone RV Company

Submission Date : OCT 06, 2017

NHTSA Recall No. : 17V-626

Manufacturer Recall No. : 17-302



Manufacturer Information :

Manufacturer Name : Keystone RV Company

Address : PO Box 2000
2642 Hackberry Drive Goshen IN
46527

Company phone : 574-535-2100

Population :

Number of potentially involved : 270

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2018-2018 Crossroads Cruiser All Models

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : All Models

Production Dates : AUG 04, 2017 - SEP 08, 2017

VIN Range 1 : Begin : 4YDF29B2XJ6320297 **End :** 4YDF30M28J6320367 Not sequential

Vehicle 2 : 2018-2018 Crossroads Volante All Models

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : All Models

Production Dates : JUL 21, 2017 - SEP 15, 2017

VIN Range 1 : Begin : 4YDF31022J6360424 **End :** 4YDT32S26J6360691 Not sequential

Description of Defect :

Description of the Defect : It has been decided that the vehicles in the recall population were manufactured with Propane detectors instead of a Propane/CO combo detector.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Carbon monoxide is a colorless, odorless, tasteless and highly poisonous gas. Without a properly operated and functioning combined Propane/CO detector, the RV user(s) may not be alerted to the release of carbon monoxide in the RV

Description of the Cause : from any source of combustion. Exposure to carbon monoxide may cause headaches, dizziness, or nausea. Excessive exposure may cause serious personal injury, unconsciousness, or death.

Identification of Any Warning that can Occur : A detector for Propane only was installed instead of a combination Propane/CO detector.

The existing detector is for Propane only.

Supplier Identification :

Component Manufacturer

Name : NR
Address : NR
NR
Country : NR

Chronology :

September 19, 2017 – An audit found the installed detector was for Propane only.
September 29, 2017 – Investigation and scope completed.

Description of Remedy :

Description of Remedy Program : The remedy is to add a CO detector.

How Remedy Component Differs from Recalled Component : Adding the part will provide a means to detect carbon monoxide as described above.

Identify How/When Recall Condition was Corrected in Production : Units were quarantined, inspected then repaired as indicated by inspection.

Recall Schedule :

Description of Recall Schedule : Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.

Planned Dealer Notification Date : OCT 17, 2017 - OCT 17, 2017

Planned Owner Notification Date : OCT 17, 2017 - OCT 17, 2017

* NR - Not Reported